

SUPERINTENDENT ROCKY HANNA

BOARD CHAIR
Rosanne Wood
BOARD VICE CHAIR
Laurie Lawson Cox

BOARD MEMBERS Marcus Nicolas Darryl Jones Alva Swafford Smith

To:

Ms. Delshauna Jackson, Principal, Bond Elementary School

Mr. Ronald Peterson, Assistant Principal, Bond Elementary School

Mr. Ryan Peck, Director of Maintenance

Mr. Danny Allbritton, Director of Construction & Facilities

From:

Mr. Tonnie W. Rollins, Project Manager, Fire & Safety Inspector

Through:

Mr. LaRoderick E. McQueen, Certified Building Official/Divisional Director

Date:

November 19, 2024

Subject:

SREF Inspection for Bond Elementary School

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Please do not submit work orders for the deficiency line items in the M (Maintenance) column. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction and Capital Outlay) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement and Compliance Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Katheryn White at whitek3@leonschools.net or fax the report to (850) 617-1790, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board.

Additionally a separate inspection report has been provided for each portable at your site, in accordance with SREF Chapter 4 Section 4.4 (2)

**The SREF Inspection Reports for each individual portable on site are required by state to be posted. Please post the SREF Inspection Report in their respective portables in a visible location.

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Tonnie W. Rollins at the Code Enforcement and Compliance Department at (850) 617-1814 or email at rollinst2@leonschools.net. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc: Ms. Anicia Robinson, Director of Elementary Schools (with attachments)

SANITATION

SIGNATURE DATE

CASUALTY

TYPE OF INSPECTION

INSPECTOR SIGNATURE

COUNTY
SCHOOLS
FACILITIES & CONSTRUCTION DEPARTMENT
3420 W. THARPE ST., TALLAHASSEE, FL 32303

Bond Elementary School
SCHOOL FACILITY/CAMPUS

2204 Saxon Street Tallahassee, FL 32310

F.I.S.H. NUMBER

COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025

037-1181-118

			07.	JANUARY CONTRACTOR OF THE PROPERTY OF THE PROP	FISCAL YEAR: 2024-2025	037-1191-110				
Item #	Building Number	Room Number	M O C	<u>Deficiency Desc</u>	ription and Corrective Action Required	Previously No Later Correction Exterior CODE REFER				REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
1	0000	0	М	Mulch_needed to be add to playground						
2	0000	0	M	Remove combustible materials from ceiling.	NFPA 101-10.3.1					
3	0001	100	M	Alarm System showing trouble.		0				
4	0001	100	М	Ceiling tile painted		0				
5	0001	117	0	Replace water stained ceiling tile(s). SREF	place water stained ceiling tile(s). SREF 5 (2) (e) (8) j					
6	0001	118	0	Replace water stained ceiling tile(s). SREF	5 (2) (e) (8) j	0				
7	0001	123	0	Replace water stained ceiling tile(s). SREF	5 (2) (e) (8) j	0				
8	0001	123	0	Remove combustible materials from ceiling	NFPA 101-10.3.1	0				
9	0001	134A	0	Ceiling Tile Sagging		1				Building Automation/Locksmith
10	0001	135	0	Walkway obstructed		0				
11	0001	140	M	Replace water stained ceiling tile(s). SREF	5 (2) (e) (8) j					
12	002	200	0	Curtains shall have label or certificate verifying flame	retardant meeting NFPA 701. NFPA 101-10.3.1.					
13	0002	201	0	Combustible materials on wall shall not exceed 40%	NFPA 101-15.7.4.3 (2)	2				
14	0002	201A	0	Doorway obstructed		1				
15	0002	201A	М	Curtains shall have label or certificate verifying flame	retardant meeting NFPA 701. NFPA 101-10.3.1.	1				Electrical Department
16	0002	204	0	Remove combustible materials from ceiling	. NFPA 101-10.3.1	1				Building Automation
17	0002	204A	0	Appliances shall be plugged into the wall o	atlet.	1				

3420 W. THARPE ST., TALLAHASSEE, FL 32303

Bond Elementary School SCHOOL/ FACILITY/CAMPUS

> 2204 Saxon Street Tallahassee, FL 32310

> > F.I.S.H. NUMBER

037-1181-118

INSPECTO	R SIGNATURE	SIGNATURE DATE	
		TYPE OF INSPECTION	

CASUALTY

SANITATION

COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025

Item #	Building Number	Room Number	M O C	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
18	0002	204B	0	Replace water stained ceiling tile(s). SREF 5 (2) (e) (8) j, Smoke Detector	0				
19	0002	204B	0	Doorway obstructed	0				Electrical Department
20	0002	206C	0	Walkway obstructed	1				Electrical Department
21	0002	209	0	Lights not working	1				
22	0002	209	0	Alarm panel showing trouble.	0				
23	0002	212C	0	Curtains shall have label or certificate verifying flame retardant meeting NFPA 701. NFPA 101-10.3.1.	0				
24	0002	212D	0	Replace water stained ceiling tile(s). SREF 5 (2) (e) (8) j, Smoke Detector	0				
25	0002	212E	0	Emergency knob difficult to turn.	0				
26	0003	301	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)	0				
27	0003	303	0	Exit/Entrance Obstructed	0				
28	0003	303	0	Remove combustible on doors and walls	0				HVAC
29	0003	304	0	Remove non-approved furniture that does not have NFPA label or certificate. NFPA 101-10.3.2	1				
30	0003	304	0	Remove combustible materials from ceiling. NFPA 101-10.3.1	0				
31	0003	304	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)	1				Electrical Department
32	0003	304	0	Remove rugs in walkway.	0				
33	0003	306	0	Doorway obstructed	0				
34	0003	307	0	Remove combustible materials from ceiling. NFPA 101-10.3.1	0				

11/07/2024	
INSPECTION DATE	
INSPECTOR: Tonnie Rollins	

SIGNATURE DATE

TYPE OF INSPECTION

INSPECTOR SIGNATURE

3420 W. THARPE ST., TALLAHASSEE, FL 32303

Bond Elementary School SCHOOL FACILITY/CAMPUS

2204 Saxon Street Tallahassee, FL 32310

F.I.S.H. NUMBER

COMPREHENSIVE SAFETY INSPECTION

90	40	FIRE	CA	SUALTY SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025	037-1181-118				
Item #	Building Number	Room Number	M O C	<u>Deficiency Desc</u>	ription and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
35	0003	307	О	Combustible materials on wall shall not exce	ped 40% NFPA 101-15.7.4.3 (2)	0				
36	0003	307	0	Remove rugs in walkway.		0				
37	0003	309	0	Combustible materials on wall shall not exce	eed 40% NFPA 101-15.7.4.3 (2)	0				
38	0003	309	О	Remove non-approved furniture that does no	ot have NFPA label or certificate. NFPA 101-10.3.2	0				
39	0004	403	0	Place a sign on cabinet that has the fire extin	iguisher.	0				Structural Department
40	0004	406	0	Remove combustible materials from ceiling	NFPA 101-10.3.1	0				
41	0004	406	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)	1				
42	0004	407	0	Remove combustible materials from ceiling	NFPA 101-10.3.1	0				
43	0004	407	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)	2				
44	0004	407	0	All appliances shall be plugged into outlet.		0				
45	0004	407	0	Remove rugs in walkway.		0				
46	0004	408	0	Remove combustible materials from ceiling	NFPA 101-10.3.1	1				HVAC
47	0004	408	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)					
48	0004	408	0	Remove non-approved furniture that does n	ot have NFPA label or certificate. NFPA 101-10.3.2					
49	0004	409	0	Entrance/ Exit Obstructed						
50	0004	409	0	Remove non-approved furniture that does n	ot have NFPA label or certificate. NFPA 101-10.3.2					
51	004	412B	0	Doorway obstructed						

3420 W. THARPE ST., TALLAHASSEE, FL 32303

Bond Elementary School SCHOOL/ FACILITY/CAMPUS

> 2204 Saxon Street Tallahassee, FL 32310

> > F.I.S.H. NUMBER

037-1181-118

INSPECTOR SIGNATURE SIGNATURE DATE TYPE OF INSPECTION









CASUALTY SANITATION

COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025

Item #	Building Number	Room Number	M O C	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
52	004	412C	0	Doorway obstructed					
53	004	413	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)					
54	004	414	0	Remove combustible materials from ceiling, NFPA 101-10.3.1					
55	004	416	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)					
56	004	616	0	Remove combustible materials from ceiling. NFPA 101-10.3.1					
57	0005	501	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)	0				
58	0005	501B	0	Replace water stained ceiling tile(s). SREF 5 (2) (e) (8) j	0				
59	0005	501B	0	Box on wall needs cover plate.	0				
60	0005	504	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)					
61	0005	504	0	Remove combustible materials from celling. NFPA 101-10.3.1					
62	0005	504	0	Walkway obstructed					
63	0005	507	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)					
64	0005	507	0	Entrance/ Exit Obstructed					
65	0005	508	0	Lights on Wall					
66	0005	508	0	Remove combustible materials from ceiling, NFPA 101-10.3.1					
67	0005	508	0	Combustible materials on wall shall not exceed 40% NFPA 101-15.7.4.3 (2)					
68	0005	508	0	Remove non-approved furniture that does not have NFPA label or certificate. NFPA 101-10.3.2					



Bond Elementary School SCHOOL/ FACILITY/CAMPUS

2204 Saxon Street Tallahassee, FL 32310

F.I.S.H. NUMBER

037-1181-118

INSPECTOR SIGNATURE SIGNATURE DATE TYPE OF INSPECTION

FIRE

CASUALTY SANITATION

COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025

					FIGUAL 1 EAR: 2024-2025					
Item #	Building Number	Room Number	M O C	<u>Deficiency Desc</u>	ription and Corrective Action Required					CODE REFERENCE
69	0005	508	0	Combustible materials on wall shall not exce	ed 40% NFPA 101-15.7.4.3 (2)					
70	0005	509	0	Remove combustible materials from ceiling. NFPA 101	10.3.1					
71	0005	509	0	Combustible materials on wall shall not exce	ed 40% NFPA 101-15.7.4.3 (2)					
72	0005	509	0	Lights on Wall						
73	0005	509	0	Entrance/ Exit Obstructed						
74	0005	511	0	Remove combustible materials from ceiling. NFPA 101	emove combustible materials from ceiling. NFPA 101-10.3.1					
75	0005	511	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)					
76	0005	511	0	Remove non-approved furniture that does no	ot have NFPA label or certificate. NFPA 101-10.3.2					
77	0005	511	0	Remove rugs in walkway.						
78	0005	511	0	Lights on Wall						
79	0005	511	0	Entrance/ Exit Obstructed						
80	0005	512	0	Lights on Wall						Electrical Department
81	0005	512	0	Replace water stained ceiling tile(s). SREF 5 (2) (e) (9) j					
82	0005	512	0	Remove non-approved furniture that does n	ot have NFPA label or certificate. NFPA 101-10.3.2					
83	0005	512	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)					
84	0005	513	0	Combustible materials on wall shall not exc	eed 40% NFPA 101-15.7.4.3 (2)					
85	0005	513	0	Lights on Monitor						

										rage o or	
			11	/07/2024	A I I I I I I	Bond Elementary School					
				ECTION DATE	LLON	SCHOOL/ FACILITY/CAMPUS					
		INS	PECTO	R: Tonnie Rollins	COUNTY			2204	G G:		
					L CHOOIS				Saxon Strossee, FL 3		
INSPE	CTOR SIGN	VATURE	SIGNA	TURE DATE	FACILITIES & CONSTRUCTION DEPARTMENT			Tananas	ssee, FL 3.	2510	
				OF INSPECTION	3420 W. THARPE ST., TALLAHASSEE, FL 32303			F.I.S	.H. NUMBEF	?	
*	34	FIRE	CA	SUALTY SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025	037-1181-118				3	
Item #	Building Number	Room Number	M O C	<u>Deficiency Desc</u>	cription and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	
86	0005	513	0	Remove non-approved furniture that does no	ot have NFPA label or certificate. NFPA 101-10.3.2						
87	0005	513	0	Remove combustible materials from celling. NFPA 10:	1-10.3.1						
88	0005	506	0	Remove rugs in walkway.							
89	0099	506	М	Skirting damaged							
90	0099	510	М	Gate valve cover missing (eastside)							
91	0099	510	М	Skirting damaged						Electrical Department	
92	0099	510	М	Gate valve cover missing (westside)					Portable	Structural Department	
				END	OF SREF INSPECTION REPORT						
A re-in	spection of t	he identified	deficienc		bsequent of inspection date. Re-Inspection Date:		1	1	1		
\vdash				te drill during each month, with an additional drill bei		1	_				
-		ncy Generat			Emergency Generator Report up-to-date as of SREF Inspection.	\$	N		_		
\vdash					ction report acknowledging awareness of discovered deficiencies:						
Signat	uie or iaciii	ty administr	ator attes	ting to the Evacuation Dinis and review of hispe	choir report acknowledging awareness of discovered deficiencies.						
Lec	Leon County School Site Administrator										