

SUPERINTENDENT ROCKY HANNA

EOARD CHAIR Laurie Lawson Cox EOARD VICE CHAIR Marcus Noclas BOARD MEMBERS
Darryl Jones
Alva Swefford Smith
Rosanne Wood

To: Jason Koerner/ Garrett Jahn

Mr. Ryan Peck, Interim Director of Maintenance Mr. Danny Allbritton, Director of Construction

From: Mr. LaRoderick E. McQueen, Certified Building Official / Divisional Director

Date: 05/30/2025

Subject: SREF Inspection Report - Swift Creek Middle School, 2100 Pedrick Rd, Tallahassee, Fl 32317

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the referenced facility. This report outlines identified deficiencies along with the corresponding corrective actions for the entire site. The "MOC" column within the report designates the responsible party for addressing each item as follows:

- M (Maintenance): These deficiencies are to be resolved by the Maintenance Department. Please do not submit work
 orders for items listed under this category. Upon completion of all related work, Code Enforcement staff must sign off
 to verify completion.
- O (Operational): Items in this category are the responsibility of site-based staff. These should be corrected within the allotted timeframe before the follow-up inspection.
- C (Construction and Capital Outlay): These deficiencies are to be addressed by the Construction/Facilities
 Department, or an appropriate corrective action plan should be developed.

Please note: Any duplicate/completed deficiencies listed on the attached report, please disregard.

Upon completion or development of a corrective action plan for the noted deficiencies, please submit notification to the Code Enforcement Department. Indicate completion by initialing and dating the line items you are responsible for on the provided report. Completed reports can be emailed to Mrs. Katheryn White at katheryn.white@leonschools.net.

A copy of this SREF Inspection Report will also be forwarded to the Board.

Please Note:

Under SREF Chapter 4, Section 4.4 (2), a separate inspection report has been provided for each portable classroom on your site. State requirements mandate that these individual reports be posted in a visible location within each respective portable.

If you have any questions or require clarification regarding any item in this report, please contact Mr. Richard Taylor at the Code Enforcement Department at (850) 617-1812 or via email at richard.taylor@leonschools.net.

Thank you for your prompt attention and cooperation regarding this matter.

Attachment

Cc: Dr. Benny Bolden, Director of Interdivisional Support Services and Secondary Schools

2757 W. Pensacola Street • Tallahassee, Florida 32304-2998 • Phone (850) 487-7100 • Fax (850) 414-5194 • www.leonschools.net

"No person shall on the basis of sex, gender identity, marital status, sexual orientation, race, religion, ethnicity, national origin, age, color, pregnancy, disability, military status or genetic information be denied employment, receipt of services, access to or participation in school activities or programs if qualified to receive such services, or otherwise be discriminated against or placed in a hostile environment in any educational program or activity including those receiving federal financial assistance, except as provided by law." No person shall deny equal access or a fair opportunity to meet to, or discriminate against, any group officially affiliated with the Boy Scouts of America, or any other youth

02/16/2025 Swift Creek Middle School INSPECTION DATE SCHOOL/ FACILITY/CAMPUS INSPECTOR: Richard Taylor 2100 Pedrick Road Tallahassee, Florida 32317 INSPECTOR SIGNATURE SIGNATURE DATE **FACILITIES & CONSTRUCTION DEPARTMENT** TYPE OF INSPECTION F.I.S.H. NUMBER 3420 W. THARPE ST., TALLAHASSEE, FL 32303 FIRE CASUALTY XX **COMPREHENSIVE SAFETY INSPECTION** SANITATION 037-1151-115 FISCAL YEAR: 2024-2025 Site-Wide M Schedule # of Times Re-**Building**item Building Room Deficiency Inspection Wide REMARKS 0 **Deficiency Description and Corrective Action Required** Correction Number Number Previously Exterior CODE REFERENCE Correction No Later C Cited Date Campus MAINTENANCE ASSIGNMENT Than or Portable 0000 000 Emergency phone outside of office is inoperable. 1 **Building Automation** 0000 000 0 Hand sanitizer must be in rooms only, cannot be located in corridor. 3 Site-Wide 0000 000 0 General housekeeping is needed directly outside of 0800-998. 1 0000 000 0 Painted ceiling tiles throughout the entire campus. 1 Site-Wide 5 0000 000 M Outside of #08-801P the concrete is a uneven causing a tripping hazard. 1 Masonry 000 0000 0 All room numbers need to be seen at all times and not covered. 2 Site-Wide 0000 000 0 Remove spider webs from various areas throughout the entire campus. 1 Site-Wide 0001 114 0 Lock needed on Mechanical equipment outside of #01-114. 3 0002 000 Remove storage from the egress corridor by the Chorus Room. 0 6 10 0002 000 M Check entire building (Bldg. #2) for possible leaks. 2 Roofing Department 1112 0002 105 0 Remove storage inside of corridor. 3 13 0002 204 0 Replace stained ceiling tile. 2 0002 205B 0 Replace stained ceiling tile outside of #205B. 2

02/16/2025 Swift Creek Middle School INSPECTION DATE SCHOOL/ FACILITY/CAMPUS INSPECTOR: Richard Taylor 2100 Pedrick Road Tallahassee, Florida 32317 INSPECTOR SIGNATURE SIGNATURE DATE **FACILITIES & CONSTRUCTION DEPARTMENT TYPE OF INSPECTION** 3420 W. THARPE ST., TALLAHASSEE, FL 32303 F.I.S.H. NUMBER **COMPREHENSIVE SAFETY INSPECTION** FIRE CASUALTY SANITATION 037-1151-115 FISCAL YEAR: 2024-2025 Site-Wide M Schedule # of Times **Building-**Refor **Item** Building Room Wide Deficiency Inspection REMARKS **Deficiency Description and Corrective Action Required** 0 Correction Number Number Previously Correction Exterior CODE REFERENCE No Later C Cited Date Campus MAINTENANCE ASSIGNMENT Than or Portable 15 0002 205B 0 Replace missing ceiling tile. 2 16 0002 210 0 Remove items on wheelchair ramp leading to stage, area must remain clear at all times. 17 0002 Remove duct tape from stage floor electrical outlet, replace cover, and secure box. 210 M 2 Electrical Department Reattach base trim at ramp leading to stage. 18 0002 210 M 2 Structural Department 19 Replace missing place card on Fire Riser. 0002 211 M 2 EH&S 0002 20 211 0 Classroom need general housekeeping 1 21 0002 212 0 Replace and date water stained ceiling tile(s) (x3). 1 SREF 5(2)(e)(8)j 22 0002 212K O Replace extremely stained ceiling tile. 2 23 0002 212U 0 Replace and date water stained ceiling tile(s) (x4). SREF 5(2)(e)(8)j 24 0003 302 Stabilize guard rail at top of stairs leading to mezzanine. M 2 Structural Department 303A 0003 25 0 Remove non-approved furniture that does not have NFPA label or certificate. 3 NFPA 101-10.3.2 Replace and date water stained ceiling tile(s) (x3). 26 0003 303A 0 1 SREF 5(2)(e)(8)j 27 0003 303B 0 Remove non-approved furniture that does not have NFPA label or certificate. 1 NFPA 101-10.3.2

NFPA 101-10.3.1

02/16/2025 Swift Creek Middle School INSPECTION DATE SCHOOL/ FACILITY/CAMPUS INSPECTOR: Richard Taylor 2100 Pedrick Road Tallahassee, Florida 32317 INSPECTOR SIGNATURE SIGNATURE DATE **FACILITIES & CONSTRUCTION DEPARTMENT** TYPE OF INSPECTION 3420 W. THARPE ST., TALLAHASSEE, FL 32303 F.I.S.H. NUMBER X FIRE **COMPREHENSIVE SAFETY INSPECTION** CASUALTY SANITATION 037-1151-115 FISCAL YEAR: 2024-2025 Site-Wide M Schedule # of Times **Building-**Refor Item Building Room Wide Deficiency Inspection **REMARKS Deficiency Description and Corrective Action Required** 0 Correction Number Number Previously Correction Exterior **CODE REFERENCE** No Later C Cited Date Campus MAINTENANCE ASSIGNMENT Than or Portable 0003 307A 0 Extension cords cannot be used as permanent power. 0003 315 0 Replace stained ceiling tile outside of #315. Combustible materials on walls shall not exceed 20% in a non-sprinklered building and/or 40% in a 0004 403B 0 1 NFPA 101-15.7.4.3 sprinklered building. 31 0004 417 0 Housekeeping, area needs to be clear of storage and combustibles at all times. 2 32 0005 503A 0 Remove combustibles off of walls and ceilings/ Festive lights approved only fo 60 days 2 Aftermarket furniture should be (NFPA) approved with label displayed. 33 0005 505A 0 2 0005 507 34 0 Temporary extension cords are not to be used as permanent power. 2 35 0005 510 Missing electrical outlet cover near stove. M 2 Electrical Department 36 0005 Replace and date water stained and/or broken ceiling tile(s) (x5). 510 O 1 SREF 5(2)(e)(8)j

0

2

2

1

Printed: 05/27/2025 - 9:51 AM

0005

0005

0005

0005

518 AB

519

520

521

0

0

0

Walkway blocked

Replace stained ceiling tile.

Festive lighting shall be temporary for 60 days.

Remove combustible materials from ceiling.

37

38

39

40

										Page 4 of		
		02/16/	2025			Swift Creek Middle School						
	CTION DA					SCHOOL/ FACILITY/CAMPUS						
INSPL	ECTOR:	Richard	Taylor			2100 Pedrick Road						
					LEON COUNTY SCHOOLS	Tallahassee, Florida 32317						
INSPE	CTOR SIGN	<i>IATURE</i> PE OF IN:		TURE DATE	FACILITIES & CONSTRUCTION DEPARTMENT	E LO II NUMBER						
*	FIRE 🔰	CASUAL		SANITATION	3420 W. THARPE ST., TALLAHASSEE, FL 32303 COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025	F.I.S.H. NUMBER 037-1151-115						
item #	Building Number	Room Number	M O C	<u>Defic</u>	iency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT		
41	0006	609	0	Replace painted	ceiling tile	0						
42	0007	000	M	Check entire bui	lding (Bldg. #7) for possible leaks.	1				Roofing Department		
43	0007	701	M	Replace missing	GFCI cover outside of Gymnasium.	6				Electrical Department		
44	007	702	0	Replace missing	ceiling tile outside of #07-702 corridor area (x3)/ mats blocking doorway	3						
45	0007	703	0	Replace missing	shield on light.	4						
46	0007	707	0	CO2 notification	device needed in #07-707	2				Building Automation		
47	0007	713	M	Repair broken se	pap dish in shower stall.	4				Structural Department		
48	0007	713	0	Light cover is no	eeded in boys locker room.	1						
49	0008	801	0	Remove storage times.	items blocking rear exit. Interior and exterior of ALL exits shall be kept clear at all	3						
50	0008	801T	0	Replace missing	ceiling tile(s).	1						
51	0008	802F	0	Clinic with only	two (2) beds, (4) beds required.	4				FBC-B 453 22.4.2		
52	0009	902	0	Mechanical room	n used as storage	0						
53	0009	902	М	Install Carbon N	Monoxide Detector (CO2).	3				Building Automation		

		02/16/	2025						Swift Creek Middle School						
INSPECTION	N DA	TE			LEON COUNTY SCHOOLS			SCHOOL/ FACILITY/CAMPUS							
INSPECTO	R: R	Richard	Taylor					2100 Pedrick Road							
								Tallahassee, Florida 32317							
INSPECTOR	SIGNA	ATURE	SIGNA	TURE DATE	FACILITIES & CONSTRUCTION DEPARTMENT										
	TYP	E OF IN	SPECTION	N	3420 W. THARPE ST., TALLAHASSEE, FL 32303				F.I.S.H. NUMBER						
FIRE	×	CASUAI	-тү 🞇	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025			037-1151-115							
Item Build # Num		Room Number	M O C	<u>Defic</u>	iency Desc	ncy Description and Corrective Action Required					Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	
					END OF	END OF SREF INSPECTION REPORT									
A re-inspection of the identified deficiencies will be preformed approximately days subsequent of inspection date. Re-Inspection Date:															
The principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school.															
Reviewed Emergency Generator Report. YES NO Emergency Generator Report up-to-date as of SREF Inspection. YES NO NO															
Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies:															

Leon County

School/Site Administrator