



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 46-F DEVURN GLENN SERVICE CENTER
BUILDING: 1 - Building Number 00001

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: COUNTY ADMINISTRATION	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1972	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1974	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: STEEL
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	900	600	ANCILLARY LIBRARY WAREHOUSE/STACKS	0	01	CARPET	1972	SATISFACTORY	1	59	46
002	270	600	ANCILLARY LIBRARY WAREHOUSE/STACKS	0	01	CARPET	1972	SATISFACTORY	1	59	46
002A	112	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
002B	112	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
002C	112	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
002D	112	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
002E	418	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
003A	262	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
003B	234	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
004	244	415	MAIL ROOM	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
004A	50	415	MAIL ROOM	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
006	180	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
007	200	405	VAULT	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
008	556	702	MECHANICAL ROOM	0	01	CONCRETE	1972	SATISFACTORY	1	59	46
009	483	411	WORD PROCESSING CENTER	0	01	CARPET	1972	SATISFACTORY	1	59	46
010	483	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
011	160	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
013	77	600	ANCILLARY LIBRARY WAREHOUSE/STACKS	0	01	CONCRETE	1972	SATISFACTORY	1	59	46
014	85	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
015	85	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
017	86	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
018	100	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
019	86	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
020	110	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
022	9	600	ANCILLARY LIBRARY WAREHOUSE/STACKS	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
024	264	424	DIRECTORS OFFICE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
025	409	401	ANCILLARY CONFERENCE ROOM	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
026	10	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
027	10	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
028	10	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
029	215	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
029A	12	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
030	704	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030A	84	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030B	21	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030C	32	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030D	57	412	PERSONNEL SERVICES	0	01	CARPET	1972	SATISFACTORY	1	59	46
030E	67	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030F	28	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1972	SATISFACTORY	1	59	46
030G	80	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030H	80	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030J	80	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030K	53	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030L	51	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030M	134	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1972	SATISFACTORY	1	59	46
030Y	80	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
031	516	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
031A	132	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
031B	165	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
035	30	416	ANCILLARY CUSTODIAL SERVICES	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
036	25	515	CENTRAL KITCHEN	0	01	COMPOSITION TILE	1972	SATISFACTORY	1	59	46
037	145	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
038	145	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
040	124	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
041	40	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
041A	46	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	1972	SATISFACTORY	1	59	46
042	169	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
043	124	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
044	372	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
045	124	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
046	92	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
047	150	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
048	230	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
049	180	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
050	262	412	PERSONNEL SERVICES	0	01	CARPET	1972	SATISFACTORY	1	59	46
051	180	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
052	372	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1972	SATISFACTORY	1	59	46
053	128	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
054	926	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
054A	128	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
054B	130	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
054C	128	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46
057	5600	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	1	59	46
058	2040	700	INSIDE CIRCULATION	0	01	CARPET	1972	SATISFACTORY	1	59	46
059	40	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1972	SATISFACTORY	1	59	46
060	220	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1972	SATISFACTORY	1	59	46

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	20,970	0	0	0	0	0	0	0
TOTAL	20,970	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 46-F DEVURN GLENN SERVICE CENTER
BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS				
Use: COUNTY ADMINISTRATION	Mech Vent: NONE	Heat Source: ELECTRIC				
Year Constructed: 1956	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE				
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE				
Average Age NSF: 1956	Intercom: NONE	Walls: RELOCATABLE				
Relocatable Units: 1	Telephone: PARTIAL SYSTEM	Struct Comp: RELOCATABLE				
Stories: 1		Corridor: NONE				

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
012	688	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	COMPOSITION TILE	1956	UNSATISFACTORY	2	59	46

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Relocatable	0	0	688	0	0	0	0	0
TOTAL	0	0	688	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MAINTENANCE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1969	Artificial Lighting: INDIRECT LIGHTING	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1969	Intercom: NONE	Walls: BRICK
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	100	419	ANCILLARY FLAMMABLE STORAGE	0	01	CONCRETE	1969	SATISFACTORY	3	59	46

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	100	0	0	0	0	0	0	0
TOTAL	100	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 4 - Building Number 00004

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: COUNTY ADMINISTRATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1977	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT AIR
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1977	Intercom: TWO WAY COMPLETE	Walls: CONCRETE
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	177	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
002	118	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
003	121	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
003A	206	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
003B	125	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
004	15	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
004A	54	825	ANCILLARY RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
005	22	416	ANCILLARY CUSTODIAL SERVICES	0	01	CARPET	1977	SATISFACTORY	4	59	46
006	54	825	ANCILLARY RESTROOM (FEMALE)	0	01	CARPET	1977	SATISFACTORY	4	59	46
006A	54	825	ANCILLARY RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
007	149	402	SUPERINTENDENTS SECRETARY	0	01	CARPET	1977	SATISFACTORY	4	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 4 - Building Number 00004

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
007A	203	406	ASSISTANT SUPERINTENDENTS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
007B	16	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1977	SATISFACTORY	4	59	46
007C	12	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1977	SATISFACTORY	4	59	46
008	121	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
009	178	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
010	62	700	INSIDE CIRCULATION	0	01	CARPET	1977	SATISFACTORY	4	59	46
010A	80	824	ANCILLARY RESTROOM (MALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
010B	80	825	ANCILLARY RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
011	177	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
011A	144	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
012	122	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
012A	120	424	DIRECTORS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
012B	227	424	DIRECTORS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
013	155	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
013A	218	406	ASSISTANT SUPERINTENDENTS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
014	151	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
014A	114	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
014B	114	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
014C	160	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1977	SATISFACTORY	4	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 4 - Building Number 00004

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
015	200	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
016	116	402	SUPERINTENDENTS SECRETARY	0	01	CARPET	1977	SATISFACTORY	4	59	46
016A	182	406	ASSISTANT SUPERINTENDENTS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
017	218	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
018	414	400	SUPERINTENDENTS OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
018A	67	824	ANCILLARY RESTROOM (MALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
019	409	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	1977	SATISFACTORY	4	59	46
021	273	404	ANCILLARY RECEPTION AREA	0	01	QUARRY TILE	1977	SATISFACTORY	4	59	46
022	86	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
023	99	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
023A	46	703	ELECTRICAL ROOM	0	01	CONCRETE	1977	SATISFACTORY	4	59	46
024	142	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
024A	189	405	VAULT	0	01	CARPET	1977	SATISFACTORY	4	59	46
025	121	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
026	114	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
027	130	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46
027A	213	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
028	139	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
028A	165	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1977	SATISFACTORY	4	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 4 - Building Number 00004

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
029	24	825	ANCILLARY RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1977	SATISFACTORY	4	59	46
030	380	408	BUSINESS OPERATIONS WORK AREA	0	01	CARPET	1977	SATISFACTORY	4	59	46
030A	45	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1977	SATISFACTORY	4	59	46
032	127	702	MECHANICAL ROOM	0	01	CONCRETE	1977	SATISFACTORY	4	59	46
033	114	702	MECHANICAL ROOM	0	01	CONCRETE	1977	SATISFACTORY	4	59	46
034	148	702	MECHANICAL ROOM	0	01	CONCRETE	1977	SATISFACTORY	4	59	46
035	470	701	COVERED WALKWAY	0	01	CONCRETE	1977	SATISFACTORY	4	59	46
036	1634	700	INSIDE CIRCULATION	0	01	CARPET	1977	SATISFACTORY	4	59	46

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	9,814	0	0	0	0	0	0	0
TOTAL	9,814	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 99 - Building Number 00099

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: COUNTY ADMINISTRATION	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1956	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1962	Intercom: NONE	Walls: RELOCATABLE
Relocatable Units: 5	Telephone: PARTIAL SYSTEM	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
002A	367	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1956	SATISFACTORY	99	59	46
002B	136	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
002C	97	412	PERSONNEL SERVICES	0	01	CARPET	1956	SATISFACTORY	99	59	46
002D	136	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
002E	1866	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	1956	SATISFACTORY	99	59	46
002F	58	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	1956	SATISFACTORY	99	59	46
002G	58	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	1956	SATISFACTORY	99	59	46
002H	125	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
002Y	50	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1956	SATISFACTORY	99	59	46
008A	529	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CARPET	1956	SATISFACTORY	99	59	46
008B	212	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CARPET	1956	SATISFACTORY	99	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 99 - Building Number 00099

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
011A	242	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1956	SATISFACTORY	99	59	46
011B	126	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011C	122	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011D	101	412	PERSONNEL SERVICES	0	01	CARPET	1956	SATISFACTORY	99	59	46
011E	148	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1956	SATISFACTORY	99	59	46
011F	140	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011G	14	702	MECHANICAL ROOM	0	01	CONCRETE	1956	SATISFACTORY	99	59	46
011H	234	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011J	8	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011K	190	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011L	101	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011M	120	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011N	186	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011P	91	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011Q	153	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011R	160	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
011S	260	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1956	SATISFACTORY	99	59	46
011Z	5	703	ELECTRICAL ROOM	0	01	CONCRETE	1956	SATISFACTORY	99	59	46
012A	87	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1956	SATISFACTORY	99	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 99 - Building Number 00099

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
012B	79	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012C	82	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012D	71	825	ANCILLARY RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1956	SATISFACTORY	99	59	46
012E	9	703	ELECTRICAL ROOM	0	01	CONCRETE	1956	SATISFACTORY	99	59	46
012F	158	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012G	103	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012H	51	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012J	52	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1956	SATISFACTORY	99	59	46
012K	104	700	INSIDE CIRCULATION	0	01	CARPET	1956	SATISFACTORY	99	59	46
151A	96	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151B	78	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151C	80	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151D	80	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151E	39	700	INSIDE CIRCULATION	0	01	CARPET	1968	SATISFACTORY	99	59	46
151F	121	424	DIRECTORS OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151G	30	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1968	SATISFACTORY	99	59	46
151H	30	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1968	SATISFACTORY	99	59	46
151J	80	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151K	100	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 46-F DEVURN GLENN SERVICE CENTER

BUILDING: 99 - Building Number 00099

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
151L	120	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151M	120	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151N	120	424	DIRECTORS OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151P	12	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	1968	SATISFACTORY	99	59	46
151Q	110	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151R	50	700	INSIDE CIRCULATION	0	01	CARPET	1968	SATISFACTORY	99	59	46
151S	30	820	STAFF RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1968	SATISFACTORY	99	59	46
151T	30	819	STAFF RESTROOM (MALE)	0	01	COMPOSITION TILE	1968	SATISFACTORY	99	59	46
151U	1507	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	1968	SATISFACTORY	99	59	46
151V	269	413	CENTRAL REPRODUCTION & COPY	0	01	CARPET	1968	SATISFACTORY	99	59	46
151W	48	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151X	551	700	INSIDE CIRCULATION	0	01	CARPET	1968	SATISFACTORY	99	59	46
151Y	2	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CARPET	1968	SATISFACTORY	99	59	46
151Z	121	404	ANCILLARY RECEPTION AREA	0	01	CARPET	1968	SATISFACTORY	99	59	46
533	864	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1990	SATISFACTORY	99	59	46

Satisfactory			Unsatisfactory		Failed Standards		Scheduled For Replacement	
Square Feet		Student Stations	Square Feet		Student Stations	Square Feet		Student Stations
Relocatable	11,519	0	0	0	0	0	0	0
TOTAL	11,519	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:																			
FACILITY: DEVURN GLENN SERVICE CENTER																			
Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsat Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00334	CUSTODIAL EQUIPMENT STORAGE	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0
00400	SUPERINTENDENTS OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00401	ANCILLARY CONFERENCE ROOM	0	0	0	0	0	0	0	0	2	0	2	0	0	0	0	0	0	0
00402	SUPERINTENDENTS SECRETARY	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	0	0	0	0	0	0	0	6	0	2	0	0	0	0	0	0	0
00404	ANCILLARY RECEPTION AREA	0	0	0	0	0	0	0	0	3	0	6	0	0	0	0	0	0	0
00405	VAULT	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00406	ASSISTANT SUPERINTENDENTS OFFICE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00407	ANCILLARY ADMINISTRATIVE OFFICE	0	0	0	0	0	0	0	0	54	0	17	0	0	0	0	0	0	0
00408	BUSINESS OPERATIONS WORK AREA	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00411	WORD PROCESSING CENTER	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00412	PERSONNEL SERVICES	0	0	0	0	0	0	0	0	2	0	2	0	0	0	0	0	0	0
00413	CENTRAL REPRODUCTION & COPY	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
00415	MAIL ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00416	ANCILLARY CUSTODIAL SERVICES	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00418	ANCILLARY ADMINISTRATIVE STORAGE	0	0	0	0	0	0	0	0	12	0	5	0	0	1	0	0	0	0
00419	ANCILLARY FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00421	ANCILLARY STAFF LOUNGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00424	DIRECTORS OFFICE	0	0	0	0	0	0	0	0	3	0	2	0	0	0	0	0	0	0
00426	GENERAL ANCILLARY OFFICE	0	0	0	0	0	0	0	0	0	0	10	0	0	0	0	0	0	0
00515	CENTRAL KITCHEN	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00600	ANCILLARY LIBRARY WAREHOUSE/STACKS	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00700	INSIDE CIRCULATION	0	0	0	0	0	0	0	0	4	0	4	0	0	0	0	0	0	0
00701	COVERED WALKWAY	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:																			
FACILITY: DEVURN GLENN SERVICE CENTER																			
Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	4	0	1	0	0	0	0	0	0	0
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	1	0	2	0	0	0	0	0	0	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	0	0	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0
00819	STAFF RESTROOM (MALE)	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
00820	STAFF RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0
00824	ANCILLARY RESTROOM (MALE)	0	0	0	0	0	0	0	0	4	0	1	0	0	0	0	0	0	0
00825	ANCILLARY RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	8	0	2	0	0	0	0	0	0	0
Totals:		0	0	0	0	0	0	0	0	134	0	64	0	0	1	0	0	0	0