



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

Parking: NOT DEVELOPED	Owner: SCHOOL BOARD	Fire: 9
Athletic: NO ATHLETIC FACILITY	Water: ON-SITE WELL	Police: COUNTY
Sewage: ON-SITE SEPTIC TANK	Plan: NONE ON PARCEL	Drainage: ADEQUATE
Landscape: DEVELOPED	Playground: NO PARK/PUBLIC ACCESS	Acreage: 6.00
Date Acquired: 1/1/1928		Lease Expiration Date:

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT**

**FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN**

**BUILDING: 12 - Building Number 00012**

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: PRE-K E S E	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1929	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1929	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	662	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1929	SATISFACTORY	12	13	11
001A	10	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
001B	29	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
001C	48	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
002	618	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1929	SATISFACTORY	12	13	11



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
002A	10	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
002B	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
002C	48	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
003	253	316	TEACHER LOUNGE/DINING	0	01	CARPET	1929	SATISFACTORY	12	13	11
003A	17	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
004	40	383	AUDIO VISUAL STORAGE	0	01	CERAMIC TILE	1929	SATISFACTORY	12	13	11
004A	225	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1929	SATISFACTORY	12	13	11
004B	232	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1929	SATISFACTORY	12	13	11
005	2779	700	INSIDE CIRCULATION	0	01	CARPET	1929	SATISFACTORY	12	13	11
006	561	40	RESOURCE ROOM	10	01	CARPET	1929	SATISFACTORY	12	13	11
006A	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
007	561	40	RESOURCE ROOM	10	01	CARPET	1929	SATISFACTORY	12	13	11
007A	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
008	561	340	DINING AREA	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
008A	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
009	751	340	DINING AREA	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
009A	112	350	OTHER FOOD SERVICE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
009B	25	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
010	587	368	TEXTBOOK STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
011	150	317	GENERAL SCHOOL SPACE	0	01	CARPET	1929	SATISFACTORY	12	13	11
011A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
012	582	40	RESOURCE ROOM	10	01	CARPET	1929	SATISFACTORY	12	13	11
012A	501	315	TEACHER PLANNING OFFICE	0	01	CARPET	1929	SATISFACTORY	12	13	11
013	171	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	1929	SATISFACTORY	12	13	11
013A	87	307	CLINIC	0	01	CARPET	1929	SATISFACTORY	12	13	11
013B	125	317	GENERAL SCHOOL SPACE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
013C	243	304	RECEPTION AREA	0	01	CARPET	1929	SATISFACTORY	12	13	11
013D	15	309	VAULT/STUDENT RECORDS	0	01	CONCRETE	1929	SATISFACTORY	12	13	11
013E	25	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1929	SATISFACTORY	12	13	11
014	720	50	ART - ELEMENTARY	19	01	CARPET	1929	SATISFACTORY	12	13	11
014A	10	808	MATERIAL STORAGE	0	01	WOOD	1929	SATISFACTORY	12	13	11
014B	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
014C	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
015	720	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1929	SATISFACTORY	12	13	11
015A	10	808	MATERIAL STORAGE	0	01	WOOD	1929	SATISFACTORY	12	13	11
015B	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
015C	34	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
016	673	810	MATERIAL STORAGE (LARGE)	0	01	CARPET	1929	SATISFACTORY	12	13	11



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
016A	10	808	MATERIAL STORAGE	0	01	WOOD	1929	SATISFACTORY	12	13	11
016B	29	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
016C	34	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1929	SATISFACTORY	12	13	11
017	2366	360	AUDITORIUM	0	01	CARPET	1929	SATISFACTORY	12	13	11
018	633	363	STAGE	0	01	WOOD	1929	SATISFACTORY	12	13	11
019	304	317	GENERAL SCHOOL SPACE	0	01	CARPET	1929	SATISFACTORY	12	13	11
020	304	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1929	SATISFACTORY	12	13	11
021	22	334	CUSTODIAL EQUIPMENT STORAGE	0	01	WOOD	1929	SATISFACTORY	12	13	11
022	86	332	CUSTODIAL WORK AREA	0	01	QUARRY TILE	1929	SATISFACTORY	12	13	11
023	300	334	CUSTODIAL EQUIPMENT STORAGE	0	B1	CONCRETE	1929	SATISFACTORY	12	13	11

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	16,534	103	0	0				
TOTAL	16,534	103	0	0	0	0	0	0



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN

BUILDING: 13 - Building Number 00013

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: COMBINATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1948	Artificial Lighting: UNSHIELDED INCANDESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1948	Intercom: NONE	Walls: BRICK
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	255	317	GENERAL SCHOOL SPACE	0	01	CONCRETE	1948	SATISFACTORY	13	13	11

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	255	0	0	0				
TOTAL	255	0	0	0	0	0	0	0



# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 11-A CHAIRES ELEMENTARY PRE-KINDERGARTEN

BUILDING: 14 - Building Number 00014

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: COMBINATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1992	Artificial Lighting: UNSHIELDED INCANDESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1992	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	142	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1992	SATISFACTORY	14	13	11

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	142	0	0	0				
TOTAL	142	0	0	0	0	0	0	0