



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 0 - Portable Classroom

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: MIDDLE	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 2024	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL RADIANT
Year Modified:	Educational TV: COMMERCIAL CABLE	Heat Capacity: ADEQUATE
Average Age NSF:	Intercom: TWO WAY PARTIAL	Walls: RELOCATABLE
Relocatable Units: 4	Telephone: PARTIAL SYSTEM	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	744	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	2024	SATISFACTORY	0	23	19
001A	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2024	SATISFACTORY	0	23	19
002	744	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	2024	SATISFACTORY	0	23	19
002A	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2024	SATISFACTORY	0	23	19
003	744	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	2024	SATISFACTORY	0	23	19
003A	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2024	SATISFACTORY	0	23	19
004	744	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	2024	SATISFACTORY	0	23	19
004A	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2024	SATISFACTORY	0	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Relocatable	3,200	88	0	0	0	0	0	0
TOTAL	3,200	88	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1954	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1961	Intercom: ONE WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: STEEL
Stories: 2		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001A	279	304	RECEPTION AREA	0	01	CARPET	1954	SATISFACTORY	2	23	19
001B	153	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1954	SATISFACTORY	2	23	19
001C	249	306	CONFERENCE ROOM	0	01	CARPET	1954	SATISFACTORY	2	23	19
001D	148	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1954	SATISFACTORY	2	23	19
002A	853	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1954	SATISFACTORY	2	23	19
003A	838	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1954	SATISFACTORY	2	23	19
003B	18	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	2	23	19
004A	853	21	INTERMEDIATE/MIDDLE SCIENCE LAB (4-8)	22	01	CARPET	1954	SATISFACTORY	2	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 2 - Building Number 00002

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
005A	770	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	CARPET	1954	SATISFACTORY	2	23	19
005b	282	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1954	SATISFACTORY	2	23	19
005C	80	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	2	23	19
006A	850	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	CARPET	1954	SATISFACTORY	2	23	19
006C	139	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	2	23	19
007B	2296	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	2	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	7,808	110	0	0				
TOTAL	7,808	110	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 4 - Building Number 00004

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1966	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1966	Intercom: ONE WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: STEEL
Stories: 2		Corridor: DOUBLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	840	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
002	840	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
003	840	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
004	832	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
005	832	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
006	832	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1966	SATISFACTORY	4	23	19
007	28	334	CUSTODIAL EQUIPMENT STORAGE	0	01	COMPOSITION TILE	1966	SATISFACTORY	4	23	19
008	136	815	STUDENT RESTROOM (MALE)	0	01	COMPOSITION TILE	1966	SATISFACTORY	4	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 4 - Building Number 00004

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009	136	816	STUDENT RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1966	SATISFACTORY	4	23	19
010	384	316	TEACHER LOUNGE/DINING	0	01	CARPET	1966	SATISFACTORY	4	23	19
010A	33	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1966	SATISFACTORY	4	23	19
010B	33	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	1966	SATISFACTORY	4	23	19
013	171	702	MECHANICAL ROOM	0	01	CONCRETE	1966	SATISFACTORY	4	23	19
016	664	701	COVERED WALKWAY	0	01	CONCRETE	1966	SATISFACTORY	4	23	19
800	768	700	INSIDE CIRCULATION	0	01	CARPET	1966	SATISFACTORY	4	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	7,369	132	0	0				
TOTAL	7,369	132	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 7 - Building Number 00007

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1954	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1971	Intercom: ONE WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: STEEL
Stories: 2		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	183	702	MECHANICAL ROOM	0	01	CONCRETE	1966	SATISFACTORY	7	23	19
002	187	816	STUDENT RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1966	SATISFACTORY	7	23	19
003	187	815	STUDENT RESTROOM (MALE)	0	01	COMPOSITION TILE	1966	SATISFACTORY	7	23	19
004	188	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1966	SATISFACTORY	7	23	19
005	120	121	OTHER P E SPACE	0	01	COMPOSITION TILE	1966	SATISFACTORY	7	23	19
006	6690	111	JR HIGH GYMNASIUM	80	01	WOOD	1966	SATISFACTORY	7	23	19
009	636	93	P E LOCKER ROOM (FEMALE)	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
009A	106	315	TEACHER PLANNING OFFICE	0	01	CARPET	1954	SATISFACTORY	7	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 7 - Building Number 00007

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009B	35	100	P E TEACHERS SHOWER (FEMALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	7	23	19
009C	27	114	P E LAUNDRY	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
009D	76	120	GYMNASIUM STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	7	23	19
009E	329	95	P E SHOWER (FEMALE)	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
009F	36	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	7	23	19
010	636	92	P E LOCKER ROOM (MALE)	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
010A	106	315	TEACHER PLANNING OFFICE	0	01	CARPET	1954	SATISFACTORY	7	23	19
010B	35	99	P E TEACHERS SHOWER (MALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	7	23	19
010C	27	331	CUSTODIAL SERVICE CLOSET	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
010D	76	120	GYMNASIUM STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	7	23	19
010E	329	94	P E SHOWER (MALE)	0	01	QUARRY TILE	1954	SATISFACTORY	7	23	19
010F	36	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	7	23	19
011	36	703	ELECTRICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	7	23	19
800	566	700	INSIDE CIRCULATION	0	01	QUARRY TILE	1966	SATISFACTORY	7	23	19
801	3368	701	COVERED WALKWAY	0	01	CONCRETE	1997	SATISFACTORY	7	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	14,015	80	0	0				
TOTAL	14,015	80	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 9 - Building Number 00009

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1954	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1954	Intercom: ONE WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: STEEL
Stories: 2		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	630	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1954	SATISFACTORY	9	23	19
001A	630	272	VOCATIONAL LAB SUPPORT SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
002	136	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	9	23	19
003	28	703	ELECTRICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
004	72	803	INSTRUCTIONAL DARKROOM	0	01	COMPOSITION TILE	1954	SATISFACTORY	9	23	19
005	1906	240	TECHNOLOGY/INDUSTRY EXPLORATION LAB	22	01	CONCRETE	1954	SATISFACTORY	9	23	19
006	204	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1954	SATISFACTORY	9	23	19
008	18	822	PUBLIC USE RESTROOM (MALE)	0	01	TERRAZZO	1954	SATISFACTORY	9	23	19
009	167	272	VOCATIONAL LAB SUPPORT SPACE	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
010	317	810	MATERIAL STORAGE (LARGE)	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
011	327	810	MATERIAL STORAGE (LARGE)	0	01	CONCRETE	1954	SATISFACTORY	9	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 9 - Building Number 00009

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
012	69	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
013	1024	330	CUSTODIAL RECEIVING	0	01	COMPOSITION TILE	1954	SATISFACTORY	9	23	19
015	704	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
101	2200	76	BAND CLASS (MIDDLE-SR HIGH)	40	01	CARPET	1954	SATISFACTORY	9	23	19
102	36	702	MECHANICAL ROOM	0	01	CARPET	1954	SATISFACTORY	9	23	19
103	36	83	MUSIC RELATED SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
104	36	83	MUSIC RELATED SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
105	33	83	MUSIC RELATED SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
106	86	317	GENERAL SCHOOL SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
107	274	83	MUSIC RELATED SPACE	0	01	CARPET	1954	SATISFACTORY	9	23	19
108	106	368	TEXTBOOK STORAGE	0	01	CARPET	1954	SATISFACTORY	9	23	19
109	42	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	9	23	19
110	121	82	INSTRUMENT REPAIR	0	01	CARPET	1954	SATISFACTORY	9	23	19
111	118	82	INSTRUMENT REPAIR	0	01	CARPET	1954	SATISFACTORY	9	23	19
112	91	82	INSTRUMENT REPAIR	0	01	CARPET	1954	SATISFACTORY	9	23	19
800	299	700	INSIDE CIRCULATION	0	01	CARPET	1954	SATISFACTORY	9	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	9,710	84	0	0				
TOTAL	9,710	84	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 10 - Building Number 00010

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1954	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1954	Intercom: ONE WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: STEEL
Stories: 2		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	2840	340	DINING AREA	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
001A	485	363	STAGE	0	01	WOOD	1954	SATISFACTORY	10	23	19
001B	316	316	TEACHER LOUNGE/DINING	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
001C	60	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1954	SATISFACTORY	10	23	19
001D	55	345	KITCHEN NONFOOD STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
002	983	346	KITCHEN FOOD PREPARATION	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
002A	238	341	KITCHEN & SERVING AREA	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
002B	700	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
002C	130	341	KITCHEN & SERVING AREA	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
003	110	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
004	118	345	KITCHEN NONFOOD STORAGE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 10 - Building Number 00010

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
005	212	342	KITCHEN DRY STORAGE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
005A	100	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
005B	100	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
006	103	343	KITCHEN OFFICE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
007	60	820	STAFF RESTROOM (FEMALE)	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
008	35	334	CUSTODIAL EQUIPMENT STORAGE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
009	59	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1954	SATISFACTORY	10	23	19
009A	99	344	KITCHEN GARBAGE WASH	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
010	689	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
012	168	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	1954	SATISFACTORY	10	23	19
013	17	808	MATERIAL STORAGE	0	01	CARPET	1954	SATISFACTORY	10	23	19
014	133	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
015	397	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
016	865	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
017	884	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
017A	456	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
018	876	701	COVERED WALKWAY	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
018A	65	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	10	23	19
018B	68	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 10 - Building Number 00010

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
018C	68	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
019	145	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1954	SATISFACTORY	10	23	19
019A	135	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	10	23	19
019B	145	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1954	SATISFACTORY	10	23	19
020	688	702	MECHANICAL ROOM	0	01	CONCRETE	1954	SATISFACTORY	10	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	12,602	0	0	0				
TOTAL	12,602	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 11 - Building Number 00011

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1979	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1979	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	3603	380	LIBRARY (READING ROOM/STACKS)	0	01	CARPET	1979	SATISFACTORY	11	23	19
001A	63	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1979	SATISFACTORY	11	23	19
001B	72	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1979	SATISFACTORY	11	23	19
001C	709	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
001D	921	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
002	989	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
003	158	385	CLOSED CIRCUIT TV LAB	0	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
003A	192	385	CLOSED CIRCUIT TV LAB	0	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 11 - Building Number 00011

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
004	250	702	MECHANICAL ROOM	0	01	CONCRETE	1979	SATISFACTORY	11	23	19
005	55	334	CUSTODIAL EQUIPMENT STORAGE	0	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
006	420	383	AUDIO VISUAL STORAGE	0	01	CARPET	1979	SATISFACTORY	11	23	19
007	127	702	MECHANICAL ROOM	0	01	CONCRETE	1979	SATISFACTORY	11	23	19
008	618	382	PROFESSIONAL LIBRARY	0	01	COMPOSITION TILE	1979	SATISFACTORY	11	23	19
010	397	389	MEDIA SMALL GROUP ROOM	0	01	CARPET	1979	SATISFACTORY	11	23	19
011	149	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	1979	SATISFACTORY	11	23	19
012	64	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1979	SATISFACTORY	11	23	19
014	126	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CERAMIC TILE	1979	SATISFACTORY	11	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	8,913	66	0	0				
TOTAL	8,913	66	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 12 - Building Number 00012

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1997	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1997	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: CONCRETE
Stories: 2		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	882	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1997	SATISFACTORY	12	23	19
101A	36	808	MATERIAL STORAGE	0	01	CARPET	1997	SATISFACTORY	12	23	19
101B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19
101C	127	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
101D	210	315	TEACHER PLANNING OFFICE	0	01	CARPET	1997	SATISFACTORY	12	23	19
102	882	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1997	SATISFACTORY	12	23	19
102A	127	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
102B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CONCRETE	1997	SATISFACTORY	12	23	19
102C	36	808	MATERIAL STORAGE	0	01	CARPET	1997	SATISFACTORY	12	23	19
103	27	317	GENERAL SCHOOL SPACE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
104	131	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
105	44	827	ELEVATOR (PASSENGER/HANDICAPPED)	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
106	451	40	RESOURCE ROOM	0	01	CARPET	1997	SATISFACTORY	12	23	19
106A	110	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
106B	219	315	TEACHER PLANNING OFFICE	0	01	CARPET	1997	SATISFACTORY	12	23	19
107	451	40	RESOURCE ROOM	0	01	CARPET	1997	SATISFACTORY	12	23	19
107A	110	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
108	1741	78	GENERAL MUSIC CLASS (MIDDLE-SR HIGH)	30	01	CARPET	1997	SATISFACTORY	12	23	19
108A	37	83	MUSIC RELATED SPACE	0	01	CARPET	1997	SATISFACTORY	12	23	19
109	37	334	CUSTODIAL EQUIPMENT STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
110	46	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19
111	46	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19
112	35	331	CUSTODIAL SERVICE CLOSET	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
113	48	831	MUSIC PRACTICE ROOM	0	01	CARPET	1997	SATISFACTORY	12	23	19
114	48	831	MUSIC PRACTICE ROOM	0	01	CARPET	1997	SATISFACTORY	12	23	19
115	103	833	ROBE STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
116	1196	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1997	SATISFACTORY	12	23	19
116A	118	315	TEACHER PLANNING OFFICE	0	01	CARPET	1997	SATISFACTORY	12	23	19
117	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19
118	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1997	SATISFACTORY	12	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
119	113	703	ELECTRICAL ROOM	0	01	CONCRETE	1997	SATISFACTORY	12	23	19
120	250	702	MECHANICAL ROOM	0	01	CONCRETE	1997	SATISFACTORY	12	23	19
121	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
201	1176	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
201A	218	812	PROJECT STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
201B	142	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
201C	56	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
201D	211	315	TEACHER PLANNING OFFICE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
202	1002	21	INTERMEDIATE/MIDDLE SCIENCE LAB (4-8)	22	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
202A	160	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
202B	56	333	FLAMMABLE STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
203	27	334	CUSTODIAL EQUIPMENT STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
204	175	816	STUDENT RESTROOM (FEMALE)	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
205	44	827	ELEVATOR (PASSENGER/HANDICAPPED)	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
206	407	65	E S E RESOURCE	0	02	CARPET	1997	SATISFACTORY	12	23	19
206A	219	315	TEACHER PLANNING OFFICE	0	02	CARPET	1997	SATISFACTORY	12	23	19
206B	101	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
207	363	331	CUSTODIAL SERVICE CLOSET	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19
800	1234	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	1997	SATISFACTORY	12	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 12 - Building Number 00012

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
801	2326	701	COVERED WALKWAY	0	02	CONCRETE	1997	SATISFACTORY	12	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	15,782	140	0	0				
TOTAL	15,782	140	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 13 - Building Number 00013

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1960	Artificial Lighting: GLOBE FIXTURE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1960	Intercom: NONE	Walls: CONCRETE
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
020	74	333	FLAMMABLE STORAGE	0	01	CONCRETE	1960	SATISFACTORY	13	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	74	0	0	0				
TOTAL	74	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 14 - Building Number 00014

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: MIDDLE	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1992	Artificial Lighting: NONE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1992	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	160	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1992	SATISFACTORY	14	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	160	0	0	0				
TOTAL	160	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 15 - Griffin Building 15 (Admin & IT)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2011	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2011	Intercom: TWO WAY COMPLETE	Walls: CONCRETE
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 2		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	680	317	GENERAL SCHOOL SPACE	0	01	CARPET	2011	SATISFACTORY	15	23	19
002	308	303	SECRETARIAL SPACE	0	01	CARPET	2011	SATISFACTORY	15	23	19
003	168	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
004	133	302	BOOKKEEPING OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
005	215	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
005A	32	808	MATERIAL STORAGE	0	01	CARPET	2011	SATISFACTORY	15	23	19
005B	43	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
006	297	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
007	285	306	CONFERENCE ROOM	0	01	CARPET	2011	SATISFACTORY	15	23	19
008	44	308	GENERAL SCHOOL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
009	423	305	PRODUCTION WORKROOM	0	01	CARPET	2011	SATISFACTORY	15	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 15 - Griffin Building 15 (Admin & IT)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009A	51	808	MATERIAL STORAGE	0	01	CARPET	2011	SATISFACTORY	15	23	19
010	78	310	SCHOOL STORE	0	01	CARPET	2011	SATISFACTORY	15	23	19
011	158	314	ITINERANT OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
012	138	311	STUDENT ACTIVITIES	0	01	CARPET	2011	SATISFACTORY	15	23	19
013	186	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
014	150	308	GENERAL SCHOOL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
015	7	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
016	65	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
017	143	314	ITINERANT OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
018	65	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
019	378	312	COMPUTER AREA	0	01	CARPET	2011	SATISFACTORY	15	23	19
020	182	315	TEACHER PLANNING OFFICE	0	01	CARPET	2011	SATISFACTORY	15	23	19
021	183	313	CAREERS ROOM	0	01	CARPET	2011	SATISFACTORY	15	23	19
022	325	307	CLINIC	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
022A	53	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
022B	53	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
023	153	311	STUDENT ACTIVITIES	0	01	CARPET	2011	SATISFACTORY	15	23	19
024	176	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
024A	8	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 15 - Griffin Building 15 (Admin & IT)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
025	448	304	RECEPTION AREA	0	01	CARPET	2011	SATISFACTORY	15	23	19
026	24	702	MECHANICAL ROOM	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
101	960	11	INTERMEDIATE/MIDDLE SKILLS LAB (4-8)	22	01	CARPET	2011	SATISFACTORY	15	23	19
101A	103	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
102	54	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
103	147	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
104	97	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
105	126	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
106	870	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
106A	76	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
107	1018	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
107A	80	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2022	SATISFACTORY	15	23	19
108	1193	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
108B	68	817	STUDENT RESTROOM & BATH	0	01	CERAMIC TILE	2011	SATISFACTORY	15	23	19
109	64	703	ELECTRICAL ROOM	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
110	196	702	MECHANICAL ROOM	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
111	28	703	ELECTRICAL ROOM	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
800A	156	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
800B	654	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 15 - Griffin Building 15 (Admin & IT)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
800C	653	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
800D	139	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
801	1783	701	COVERED WALKWAY	0	01	CONCRETE	2011	SATISFACTORY	15	23	19
201	960	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	CARPET	2011	SATISFACTORY	15	23	19
201A	128	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
202	792	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
202A	122	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
203	147	816	STUDENT RESTROOM (FEMALE)	0	02	CERAMIC TILE	2011	SATISFACTORY	15	23	19
204	97	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
205	126	815	STUDENT RESTROOM (MALE)	0	02	CERAMIC TILE	2011	SATISFACTORY	15	23	19
206	823	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
206A	58	808	MATERIAL STORAGE	0	02	CONCRETE	2011	SATISFACTORY	15	23	19
207	984	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	CARPET	2011	SATISFACTORY	15	23	19
207A	117	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
208	58	703	ELECTRICAL ROOM	0	02	CONCRETE	2011	SATISFACTORY	15	23	19
209	66	821	STAFF RESTROOM (BOTH SEXES)	0	02	CERAMIC TILE	2011	SATISFACTORY	15	23	19
210	203	315	TEACHER PLANNING OFFICE	0	02	CARPET	2011	SATISFACTORY	15	23	19
211	984	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	CARPET	2011	SATISFACTORY	15	23	19
211A	117	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 19-A GRIFFIN MIDDLE

BUILDING: 15 - Griffin Building 15 (Admin & IT)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
212	778	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
212A	118	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
213	60	812	PROJECT STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
214	796	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
214A	89	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
215	906	51	ART - MIDDLE	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
215A	120	805	KILN	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
215B	133	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
216	831	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
216A	135	808	MATERIAL STORAGE	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
800	1143	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19
800E	858	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	2011	SATISFACTORY	15	23	19

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	25,866	286	0	0				
TOTAL	25,866	286	0	0	0	0	0	0