

### **FACILITY INVENTORY REPORT**

### **FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY**

Primary Use: ELEMENTARY Grades Housed: PK - 05 DOE Validation Date: Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

### **MASTER SCHOOL ID**

MSID	Name	Status
91	RUEDIGER ELEMENTARY SCHOOL	Default

### **CAPITAL OUTLAY FTE**

Year: 2022 / 2023										
PK: 20.52	01: 84.00	03: 91.02	05: 78.00	07: 0.00	09: 0.00	11: 0.00	PK-12: 481.54			
KG: 75.50	02: 68.00	04: 64.50	06: 0.00	08: 0.00	10: 0.00	12: 0.00	Adult: 0.00			
							Total: 481.54			

### **SCHOOL CAPACITY**

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE		
553	664	1.00	ELEMENTARY		

PARCEL: 11

526 W 10TH AVENUE

TALLAHASSEE, FL 32303

Parking: DEVELOPED	Owner: SCHOOL BOARD	Fire: 3
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: CITY
Sewage: PUBLIC	Plan: FINGER	Drainage: INADEQUATE
Landscape: DEVELOPED	Playground: INCLUDED WITH SITE	Acreage: 10.00
Date Acquired: 1/1/1954		Lease Expiration Date:

Page 318 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 1 - Building Number 00001** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1955	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001A	33	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	1	11	9
101	152	317	GENERAL SCHOOL SPACE	0	01	CARPET	1955	SATISFACTORY	1	11	9
101A	45	703	ELECTRICAL ROOM	0	01	CARPET	1955	SATISFACTORY	1	11	9
102	218	304	RECEPTION AREA	0	01	CERAMIC TILE	1955	SATISFACTORY	1	11	9
103	168	303	SECRETARIAL SPACE	0	01	CARPET	1955	SATISFACTORY	1	11	9
104	30	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1955	SATISFACTORY	1	11	9
105	30	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1955	SATISFACTORY	1	11	9

Page 319 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 1 - Building Number 00001** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
106	104	307	CLINIC	0	01	COMPOSITION TILE	1955	SATISFACTORY	1	11	9
106A	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	1	11	9
107	152	302	BOOKKEEPING OFFICE	0	01	CARPET	1955	SATISFACTORY	1	11	9
108	38	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1955	SATISFACTORY	1	11	9
109	32	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	1	11	9
110	191	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	1955	SATISFACTORY	1	11	9
111	196	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1955	SATISFACTORY	1	11	9
112	28	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1955	SATISFACTORY	1	11	9
113	153	702	MECHANICAL ROOM	0	01	CONCRETE	1955	SATISFACTORY	1	11	9
800	1200	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1955	SATISFACTORY	1	11	9

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	2,812	0	0	0					
TOTAL	2,812	0	0	0	0	0	0	0	

Page 320 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 2 - Building Number 00002** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1962	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	813	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	2	11	9
001A	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	2	11	9
002	813	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	2	11	9
002a	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	2	11	9
003	813	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	2	11	9
003A	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1955	SATISFACTORY	2	11	9
004	800	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1955	SATISFACTORY	2	11	9
004B	126	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	2	11	9

Page 321 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 2 - Building Number 00002** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
005	669	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1955	SATISFACTORY	2	11	9
005B	395	810	MATERIAL STORAGE (LARGE)	0	01	COMPOSITION TILE	1955	SATISFACTORY	2	11	9
800	60	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1955	SATISFACTORY	2	11	9
810	2032	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	2	11	9

	Satisfactory		Unsati	sfactory	Failed S	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	6,572	90	0	0					
TOTAL	6,572	90	0	0	0	0	0	0	

Page 322 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 3 - Building Number 00003** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1961	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
006	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	3	11	9
006A	26	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9
006B	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9
007	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	3	11	9
007A	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9
008	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	3	11	9
008A	12	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9
008B	17	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9

Page 323 of 1630 Report Date: 4/15/2024 1:35:47 PM

# THE TANK THE

# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 3 - Building Number 00003** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009	773	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	3	11	9
009B	30	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	3	11	9
010	743	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	3	11	9
011	274	810	MATERIAL STORAGE (LARGE)	0	01	CONCRETE	1955	SATISFACTORY	3	11	9
810	1488	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	3	11	9

	Satis	sfactory	Unsati	sfactory	Failed St	andards	Scheduled For	Replacement
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,797	90	0	0				
TOTAL	5,797	90	0	0	0	0	0	0

Page 324 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 4 - Building Number 00004** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1961	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
014	800	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1955	SATISFACTORY	4	11	9
015	800	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1955	SATISFACTORY	4	11	9
016	800	10	PRIMARY SKILLS LAB (K-3)	0	01	CARPET	1955	SATISFACTORY	4	11	9
017	773	312	COMPUTER AREA	0	01	CARPET	1955	SATISFACTORY	4	11	9
018	773	312	COMPUTER AREA	0	01	CARPET	1955	SATISFACTORY	4	11	9
810	1488	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	4	11	9

	Satis	sfactory	Unsati	sfactory	Failed St	andards	Scheduled For	r Replacement
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,434	44	0	0				
TOTAL	5,434	44	0	0	0	0	0	0

Page 325 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 5 - Building Number 00005** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
022	764	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1958	SATISFACTORY	5	11	9
022A	144	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	11	9
022B	144	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	11	9
022C	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	11	9
023	764	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1958	SATISFACTORY	5	11	9
023A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	11	9
024	764	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1958	SATISFACTORY	5	11	9
024A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	5	11	9

Page 326 of 1630 Report Date: 4/15/2024 1:35:47 PM

# THE TANK THE

# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 5 - Building Number 00005** 

RO	ОМ	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
810		613	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	5	11	9

	Satis	sfactory	Unsatisfactory		ctory Failed Standards Scheduled For Replacement		Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	3,268	54	0	0				
TOTAL	3,268	54	0	0	0	0	0	0

Page 327 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 6 - Building Number 00006** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1958	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1958	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
025	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1958	SATISFACTORY	6	11	9
025A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	6	11	9
026	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1958	SATISFACTORY	6	11	9
026B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	6	11	9
026C	144	315	TEACHER PLANNING OFFICE	0	01	CARPET	1958	SATISFACTORY	6	11	9
027	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1958	SATISFACTORY	6	11	9
027B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1958	SATISFACTORY	6	11	9
810	766	701	COVERED WALKWAY	0	01	CONCRETE	1958	SATISFACTORY	6	11	9

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	3,315	66	0	0					
TOTAL	3,315	66	0	0	0	0	0	0	

Page 328 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 7 - Building Number 00007** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1955	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
019	795	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1955	SATISFACTORY	7	11	9
020	795	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	7	11	9
020B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	7	11	9
020C	144	315	TEACHER PLANNING OFFICE	0	01	CARPET	1955	SATISFACTORY	7	11	9
021	795	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1955	SATISFACTORY	7	11	9
021B	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	7	11	9
810	830	701	COVERED WALKWAY	0	01	CONCRETE	1955	SATISFACTORY	7	11	9

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	3,447	58	0	0					
TOTAL	3,447	58	0	0	0	0	0	0	

Page 329 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 8 - Building Number 00008** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1955	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
010A	183	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1955	SATISFACTORY	8	11	9
010B	176	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1955	SATISFACTORY	8	11	9
010C	30	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CONCRETE	1955	SATISFACTORY	8	11	9
011	1172	50	ART - ELEMENTARY	0	01	CARPET	1955	SATISFACTORY	8	11	9
011A	53	805	KILN	0	01	COMPOSITION TILE	1955	SATISFACTORY	8	11	9
011B	58	803	INSTRUCTIONAL DARKROOM	0	01	COMPOSITION TILE	1955	SATISFACTORY	8	11	9
011C	53	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1955	SATISFACTORY	8	11	9

Page 330 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 8 - Building Number 00008** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
011D	55	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1955	SATISFACTORY	8	11	9
012	181	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1955	SATISFACTORY	8	11	9
013	915	55	MUSIC - ELEMENTARY	0	01	CARPET	1955	SATISFACTORY	8	11	9
013A	48	83	MUSIC RELATED SPACE	0	01	CARPET	1955	SATISFACTORY	8	11	9
013B	43	83	MUSIC RELATED SPACE	0	01	COMPOSITION TILE	1955	SATISFACTORY	8	11	9
014	905	119	P E GYMNASTICS & DANCE	0	01	WOOD	1955	SATISFACTORY	8	11	9
015	394	317	GENERAL SCHOOL SPACE	0	01	CARPET	1955	SATISFACTORY	8	11	9
015A	161	317	GENERAL SCHOOL SPACE	0	01	CARPET	1955	SATISFACTORY	8	11	9
015B	150	315	TEACHER PLANNING OFFICE	0	01	CARPET	1955	SATISFACTORY	8	11	9
015C	124	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1955	SATISFACTORY	8	11	9
810	1075	701	COVERED WALKWAY	0	01	CONCRETE	1955	SATISFACTORY	8	11	9

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	5,776	0	0	0					
TOTAL	5,776	0	0	0	0	0	0	0	

Page 331 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 9 - Building Number 00009** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: OIL
Year Constructed: 1955	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1972	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
028	1085	346	KITCHEN FOOD PREPARATION	0	01	OTHER	1955	SATISFACTORY	9	11	9
028A	49	343	KITCHEN OFFICE	0	01	OTHER	1955	SATISFACTORY	9	11	9
028B	20	331	CUSTODIAL SERVICE CLOSET	0	01	OTHER	1955	SATISFACTORY	9	11	9
028C	47	821	STAFF RESTROOM (BOTH SEXES)	0	01	OTHER	1955	SATISFACTORY	9	11	9
028D	200	342	KITCHEN DRY STORAGE	0	01	OTHER	1955	SATISFACTORY	9	11	9
028E	25	700	INSIDE CIRCULATION	0	01	OTHER	1955	SATISFACTORY	9	11	9
028G	140	350	OTHER FOOD SERVICE	0	01	OTHER	1955	SATISFACTORY	9	11	9
028H	100	350	OTHER FOOD SERVICE	0	01	OTHER	1955	SATISFACTORY	9	11	9

Page 332 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 9 - Building Number 00009** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
029	73	333	FLAMMABLE STORAGE	0	01	CONCRETE	1955	SATISFACTORY	9	11	9
030	2216	340	DINING AREA	0	01	COMPOSITION TILE	1955	SATISFACTORY	9	11	9
030A	652	363	STAGE	0	01	WOOD	1955	SATISFACTORY	9	11	9
031	238	702	MECHANICAL ROOM	0	01	CONCRETE	1955	SATISFACTORY	9	11	9
032	140	703	ELECTRICAL ROOM	0	01	CONCRETE	1955	SATISFACTORY	9	11	9
033	100	332	CUSTODIAL WORK AREA	0	01	CARPET	1955	SATISFACTORY	9	11	9
033A	32	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1955	SATISFACTORY	9	11	9
034	1802	361	MULTIPURPOSE ROOM (DINING)	0	01	COMPOSITION TILE	2015	SATISFACTORY	9	11	9
034A	171	362	MULTIPURPOSE ROOM CHAIR STORAGE	0	01	COMPOSITION TILE	2015	SATISFACTORY	9	11	9
035	64	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2015	SATISFACTORY	9	11	9
035A	57	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	2015	SATISFACTORY	9	11	9
035B	57	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	2015	SATISFACTORY	9	11	9
036	64	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2015	SATISFACTORY	9	11	9
036A	57	819	STAFF RESTROOM (MALE)	0	01	CERAMIC TILE	2015	SATISFACTORY	9	11	9
036B	57	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	2015	SATISFACTORY	9	11	9

Page 333 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 9 - Building Number 00009** 

	ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
8	801	381	701	COVERED WALKWAY	0	01	CONCRETE	1955	SATISFACTORY	9	11	9

	Satis	sfactory	Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet Student Station		Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	7,827	0	0	0					
TOTAL	7,827	0	0	0	0	0	0	0	

Page 334 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 10 - Building Number 00010** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: COMBINATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1979	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1979	Intercom: TWO WAY PARTIAL	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	984	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9
101A	24	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9
101B	32	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1979	SATISFACTORY	10	11	9
101C	280	315	TEACHER PLANNING OFFICE	0	01	CARPET	1979	SATISFACTORY	10	11	9
102	910	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9
102A	24	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9
102B	32	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1979	SATISFACTORY	10	11	9
103	800	62	E S E FULL-TIME	10	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9

Page 335 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 10 - Building Number 00010** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
103A	542	65	E S E RESOURCE	0	01	COMPOSITION TILE	1979	SATISFACTORY	10	11	9
103B	152	817	STUDENT RESTROOM & BATH	0	01	CERAMIC TILE	1979	SATISFACTORY	10	11	9
104	53	702	MECHANICAL ROOM	0	01	CONCRETE	1979	SATISFACTORY	10	11	9

	Satis	sfactory	Unsati	sfactory	Failed S	tandards	Scheduled For Replacement		
	Square Feet	uare Feet Student Stations Square Feet Student Sta		Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	3,833	46	0	0					
TOTAL	3,833	46	0	0	0	0	0	0	

Page 336 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 11 - Building Number 00011** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1984	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1984	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	2655	380	LIBRARY (READING ROOM/STACKS)	0	01	CARPET	1984	SATISFACTORY	11	11	9
002	95	702	MECHANICAL ROOM	0	01	CONCRETE	1984	SATISFACTORY	11	11	9
003	140	383	AUDIO VISUAL STORAGE	0	01	CARPET	1984	SATISFACTORY	11	11	9
004	100	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1984	SATISFACTORY	11	11	9
005	30	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1984	SATISFACTORY	11	11	9
006	210	381	MEDIA TECHNICAL PROCESSING	0	01	CARPET	1984	SATISFACTORY	11	11	9
007	400	383	AUDIO VISUAL STORAGE	0	01	CARPET	1984	SATISFACTORY	11	11	9

Page 337 of 1630 Report Date: 4/15/2024 1:35:47 PM

# THE TANK THE

# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 11 - Building Number 00011** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
800	230		TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CARPET	1984	SATISFACTORY	11	11	9
810	450	701	COVERED WALKWAY	0	01	CONCRETE	1984	SATISFACTORY	11	11	9

	Satis	sfactory	Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	4,310	0	0	0					
TOTAL	4,310	0	0	0	0	0	0	0	

Page 338 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 12 - Building Number 00012** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	991	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	12	11	9
101B	56	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	12	11	9
101C	193	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	12	11	9
102	794	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	12	11	9
102A	36	808	MATERIAL STORAGE	0	01	CARPET	1991	SATISFACTORY	12	11	9
102B	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	12	11	9
102C	313	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	12	11	9
103	72	702	MECHANICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	12	11	9

Page 339 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 12 - Building Number 00012** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
104	876	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	12	11	9
104A	31	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1991	SATISFACTORY	12	11	9
104B	130	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	12	11	9
104C	950	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1991	SATISFACTORY	12	11	9
801	800	701	COVERED WALKWAY	0	01	CONCRETE	1991	SATISFACTORY	12	11	9

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet Student Stations		Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	5,278	54	0	0					
TOTAL	5,278	54	0	0	0	0	0	0	

Page 340 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 13 - Building Number 00013** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	992	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	13	11	9
101B	56	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	13	11	9
101C	186	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	13	11	9
102	56	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1991	SATISFACTORY	13	11	9
103	56	703	ELECTRICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	13	11	9
104	239	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	13	11	9
105	490	65	E S E RESOURCE	0	01	CARPET	1991	SATISFACTORY	13	11	9
105C	233	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	13	11	9

Page 341 of 1630 Report Date: 4/15/2024 1:35:47 PM

# THE STATE OF THE S

# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 13 - Building Number 00013** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
106	490	40	RESOURCE ROOM	0	01	CARPET	1991	SATISFACTORY	13	11	9
106C	233	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	13	11	9
107	124	702	MECHANICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	13	11	9
108	798	61	E S E PART-TIME	15	01	CARPET	1991	SATISFACTORY	13	11	9
108A	60	808	MATERIAL STORAGE	0	01	CARPET	1991	SATISFACTORY	13	11	9
108B	56	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	13	11	9
108C	300	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	13	11	9
109	736	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1991	SATISFACTORY	13	11	9
109A	31	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1991	SATISFACTORY	13	11	9
109B	56	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	13	11	9
109C	950	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1991	SATISFACTORY	13	11	9
801	2606	701	COVERED WALKWAY	0	01	CONCRETE	1991	SATISFACTORY	13	11	9

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Square Feet Student Stations		Student Stations	Square Feet	Student Stations	
Permanent	8,748	51	0	0					
TOTAL	8,748	51	0	0	0	0	0	0	

Page 342 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 14 - Building Number 00014** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1992	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	168	305	PRODUCTION WORKROOM	0	01	CARPET	1991	SATISFACTORY	14	11	9
101A	204	306	CONFERENCE ROOM	0	01	CARPET	1991	SATISFACTORY	14	11	9
101B	270	305	PRODUCTION WORKROOM	0	01	CARPET	1991	SATISFACTORY	14	11	9
102	182	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1991	SATISFACTORY	14	11	9
102A	72	702	MECHANICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	14	11	9
103	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	14	11	9
104	303	316	TEACHER LOUNGE/DINING	0	01	CARPET	1991	SATISFACTORY	14	11	9
105	245	306	CONFERENCE ROOM	0	01	CARPET	1991	SATISFACTORY	14	11	9

Page 343 of 1630 Report Date: 4/15/2024 1:35:47 PM

# THE TANK THE

# FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 14 - Building Number 00014** 

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
800	130	700	INSIDE CIRCULATION	0	01	CARPET	1991	SATISFACTORY	14	11	9
801	1932	701	COVERED WALKWAY	0	01	CONCRETE	1994	SATISFACTORY	14	11	9

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	3,542	0	0	0					
TOTAL	3,542	0	0	0	0	0	0	0	

Page 344 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 15 - Building Number 00015** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1991	Intercom: NONE	Walls: RELOCATABLE
Relocatable Units: 0	Telephone: NONE	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	192	333	FLAMMABLE STORAGE	0	01	CONCRETE	1991	SATISFACTORY	15	11	9

	Satisfactory		Unsatisfactory		Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Relocatable	192	0	0	0	0	0	0	0	
TOTAL	192	0	0	0	0	0	0	0	

Page 345 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

**BUILDING: 16 - Covered Play Area** 

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 2022	Artificial Lighting: LIGHT - EMITTING DIODE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 2022	Intercom: NONE	Walls: FACTORY BUILT
Relocatable Units: 0	Telephone: NONE	Struct Comp: STEEL
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	2500	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	2022	SATISFACTORY	16	11	9
800	500	701	COVERED WALKWAY	0	01	CONCRETE	2022	SATISFACTORY	16	11	9

	Satisfactory		Unsati	sfactory	Failed S	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	3,000	0	0	0					
TOTAL	3,000	0	0	0	0	0	0	0	

Page 346 of 1630 Report Date: 4/15/2024 1:35:47 PM

## **FACILITY INVENTORY REPORT**

**DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT** 

**FACILITY: 9-A LILLIAN RUEDIGER ELEMENTARY** 

BUILDING: 99 - Temp building created 6/10/2009 8:55:35 AM

Owner: SCHOOL BOARD	Light: NONE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1999	Artificial Lighting: NONE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1999	Intercom: NONE	Walls: RELOCATABLE
Relocatable Units: 2	Telephone: NONE	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
508	805	317	GENERAL SCHOOL SPACE	0	01	CARPET	1999	SATISFACTORY	99	11	9
508A	49	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1999	SATISFACTORY	99	11	9
525	805	317	GENERAL SCHOOL SPACE	0	01	CARPET	1999	SATISFACTORY	99	11	9
525A	49	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1999	SATISFACTORY	99	11	9

	Satisfactory		Unsatisfactory		Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Relocatable	1,708	0	0	0	0	0	0	0	
TOTAL	1,708	0	0	0	0	0	0	0	

Page 347 of 1630 Report Date: 4/15/2024 1:35:47 PM