FACILITY INVENTORY REPORT

PARCEL: 9

2813 RIDGEWAY STREET

TALLAHASSEE, FL 32304

Parking: PARTIALLY DEVELOPED	Owner: SCHOOL BOARD	Fire: 3
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: COMBINATION
Sewage: PUBLIC	Plan: FINGER	Drainage: INADEQUATE
Landscape: DEVELOPED	Playground: INCLUDED WITH SITE	Acreage: 12.00
Date Acquired: 1/1/1958		Lease Expiration Date:

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 1 - Building 1 (previously listed as part of building 2)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1962	Artificial Lighting: INDIRECT LIGHTING	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1962	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
030	78	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1962	SATISFACTORY	1	9	7
031	140	816	STUDENT RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7

Page 252 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 1 - Building 1 (previously listed as part of building 2)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
032	140	815	STUDENT RESTROOM (MALE)	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
033	475	304	RECEPTION AREA	0	01	CARPET	1962	SATISFACTORY	1	9	7
033A	278	307	CLINIC	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
034	48	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
035	54	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
036	20	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
037	181	305	PRODUCTION WORKROOM	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
037A	126	308	GENERAL SCHOOL STORAGE	0	01	CARPET	1962	SATISFACTORY	1	9	7
037B	126	808	MATERIAL STORAGE	0	01	CARPET	1962	SATISFACTORY	1	9	7
037C	25	822	PUBLIC USE RESTROOM (MALE)	0	01	CERAMIC TILE	1962	SATISFACTORY	1	9	7
038	173	316	TEACHER LOUNGE/DINING	0	01	CARPET	1962	SATISFACTORY	1	9	7
039	154	302	BOOKKEEPING OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
039A	12	702	MECHANICAL ROOM	0	01	CONCRETE	1962	SATISFACTORY	1	9	7
041	236	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
042	195	306	CONFERENCE ROOM	0	01	CARPET	1962	SATISFACTORY	1	9	7
043	85	819	STAFF RESTROOM (MALE)	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
043A	86	820	STAFF RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7
044	183	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
045	171	305	PRODUCTION WORKROOM	0	01	CARPET	1962	SATISFACTORY	1	9	7

Page 253 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 1 - Building 1 (previously listed as part of building 2)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
046	851	306	CONFERENCE ROOM	0	01	CARPET	1962	SATISFACTORY	1	9	7
046A	121	315	TEACHER PLANNING OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
046B	135	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
046C	135	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
046D	202	306	CONFERENCE ROOM	0	01	CARPET	1962	SATISFACTORY	1	9	7
047	119	315	TEACHER PLANNING OFFICE	0	01	CARPET	1962	SATISFACTORY	1	9	7
047A	99	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1962	SATISFACTORY	1	9	7

	Satis	sfactory	Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	4,648	0	0	0					
TOTAL	4,648	0	0	0	0	0	0	0	

Page 254 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1962	Artificial Lighting: INDIRECT LIGHTING	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1962	Intercom: TWO WAY PARTIAL	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1962	SATISFACTORY	2	9	7
001A	41	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	2	9	7
002	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1962	SATISFACTORY	2	9	7
002A	41	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	2	9	7
003	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1962	SATISFACTORY	2	9	7
003A	41	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	2	9	7
004	800	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1962	SATISFACTORY	2	9	7
004A	41	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	2	9	7

Page 255 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 2 - Building Number 00002

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009	769	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1962	SATISFACTORY	2	9	7
009A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	01	QUARRY TILE	2014	SATISFACTORY	2	9	7
010	769	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1962	SATISFACTORY	2	9	7
011	769	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1962	SATISFACTORY	2	9	7
012	769	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1962	SATISFACTORY	2	9	7
013	1062	50	ART - ELEMENTARY	0	01	CARPET	1962	SATISFACTORY	2	9	7
013A	84	805	KILN	0	01	QUARRY TILE	1962	SATISFACTORY	2	9	7
013B	230	810	MATERIAL STORAGE (LARGE)	0	01	QUARRY TILE	1962	SATISFACTORY	2	9	7
013C	134	315	TEACHER PLANNING OFFICE	0	01	CARPET	1962	SATISFACTORY	2	9	7
014	772	10	PRIMARY SKILLS LAB (K-3)	0	01	CARPET	1962	SATISFACTORY	2	9	7
015	772	61	E S E PART-TIME	15	01	CARPET	1962	SATISFACTORY	2	9	7
015A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	01	QUARRY TILE	2014	SATISFACTORY	2	9	7
800	258	700	INSIDE CIRCULATION	0	01	OTHER	1962	SATISFACTORY	2	9	7
801	8858	701	COVERED WALKWAY	0	01	CONCRETE	1962	SATISFACTORY	2	9	7

	Satis	sfactory	Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	18,700	171	0	0					
TOTAL	18,700	171	0	0	0	0	0	0	

Page 256 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1963	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1963	Intercom: TWO WAY PARTIAL	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
024B	18	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1963	SATISFACTORY	3	9	7
025	151	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1963	SATISFACTORY	3	9	7
026	151	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1963	SATISFACTORY	3	9	7
031	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1963	SATISFACTORY	3	9	7
032	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1963	SATISFACTORY	3	9	7
033	736	304	RECEPTION AREA	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033A	180	314	ITINERANT OFFICE	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033B	130	307	CLINIC	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7

Page 257 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 3 - Building Number 00003

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
033C	130	307	CLINIC	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033D	140	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033E	24	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033F	42	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1963	SATISFACTORY	3	9	7
033G	42	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1963	SATISFACTORY	3	9	7
033H	92	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
033J	24	331	CUSTODIAL SERVICE CLOSET	0	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
034	764	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1963	SATISFACTORY	3	9	7
035	764	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1963	SATISFACTORY	3	9	7
801	1464	701	COVERED WALKWAY	0	01	CONCRETE	1963	SATISFACTORY	3	9	7

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	6,380	88	0	0					
TOTAL	6,380	88	0	0	0	0	0	0	

Page 258 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 4 - Building Number 00004

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: LOCAL ZONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1967	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1967	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
005	815	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
005A	22	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1967	SATISFACTORY	4	9	7
005B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
006	757	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1967	SATISFACTORY	4	9	7
006A	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1967	SATISFACTORY	4	9	7
006B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
007	757	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
007A	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1967	SATISFACTORY	4	9	7

Page 259 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 4 - Building Number 00004

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
007B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
800	815	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
008A	22	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1967	SATISFACTORY	4	9	7
008B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
800	415	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1967	SATISFACTORY	4	9	7
801	555	701	COVERED WALKWAY	0	01	CONCRETE	1967	SATISFACTORY	4	9	7

	Satisfactory		Unsati	sfactory	Failed S	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Square Feet Student Stations		Student Stations	Square Feet	Student Stations	
Permanent	4,418	72	0	0					
TOTAL	4,418	72	0	0	0	0	0	0	

Page 260 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 5 - Building Number 00005

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: LOCAL ZONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
501	904	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	5	9	7
501B	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	5	9	7
501C	287	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	5	9	7
502	901	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	5	9	7
502B	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	5	9	7
503	565	40	RESOURCE ROOM	0	01	CERAMIC TILE	1991	SATISFACTORY	5	9	7
503C	261	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	5	9	7
504	852	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	5	9	7

Page 261 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 5 - Building Number 00005

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
504B	36	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	5	9	7
505	68	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1991	SATISFACTORY	5	9	7
506	32	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1991	SATISFACTORY	5	9	7
507	64	703	ELECTRICAL ROOM	0	01	CONCRETE	1991	SATISFACTORY	5	9	7
801	1337	701	COVERED WALKWAY	0	01	CONCRETE	1991	SATISFACTORY	5	9	7

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet Student Stations		Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	5,379	54	0	0					
TOTAL	5,379	54	0	0	0	0	0	0	

Page 262 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 6 - Building Number 00006

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: LOCAL ZONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1991	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
601	848	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	6	9	7
601B	92	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	6	9	7
601C	284	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	6	9	7
602	604	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	6	9	7
603	604	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	6	9	7
603C	321	315	TEACHER PLANNING OFFICE	0	01	CARPET	1991	SATISFACTORY	6	9	7
604	785	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1991	SATISFACTORY	6	9	7
604B	67	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1991	SATISFACTORY	6	9	7

Page 263 of 1630 Report Date: 4/15/2024 1:35:47 PM



FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 6 - Building Number 00006

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
801	427	701	COVERED WALKWAY	0	01	CONCRETE	1991	SATISFACTORY	6	9	7

	Satis	sfactory	Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	4,032	72	0	0					
TOTAL	4,032	72	0	0	0	0	0	0	

Page 264 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 7 - Building 7 (previously part of building 2)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1962	Artificial Lighting: INDIRECT LIGHTING	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1962	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
048	23	827	ELEVATOR (PASSENGER/HANDICAPPED)	0	01	COMPOSITION TILE	1962	SATISFACTORY	7	9	7
048A	655	363	STAGE	0	01	COMPOSITION TILE	1962	SATISFACTORY	7	9	7
049	112	364	STAGE STORAGE	0	01	COMPOSITION TILE	1962	SATISFACTORY	7	9	7
050	3092	340	DINING AREA	0	01	COMPOSITION TILE	1962	SATISFACTORY	7	9	7
051	145	349	KITCHEN CHAIR STORAGE	0	01	COMPOSITION TILE	1962	SATISFACTORY	7	9	7
052	273	341	KITCHEN & SERVING AREA	0	01	OTHER	1962	SATISFACTORY	7	9	7
053	353	341	KITCHEN & SERVING AREA	0	01	OTHER	1962	SATISFACTORY	7	9	7
054	99	344	KITCHEN GARBAGE WASH	0	01	OTHER	1962	SATISFACTORY	7	9	7
055	140	316	TEACHER LOUNGE/DINING	0	01	QUARRY TILE	1962	SATISFACTORY	7	9	7
055A	49	821	STAFF RESTROOM (BOTH SEXES)	0	01	QUARRY TILE	1962	SATISFACTORY	7	9	7
055B	50	700	INSIDE CIRCULATION	0	01	QUARRY TILE	1962	SATISFACTORY	7	9	7

Page 265 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 7 - Building 7 (previously part of building 2)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
056	60	700	INSIDE CIRCULATION	0	01	OTHER	1962	SATISFACTORY	7	9	7
056A	50	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	7	9	7
057	140	347	KITCHEN DISH WASHING	0	01	OTHER	1962	SATISFACTORY	7	9	7
058	765	346	KITCHEN FOOD PREPARATION	0	01	OTHER	1962	SATISFACTORY	7	9	7
059	102	343	KITCHEN OFFICE	0	01	OTHER	1962	SATISFACTORY	7	9	7
060	118	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1962	SATISFACTORY	7	9	7
060A	118	350	OTHER FOOD SERVICE	0	01	QUARRY TILE	1962	SATISFACTORY	7	9	7
061	209	342	KITCHEN DRY STORAGE	0	01	OTHER	1962	SATISFACTORY	7	9	7
061A	101	345	KITCHEN NONFOOD STORAGE	0	01	OTHER	1962	SATISFACTORY	7	9	7
062	85	344	KITCHEN GARBAGE WASH	0	01	CONCRETE	1962	SATISFACTORY	7	9	7
063	477	702	MECHANICAL ROOM	0	01	CONCRETE	1962	SATISFACTORY	7	9	7
064	149	703	ELECTRICAL ROOM	0	01	CONCRETE	1962	SATISFACTORY	7	9	7
064A	22	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1962	SATISFACTORY	7	9	7
065	270	700	INSIDE CIRCULATION	0	01	CERAMIC TILE	1962	SATISFACTORY	7	9	7

	Satis	sfactory	Unsati	sfactory	Failed St	tandards	Scheduled For Replacement			
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations		
Permanent	7,657	0	0	0						
TOTAL	7,657	0	0	0	0	0 0		0		

Page 266 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 8 - Building 8 (previously listed as building 1)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1983	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT WATER
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1984	Intercom: TWO WAY PARTIAL	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
016	967	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
016A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
016B	168	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
016C	300	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
017	941	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
017A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
017B	168	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
017C	103	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
018	941	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
018A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
018B	168	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7

Page 267 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 8 - Building 8 (previously listed as building 1)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
018C	300	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
019	941	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
019A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
019B	168	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
019C	103	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
020	612	312	COMPUTER AREA	0	01	CARPET	1983	SATISFACTORY	8	9	7
020A	146	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
020B	31	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
021	247	702	MECHANICAL ROOM	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
022	609	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
023	782	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
023A	96	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
023B	32	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
023C	147	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
023D	51	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
024	967	20	INTERMEDIATE/MIDDLE SCIENCE DEMO (4-8)	22	01	COMPOSITION TILE	1983	SATISFACTORY	8	9	7
024A	27	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
024B	93	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
025	967	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7

Page 268 of 1630 Report Date: 4/15/2024 1:35:47 PM

THE STATE OF THE S

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 8 - Building 8 (previously listed as building 1)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
025A	27	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
025B	79	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
026	964	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
026A	27	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
026B	79	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
026C	140	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
027	964	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
027A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
028	964	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
028A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
029	967	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
029A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
030	988	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1983	SATISFACTORY	8	9	7
030A	34	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
055	3084	380	LIBRARY (READING ROOM/STACKS)	0	01	CARPET	1983	SATISFACTORY	8	9	7
055A	308	387	MEDIA PRODUCTION LAB	0	01	CARPET	1983	SATISFACTORY	8	9	7
055B	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1983	SATISFACTORY	8	9	7
055C	42	816	STUDENT RESTROOM (FEMALE)	0	01	QUARRY TILE	1983	SATISFACTORY	8	9	7
055D	42	815	STUDENT RESTROOM (MALE)	0	01	COMPOSITION TILE	1983	SATISFACTORY	8	9	7

Page 269 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 8 - Building 8 (previously listed as building 1)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
055E	161	385	CLOSED CIRCUIT TV LAB	0	01	CARPET	1983	SATISFACTORY	8	9	7
055F	66	387	MEDIA PRODUCTION LAB	0	01	CARPET	1983	SATISFACTORY	8	9	7
055G	234	381	MEDIA TECHNICAL PROCESSING	0	01	CARPET	2011	SATISFACTORY	8	9	7
055H	137	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	2011	SATISFACTORY	8	9	7
055J	338	390	MEDIA GROUP PROJECTS/INSTRUCTION	0	01	CARPET	2011	SATISFACTORY	8	9	7
055K	137	389	MEDIA SMALL GROUP ROOM	0	01	CARPET	2011	SATISFACTORY	8	9	7
055L	98	383	AUDIO VISUAL STORAGE	0	01	CARPET	2011	SATISFACTORY	8	9	7
056	133	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
056A	41	703	ELECTRICAL ROOM	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
057	88	702	MECHANICAL ROOM	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
058A	34	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
058B	36	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
060	896	10	PRIMARY SKILLS LAB (K-3)	0	01	CARPET	1983	SATISFACTORY	8	9	7
060A	56	808	MATERIAL STORAGE	0	01	CARPET	1983	SATISFACTORY	8	9	7
060B	180	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
060C	242	315	TEACHER PLANNING OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
061	375	316	TEACHER LOUNGE/DINING	0	01	CARPET	1983	SATISFACTORY	8	9	7
062A	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7
062B	36	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1983	SATISFACTORY	8	9	7

Page 270 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 8 - Building 8 (previously listed as building 1)

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
063	209	314	ITINERANT OFFICE	0	01	CARPET	1983	SATISFACTORY	8	9	7
064	560	40	RESOURCE ROOM	0	01	CARPET	1983	SATISFACTORY	8	9	7
800	602	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1983	SATISFACTORY	8	9	7
801	3239	701	COVERED WALKWAY	0	01	CONCRETE	1983	SATISFACTORY	8	9	7
814	3360	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1992	SATISFACTORY	8	9	7

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	30,352	238	0	0					
TOTAL	30,352	238	0	0	0	0	0	0	

Page 271 of 1630 Report Date: 4/15/2024 1:35:47 PM

THE STATE OF THE S

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 9 - Building 9 (previously listed as building 7)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1992	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1992	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
701	192	333	FLAMMABLE STORAGE	0	01	CONCRETE	1992	SATISFACTORY	9	9	7

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	192	0	0	0					
TOTAL	192	0	0	0	0	0	0	0	

Page 272 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 10 - Building 10 (previously listed as building 8)

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2010	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT RADIANT
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2011	Intercom: TWO WAY COMPLETE	Walls: CONCRETE
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
002	306	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	2011	SATISFACTORY	10	9	7
003	716	13	ELEMENTARY P E STORAGE	0	01	COMPOSITION TILE	2011	SATISFACTORY	10	9	7

	Satisfactory		Unsati	sfactory	Failed St	tandards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent	1,022	0	0	0					
TOTAL	1,022	0	0	0	0	0	0	0	

Page 273 of 1630 Report Date: 4/15/2024 1:35:47 PM

THE ST

FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 89 - Building Number 00089

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: MIDDLE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1974	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1974	Intercom: TWO WAY COMPLETE	Walls: RELOCATABLE
Relocatable Units: 2	Telephone: NONE	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
108	638	317	GENERAL SCHOOL SPACE	0	01	CARPET	1974	SATISFACTORY	89	9	7
108B	29	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1974	SATISFACTORY	89	9	7
135	759	317	GENERAL SCHOOL SPACE	0	01	CARPET	1974	SATISFACTORY	89	9	7
135A	25	808	MATERIAL STORAGE	0	01	CARPET	1974	SATISFACTORY	89	9	7
135B	46	820	STAFF RESTROOM (FEMALE)	0	01	COMPOSITION TILE	1974	SATISFACTORY	89	9	7

	Satisfactory		Unsati	sfactory	Failed St	andards	Scheduled For Replacement		
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Relocatable	1,497	0	0	0	0	0	0	0	
TOTAL	1,497	0	0	0	0	0	0	0	

Page 274 of 1630 Report Date: 4/15/2024 1:35:47 PM

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 7-A SABAL PALM ELEMENTARY

BUILDING: 99 - Building Number 00099

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1970	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1970	Intercom: TWO WAY COMPLETE	Walls: RELOCATABLE
Relocatable Units: 2	Telephone: NONE	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
317A	712	317	GENERAL SCHOOL SPACE	0	01	CARPET	1970	SATISFACTORY	99	9	7
317B	712	317	GENERAL SCHOOL SPACE	0	01	CARPET	1970	SATISFACTORY	99	9	7
317C	15	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1970	SATISFACTORY	99	9	7
317D	15	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1970	SATISFACTORY	99	9	7

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Relocatable	1,454	0	0	0	0	0	0	0
TOTAL	1,454	0	0	0	0	0	0	0

Page 275 of 1630 Report Date: 4/15/2024 1:35:47 PM