



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY

BUILDING: 1 - Building Number 00001

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 2003	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2003	Intercom: TWO WAY PARTIAL	Walls: OTHER
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	4636	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2003	SATISFACTORY	1	76	70
002	41	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2003	SATISFACTORY	1	76	70
002A	206	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2003	SATISFACTORY	1	76	70
002B	44	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	2003	SATISFACTORY	1	76	70
002C	44	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	2003	SATISFACTORY	1	76	70
003	105	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	2003	SATISFACTORY	1	76	70
004	648	594	ANCILLARY SUPPORT STORAGE	0	01	CONCRETE	2003	SATISFACTORY	1	76	70
005	56	589	SCHOOL BUS PAINT/FLAMMABLE STORAGE	0	01	CONCRETE	2003	SATISFACTORY	1	76	70



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY
BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
006	116	416	ANCILLARY CUSTODIAL SERVICES	0	01	CONCRETE	2003	SATISFACTORY	1	76	70
007	48	594	ANCILLARY SUPPORT STORAGE	0	01	CONCRETE	2003	SATISFACTORY	1	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,944	0	0	0	0	0	0	0
TOTAL	5,944	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY
BUILDING: 2

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 2009	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 2009	Intercom: NONE	Walls: OTHER
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	2305	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2009	SATISFACTORY	2	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	2,305	0	0	0	0	0	0	0
TOTAL	2,305	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY
BUILDING: 3

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2019	Artificial Lighting: LIGHT - EMITTING DIODE	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: FIXED SERVICE RECEIVER	Heat Capacity: ADEQUATE
Average Age NSF: 2019	Intercom: NONE	Walls: OTHER
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: STEEL
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	133	404	ANCILLARY RECEPTION AREA	0	01	COMPOSITION TILE	2019	SATISFACTORY	3	76	70
102	49	821	STAFF RESTROOM (BOTH SEXES)	0	01	OTHER	2019	SATISFACTORY	3	76	70
103	506	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	2019	SATISFACTORY	3	76	70
104	49	821	STAFF RESTROOM (BOTH SEXES)	0	01	OTHER	2019	SATISFACTORY	3	76	70
105	19	808	MATERIAL STORAGE	0	01	CARPET	2019	SATISFACTORY	3	76	70
106	59	702	MECHANICAL ROOM	0	01	CONCRETE	2019	SATISFACTORY	3	76	70
107	97	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	2019	SATISFACTORY	3	76	70
108	97	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2019	SATISFACTORY	3	76	70



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY

BUILDING: 3

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
109	97	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2019	SATISFACTORY	3	76	70
110	97	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2019	SATISFACTORY	3	76	70
111	97	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2019	SATISFACTORY	3	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
	Permanent	1,300	0	0	0	0	0	0
TOTAL	1,300	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY

BUILDING: 4

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2020	Artificial Lighting: LIGHT - EMITTING DIODE	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMMERCIAL CABLE	Heat Capacity: ADEQUATE
Average Age NSF: 2020	Intercom: NONE	Walls: OTHER
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: STEEL
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	614	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2020	SATISFACTORY	4	76	70
102	54	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	2020	SATISFACTORY	4	76	70
103	24	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	2020	SATISFACTORY	4	76	70
104	13	703	ELECTRICAL ROOM	0	01	COMPOSITION TILE	2020	SATISFACTORY	4	76	70
105	24	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	2020	SATISFACTORY	4	76	70
106	13	331	CUSTODIAL SERVICE CLOSET	0	01	CARPET	2020	SATISFACTORY	4	76	70
107	570	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2020	SATISFACTORY	4	76	70
800	33	700	INSIDE CIRCULATION	0	01	CARPET	2020	SATISFACTORY	4	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	1,345	0	0	0	0	0	0	0
TOTAL	1,345	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY

BUILDING: 5

Owner: SCHOOL BOARD	Light: INADEQUATE	Cooling: NONE
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 2009	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF:	Intercom: NONE	Walls: OTHER
Relocatable Units: 0	Telephone: NONE	Struct Comp: PERMANENT OTHER
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	2301	702	MECHANICAL ROOM	0	01	CARPET	2009	SATISFACTORY	5	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Modular	2,301	0	0	0				
TOTAL	2,301	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY
BUILDING: 99 - Temp building created 7/28/2009 10:23:04 AM

Owner: SCHOOL BOARD	Light: NONE				Cooling: NONE			
Use: TRANSPORTATION	Mech Vent: NONE				Heat Source: NONE			
Year Constructed: 1980	Artificial Lighting: NONE				Heat Distribution: NO HEAT PROVIDED			
Year Modified:	Educational TV: NONE				Heat Capacity: NONE			
Average Age NSF: 1980	Intercom: NONE				Walls: RELOCATABLE			
Relocatable Units: 1	Telephone: NONE				Struct Comp: RELOCATABLE			
Stories: 1					Corridor: NONE			

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
401A	732	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	1980	UNSATISFACTORY	99	76	70
401B	20	808	MATERIAL STORAGE	0	01	OTHER	1980	UNSATISFACTORY	99	76	70
401C	20	821	STAFF RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1980	UNSATISFACTORY	99	76	70
401D	220	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1980	UNSATISFACTORY	99	76	70
401E	143	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1980	UNSATISFACTORY	99	76	70
401F	148	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	CARPET	1980	UNSATISFACTORY	99	76	70
401G	8	808	MATERIAL STORAGE	0	01	CARPET	1980	UNSATISFACTORY	99	76	70
401H	72	808	MATERIAL STORAGE	0	01	CARPET	1980	UNSATISFACTORY	99	76	70



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY
BUILDING: 99 - Temp building created 7/28/2009 10:23:04 AM

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
401J	8	808	MATERIAL STORAGE	0	01	OTHER	1980	UNSATISFACTORY	99	76	70
401K	52	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1980	UNSATISFACTORY	99	76	70

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Relocatable	0	0	1,423	0	0	0	0	0
TOTAL	0	0	1,423	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:																			
FACILITY: CONNOR BOULEVARD TRANSPORTATION FACILITY																			
Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00331	CUSTODIAL SERVICE CLOSET	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00401	ANCILLARY CONFERENCE ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	1	0	0	0	0
00403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	3	0	0	0	0
00404	ANCILLARY RECEPTION AREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00407	ANCILLARY ADMINISTRATIVE OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00416	ANCILLARY CUSTODIAL SERVICES	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00421	ANCILLARY STAFF LOUNGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00426	GENERAL ANCILLARY OFFICE	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	0
00589	SCHOOL BUS PAINT/FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00592	SCHOOL BUS WORK BAY	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00594	ANCILLARY SUPPORT STORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00700	INSIDE CIRCULATION	0	0	0	0	0	0	0	0	2	0	0	0	0	1	0	0	0	0
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00808	MATERIAL STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	4	0	0	0	0
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	5	0	0	0	0	1	0	0	0	0
00824	ANCILLARY RESTROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00825	ANCILLARY RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
Totals:		0	0	0	0	0	0	0	0	30	1	0	0	0	10	0	0	0	0