



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

FACILITY: 69-F MAIN TRANSPORTATION FACILITY

Primary Use: TRANSPORTATION Grades Housed: DS - DS DOE Validation Date:

Capital Outlay Classification: ANCILLARY RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
69	None	Inactive
9001	LEON DISTRICT OFFICE	Default

CAPITAL OUTLAY FTE

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
0	0	0.00	TRANSPORTATION

PARCEL: 75

1156 CAPITAL CIRCLE SW
TALLAHASSEE, FL 32304

Parking: PARTIALLY DEVELOPED	Owner: SCHOOL BOARD	Fire: 10
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: COUNTY
Sewage: PUBLIC	Plan: CAMPUS	Drainage: ADEQUATE
Landscape: NOT DEVELOPED	Playground: NO PARK/PUBLIC ACCESS	Acreage: 17.00
Date Acquired: 9/16/2005		Lease Expiration Date:



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 1

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: OIL
Year Constructed: 2005	Artificial Lighting: UNSHIELDED INCANDESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2005	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: STEEL
Stories: 2		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	180	422	MAIN LOBBY & SWITCHBOARD	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
002	100	404	ANCILLARY RECEPTION AREA	0	01	CARPET	2005	SATISFACTORY	1	75	69
003	90	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
004	20	594	ANCILLARY SUPPORT STORAGE	0	01	CARPET	2005	SATISFACTORY	1	75	69
005	110	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
006	102	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
007	14	594	ANCILLARY SUPPORT STORAGE	0	01	CARPET	2005	SATISFACTORY	1	75	69
008	251	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
009	125	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
010	244	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
011	125	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 69-F MAIN TRANSPORTATION FACILITY

BUILDING: 1

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
012	212	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
013	20	594	ANCILLARY SUPPORT STORAGE	0	01	CARPET	2005	SATISFACTORY	1	75	69
014	38	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	2005	SATISFACTORY	1	75	69
015	38	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	2005	SATISFACTORY	1	75	69
016	132	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
017	106	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	CARPET	2005	SATISFACTORY	1	75	69
017A	180	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	CARPET	2005	SATISFACTORY	1	75	69
018	110	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
019	88	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	CARPET	2005	SATISFACTORY	1	75	69
020	185	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
021	142	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	1	75	69
022	294	401	ANCILLARY CONFERENCE ROOM	0	01	CARPET	2005	SATISFACTORY	1	75	69
023	62	825	ANCILLARY RESTROOM (FEMALE)	0	01	CERAMIC TILE	2005	SATISFACTORY	1	75	69
024	62	824	ANCILLARY RESTROOM (MALE)	0	01	CERAMIC TILE	2005	SATISFACTORY	1	75	69
025	60	702	MECHANICAL ROOM	0	01	CONCRETE	2005	SATISFACTORY	1	75	69
026	140	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
700	375	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
700a	55	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
700b	75	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 1

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
700c	55	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
700d	310	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
700e	44	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2005	SATISFACTORY	1	75	69
101	210	426	GENERAL ANCILLARY OFFICE	0	02	CARPET	2005	SATISFACTORY	1	75	69
102	140	426	GENERAL ANCILLARY OFFICE	0	02	CARPET	2005	SATISFACTORY	1	75	69
103	416	424	DIRECTORS OFFICE	0	02	CARPET	2005	SATISFACTORY	1	75	69
103a	24	824	ANCILLARY RESTROOM (MALE)	0	02	CONCRETE	2005	SATISFACTORY	1	75	69
103b	135	594	ANCILLARY SUPPORT STORAGE	0	02	CARPET	2005	SATISFACTORY	1	75	69
			Satisfactory	Unsatisfactory		Failed Standards		Scheduled For Replacement			
			Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent			5,069	0	0	0	0				
TOTAL			5,069	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 3

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 2005	Artificial Lighting: UNSHIELDED INCANDESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 2005	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: STEEL
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	1285	591	SCHOOL BUS TIRE STORAGE & MOUNTING	0	01	CONCRETE	2005	SATISFACTORY	3	75	69

Satisfactory			Unsatisfactory			Failed Standards			Scheduled For Replacement		
Square Feet		Student Stations	Square Feet		Student Stations	Square Feet		Student Stations	Square Feet		Student Stations
Permanent		1,285	0		0	0		0	0		0
TOTAL		1,285	0		0	0		0	0		0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 5

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: TRANSPORTATION	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 2005	Artificial Lighting: UNSHIELDED INCANDESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 2005	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: STEEL
Stories: 2		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
101	1105	593	SCHOOL BUS DRIVERS CLASSROOM	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
102	209	824	ANCILLARY RESTROOM (MALE)	0	01	OTHER	2005	SATISFACTORY	5	75	69
103	216	825	ANCILLARY RESTROOM (FEMALE)	0	01	OTHER	2005	SATISFACTORY	5	75	69
104	176	403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
105	195	424	DIRECTORS OFFICE	0	01	CONCRETE	2005	SATISFACTORY	5	75	69
106	141	401	ANCILLARY CONFERENCE ROOM	0	01	CONCRETE	2005	SATISFACTORY	5	75	69
107	60	418	ANCILLARY ADMINISTRATIVE STORAGE	0	01	CONCRETE	2005	SATISFACTORY	5	75	69



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 69-F MAIN TRANSPORTATION FACILITY

BUILDING: 5

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
108	62	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
109	29	416	ANCILLARY CUSTODIAL SERVICES	0	01	OTHER	2005	SATISFACTORY	5	75	69
110	482	421	ANCILLARY STAFF LOUNGE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
111	92	407	ANCILLARY ADMINISTRATIVE OFFICE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
112	94	426	GENERAL ANCILLARY OFFICE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
113	92	426	GENERAL ANCILLARY OFFICE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
114	113	426	GENERAL ANCILLARY OFFICE	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
115	203	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
116	2554	586	SCHOOL BUS MACHINE SHOP	0	01	CONCRETE	2005	SATISFACTORY	5	75	69
202D	243	426	GENERAL ANCILLARY OFFICE	0	01	CARPET	2005	SATISFACTORY	5	75	69
202E	280	702	MECHANICAL ROOM	0	01	CONCRETE	2005	SATISFACTORY	5	75	69
201	38	700	INSIDE CIRCULATION	0	02	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
202	383	426	GENERAL ANCILLARY OFFICE	0	02	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
202A	75	418	ANCILLARY ADMINISTRATIVE STORAGE	0	02	COMPOSITION TILE	2005	SATISFACTORY	5	75	69
202B	42	821	STAFF RESTROOM (BOTH SEXES)	0	02	OTHER	2005	SATISFACTORY	5	75	69



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 5

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
202C	124	426	GENERAL ANCILLARY OFFICE	0	02	CARPET	2005	SATISFACTORY	5	75	69
			Satisfactory	Unsatisfactory		Failed Standards		Scheduled For Replacement			
			Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Permanent			7,008	0	0	0					
TOTAL			7,008	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT
FACILITY: 69-F MAIN TRANSPORTATION FACILITY
BUILDING: 6

Owner: SCHOOL BOARD		Light: ADEQUATE		Cooling: CENTRAL	
Use: TRANSPORTATION		Mech Vent: ADEQUATE		Heat Source: ELECTRIC	
Year Constructed: 2009		Artificial Lighting: SHIELDED FLORESCENT		Heat Distribution: CENTRAL HOT AIR	
Year Modified:		Educational TV: NONE		Heat Capacity: ADEQUATE	
Average Age NSF: 2010		Intercom: NONE		Walls: OTHER	
Relocatable Units: 0		Telephone: NONE		Struct Comp: COMBINATION OF 1-3	
Stories: 1				Corridor: NONE	

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	6900	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2009	SATISFACTORY	6	75	69
002	2408	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2009	SATISFACTORY	6	75	69
003	990	592	SCHOOL BUS WORK BAY	0	01	CONCRETE	2009	SATISFACTORY	6	75	69
104	107	594	ANCILLARY SUPPORT STORAGE	0	01	CONCRETE	2016	SATISFACTORY	6	75	69
105	502	540	ELECTRONICS SHOP	0	01	OTHER	2016	SATISFACTORY	6	75	69
106	1269	585	SCHOOL BUS PARTS ROOM	0	01	OTHER	2016	SATISFACTORY	6	75	69
106A	30	586	SCHOOL BUS MACHINE SHOP	0	01	OTHER	2016	SATISFACTORY	6	75	69
107	14	594	ANCILLARY SUPPORT STORAGE	0	01	OTHER	2016	SATISFACTORY	6	75	69



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 37 LEON COUNTY SCHOOL DISTRICT

FACILITY: 69-F MAIN TRANSPORTATION FACILITY

BUILDING: 6

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
108	45	416	ANCILLARY CUSTODIAL SERVICES	0	01	OTHER	2016	SATISFACTORY	6	75	69
109	125	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	OTHER	2016	SATISFACTORY	6	75	69
109A	119	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	OTHER	2016	SATISFACTORY	6	75	69
109B	119	428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	01	OTHER	2016	SATISFACTORY	6	75	69
110	270	825	ANCILLARY RESTROOM (FEMALE)	0	01	OTHER	2016	SATISFACTORY	6	75	69
111	270	824	ANCILLARY RESTROOM (MALE)	0	01	OTHER	2016	SATISFACTORY	6	75	69
112	80	703	ELECTRICAL ROOM	0	01	CONCRETE	2016	SATISFACTORY	6	75	69
113	85	594	ANCILLARY SUPPORT STORAGE	0	01	CONCRETE	2016	SATISFACTORY	6	75	69
114	85	589	SCHOOL BUS PAINT/FLAMMABLE STORAGE	0	01	CONCRETE	2016	SATISFACTORY	6	75	69
115	557	702	MECHANICAL ROOM	0	01	CONCRETE	2016	SATISFACTORY	6	75	69

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	13,975	0	0	0	0	0	0	0
TOTAL	13,975	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:																			
FACILITY: MAIN TRANSPORTATION FACILITY																			
Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo				
00401	ANCILLARY CONFERENCE ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00403	ANCILLARY SECRETARIAL/CLERICAL OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00404	ANCILLARY RECEPTION AREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00407	ANCILLARY ADMINISTRATIVE OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00416	ANCILLARY CUSTODIAL SERVICES	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00418	ANCILLARY ADMINISTRATIVE STORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00421	ANCILLARY STAFF LOUNGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00422	MAIN LOBBY & SWITCHBOARD	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00424	DIRECTORS OFFICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00426	GENERAL ANCILLARY OFFICE	0	0	0	0	0	0	0	0	19	0	0	0	0	0	0	0	0	0
00428	OTHER ANCILLARY ADMINISTRATIVE SUPPORT	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00540	ELECTRONICS SHOP	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00585	SCHOOL BUS PARTS ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00586	SCHOOL BUS MACHINE SHOP	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00589	SCHOOL BUS PAINT/FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00591	SCHOOL BUS TIRE STORAGE & MOUNTING	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00592	SCHOOL BUS WORK BAY	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00593	SCHOOL BUS DRIVERS CLASSROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00594	ANCILLARY SUPPORT STORAGE	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00700	INSIDE CIRCULATION	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:																					
FACILITY: MAIN TRANSPORTATION FACILITY																					
		Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms		
Design Code	Design Code Description	Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo		
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0		
00824	ANCILLARY RESTROOM (MALE)	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	0		
00825	ANCILLARY RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0		
Totals:		0	0	0	0	0	0	0	0	80	0	0	0	0	0	0	0	0	0		

FACILITY: 70-F CONNOR BOULEVARD TRANSPORTATION FACILITY

Primary Use: TRANSPORTATION Grades Housed: DS - DS DOE Validation Date: Capital Outlay Classification: ANCILLARY RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
70	None	Inactive
9001	LEON DISTRICT OFFICE	Default

CAPITAL OUTLAY FTE

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
0	0	0.00	TRANSPORTATION

PARCEL: 76



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

3601 CONNOR BLVD
TALLAHASSEE, FL 32311

Parking: DEVELOPED	Owner: SCHOOL BOARD	Fire: 1
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: COMBINATION
Sewage: PUBLIC	Plan: COMPACT	Drainage: ADEQUATE
Landscape: PARTIALLY DEVELOPED	Playground: NO PARK/PUBLIC ACCESS	Acreage: 20.00
Date Acquired: 1/1/2002		Lease Expiration Date: