INSPECTION DATE			Apalachee Elementary	ementary	
1				To the state of th	
	۴		SCHOOL	OL FACILITY	FACILITY/CAMPUS
2	7.		650 Trojan Trail		
21/0/0	Len	STOOMS ALUNOS LIGHT	Tallahassee,	Florida 32311	
INSPECTOR SIGNATURE	TURE	FACITLITIES & CONSTR		ADDRESS	
\neg	TO MOTE CHOM		The second secon	TI OLI MITTA	000
FIRE CASUALTY	ALTY V	SANITATION COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2015-2016		037-0441-044	OLN.
Building# Room#	* > <	Deficiency Description and Corrective Action Required	Number of	Schedule for	DEMARKS
	0 0		times	Correction	
0000			Deficiency	NLT	
+	C	Site-Wide, After Market Furniture Shall Be (NFPA) Approved and the Label Must Be Displayed.	alots of control		
0000	3	Missing Bars on Fixtures at the Playground, Near Building 7, Install Benjacement Barr on Electronic	1		Silewide
0000 0000	0	Remove Combustible Materials Hanging From the Calling Materials No. 14 10 10 10 10 10 10 10 10 10 10 10 10 10	2		
0000 0000	0	Site-Wide, Fire Ant Mounds Found in Several Locations Borners Fig. 1. Site-Wide, Fire Ant Mounds Found in Several Locations Borners Fig. 1.	4		Sitewide
0000 0000	С	No (ADA) Handrail on Ramos Install (ADA) Handrail on Ramos Install (ADA) Handrail on Ramos Install (ADA) Handrail	4		Sitewide
0001 000	Σ	Emergency Telephone is Not Opposition 2			SREF 5(10)(8)
0001 000	Ζ	Fire Alarm Control Board in St.	1		
0000 0000	0	Sto Wide District 18 Snowing a Frouble Alarm on the Panel.	0		
0000 0000	2	Whodo Bowell Fountains are Required to be Cleaned Regularly.	0		Sitewide
+	3	Wheelshair Ball Jamaged with Rotting Wood and Exposed Nails. Replace Deteriorated Wooden Ramps.	0		Sitewide
+	3	Processial boildeds are paraged with Rotting Wood and Exposed Nails. Replace Wheelchair Bollards.	0		Sitewide
+		(ADD) nationalis are Damaged with Rotting Wood and Exposed Nails Replace Deteriorated Handrails.	0		SPEE S(40)/O)
+	N N	Emergency Telephone is Not Operating Properly. Repair or Replace Emergency Telephone.	1		
+	C	Remove Storage for Bathroom, Bathrooms Cannot be Utilized as a Storage Area.	١.		
200	3	Automatic Door Closer is Not Operating Properly. Adjust Automatic Door Closer to Open Door Property.	-		
106	Z	Re-Attach Damaged Floor Moldings.			
0001 107	3	oser to the Entry Door to Ensure Lights Company III	0		
0001 107 A	0	Potty Parity Shall Be Maintained at All Times.	2		
0001 109	Ζ	Exit Door is Slamming Closed	0		
0001 110	3	Missing Bathroom Signage, Install Bathroom Sign	0		
0001 112	×	Directional Chevrons Shall Show the Direction of Economics Inc.	0		- Anna
0001 112	N	Sprinkler Heads are Missing Escuteboop Discussional Land Land Land Chevron Showing the Means of Egress.	0		
rincipal shall hold at least	t one (1) eme	The principal shall hold at least one (1) emergency drill during each month, with an additional daily. Install Esculcheon Rings on All Sprinkler Heads.	ω		
e administration of the little 30 days of school		YES X	ON	The same of the sa	THE RESERVE AND PROPERTY OF THE PERSON NAMED IN STREET, SANSON NAMED IN STREET

3/21/16

Page 3 of 4

Date

4/28/1

Page 4 of 4