

To: Ms. Jennifer Ricardo, Principal, Apalachee Tapestry Magnet School of Arts

Dr. Yvonne Jones, Assistant Principal, Apalachee Tapestry Magnet School of Arts

Mr. Alvin "Butch" Watkins, Director of Maintenance Mr. Danny Allbritton, Director of Construction

From: Mr. Juan E. Williams, Coordinator, Fire & Safety

Through: Mr. LaRoderick E. McQueen, Building Official

Date: February 1, 2021

Subject: SREF Inspection for Apalachee Tapestry Magnet School of Arts

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Please do not submit work orders for the deficiency line items in the M (Maintenance) column. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction and Capital Outlay) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement and Compliance Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Deanetra S. Grissom at grissomd@leonschools.net or fax the report to (850) 617-1790, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board.

**Additionally a separate inspection report has been provided for each portable at your site, in accordance with SREF Chapter 4
Section 4.4 (2)**

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Juan Williams at the Code Enforcement and Compliance Department at (850) 617-1814 or email at williams 20@leonschools.net. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc: Ms. Susan Kraul, Director of Elementary Schools (with attachments)

"Our Hands Keep Their Minds Working"

Code Enforcement and Compliance Department & Small Business Enterprise- 3420 West Tharpe Street - Suite 200 - Tallahassee, Florida 32303-1138 (850) 617-1838 · Fax (850) 617-1790

www.lcscodeenforcement@leoncountyschools.net

"The Leon County School District does not discriminate against any person on the basis of sex (including transgender status, gender nonconforming and gender identity), race, age, color, ethnicity, national origin, religion, pregnancy, marital status, disability, sexual orientation, or genetic information."

2/2/2021

INSPECTION DATE

INSPECTOR: Juan E. Williams

INSPECTOR SIGNATURE

SIGNATURE DATE

TYPE OF INSPECTION



FACITLITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303

COMPREHENSIVE SAFETY INSPECTION

Apalachee Elementary School SCHOOL/ FACILITY/CAMPUS

850 Trojan Trail

Tallahassee, Florida 32311

F.I.S.H. NUMBER

×	FIRE X	CASUAL	TY 💥	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2020-2021	037-0441-044				
Item #	Building Number	Room Number	M O C	Deficier	cy Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
1	0000	000	0	Rake fall surface	s on all playgrounds weekly.	3			Campus	
2	0000	000	0	Air fresheners, d	eodorizers, and plug-ins are not permitted on campus per SREF.	3				
3	0000	000	С	Portables on site	for four (4) or more years are required by SREF to have covered walkway.	3				SREF 5 (14)(b) 3.a
4	0001	000	0	Remove combus	tible material from ceiling.	0				
5	0001	000	0	All open electric	al sockets need covers in Pre-K rooms.	0				
6	0001	101	М	Fire Alarm in Ti	ouble Mode.	0				Building Automation
7	0001	103	М	Trip/fall hazard	- Several snags in carpet around floor outlet.	1				Structural Department
8	0001	108	0	Replace missing	ceiling tile.	1				
9	000	109	М	Adjustment nee	led to slamming exterior door.	0				Structural Department
10	0001	117	0	Investigate leak,	replace and date stained ceiling tile.	2				
11	0001	119A	М	F.I.S.H. number	needed.	1				Sign Shop
12	0001	120A	М	F.I.S.H. number	needed.	1				Sign Shop
13	0001	122	0	Tissue holder in	bathroom stall is off the wall - replace.	1				
14	0001	135	0	Festive lighting	is only temporary for 60 days.	0				
15	0001	142	M	Escutcheon mis	sing on sprinkler head.	0				EH&S

Printed: 2/2/2021 - 1:41 PM

NAPPECTOR SIGNATURE		CTION DA				The second secon		Apalachee Elementary School SCHOOL/ FACILITY/CAMPUS					
Signature Signature Signature Date Type of INSPECTION SANITATION SANITATION COMPREHENSIVE SAFETY IN SPECTION STALLANASSEE, FL 32303 SANITATION SANITATION COMPREHENSIVE SAFETY IN SPECTION STALLANASSEE, FL 32303 SANITATION S	NOPE	CIOK. 3	ruari E. Y	viiliairis	•	I SON COURTY STRONG	850 Trojan Trail Tallahassee, Florida 32311						
FIRE CASUALT SANITATION SAZOW. THASPE ST., TALLAHASSEE, FL 32203 SANITATION SOMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2028-2021 SANITATION SCHOOLING SANITATION SCHOOLING SCHOOLING						SCOII COUNTY SCHOOLS	Turranassee, Frontia 52511						
First Standard S	NSPEC						F.I.S.H. NUMBER						
Perficiency Description and Corrective Action Required Performance	*				SANITATION	COMPREHENSIVE SAFETY INSPECTION							
17 147 147 M "Fire Sprinkler Room" sign needed. 0 Sign	Item		Room	M O	<u>Deficien</u>		Deficiency Previously	Correction No Later	Re- Inspection Correction	Site-Wide Building- Wide Exterior Campus or	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT		
18	16	0001	146	0	Reduce the amou	ant of storage in the Electrical Room.	1						
19	17	0001	147	M	"Fire Sprinkler F	Room" sign needed,	0				Sign Shop		
20 0003 304 M Adjustment needed to slamming door. 0 Structural 21 0003 306 O Keep Emergency Escape Window clear at all times. 1 1 22 0003 309 M Repair gutter downspout outside of #03-309. 0 Structural 23 0003 309 M Verify if hot water heater is operating, if not remove or replace. 0 Plumbing 24 0004 000 O Pressure wash all exterior side of doors. Door have mildew building up on them. 1 1 25 0004 402 O Blocked fire escape. 0 0 1 26 0004 402 O Temporary extension cords are not allowed. All plugs shall be plugged into a dedicated permanent power source. (orange) 0 Structural 27 0005 501 M Flammable storage missing ceiling. 0 Structural 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. 4	18	0002	000	0	All fencing arou	nd Mechanical Unit needs to be locked.	2						
21 0003 306 O Keep Emergency Escape Window clear at all times. 1 22 0003 309 M Repair gutter downspout outside of #03-309. 0 Structural 23 0003 309 M Verify if hot water heater is operating, if not remove or replace. 0 Plumbing 24 0004 000 O Pressure wash all exterior side of doors. Door have mildew building up on them. 1 25 0004 402 O Blocked fire escape. 0 26 0004 402 O Blocked fire escape. 0 27 0005 501 M Flammable storage missing ceiling. 0 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. 4 END OF SREF INSPECTION REPORT	19	0002	202	0	All open sockets	in Pre-K Rooms need covers on open sockets.	2						
22 0003 309 M Repair gutter downspout outside of #03-309.	20	0003	304	M	Adjustment needed to slamming door.						Structural Department		
23 0003 309 M Verify if hot water heater is operating, if not remove or replace. 24 0004 000 O Pressure wash all exterior side of doors. Door have mildew building up on them. 25 0004 402 O Blocked fire escape. 26 0004 402 O Temporary extension cords are not allowed. All plugs shall be plugged into a dedicated permanent power source. (orange) 27 0005 501 M Flammable storage missing ceiling. 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. END OF SREF INSPECTION REPORT	21	0003	306	0	Keep Emergency	Escape Window clear at all times.	1						
24 0004 000 O Pressure wash all exterior side of doors. Door have mildew building up on them. 25 0004 402 O Blocked fire escape. 26 0004 402 O Temporary extension cords are not allowed. All plugs shall be plugged into a dedicated permanent power source. (orange) 27 0005 501 M Flammable storage missing ceiling. 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. END OF SREF INSPECTION REPORT	22	0003	309	M	Repair gutter downspout outside of #03-309.						Structural Department		
25 0004 402 O Blocked fire escape. 26 0004 402 O Temporary extension cords are not allowed. All plugs shall be plugged into a dedicated permanent power source. (orange) 27 0005 501 M Flammable storage missing ceiling. 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. END OF SREF INSPECTION REPORT	23	0003	309	М	Verify if hot water heater is operating, if not remove or replace.						Plumbing Department		
26 0004 402 O Temporary extension cords are not allowed. All plugs shall be plugged into a dedicated permanent 0 27 0005 501 M Flammable storage missing ceiling. 0 Structural 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. 4 END OF SREF INSPECTION REPORT	24	0004	000	0	Pressure wash all exterior side of doors. Door have mildew building up on them.								
26 0004 402 0 power source. (orange) 27 0005 501 M Flammable storage missing ceiling. 28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. END OF SREF INSPECTION REPORT Structural	25	0004	402	0	Blocked fire esca	аре.	0						
28 0006 000 O Remove wooden/plastic chocks from corridor/rated doors. END OF SREF INSPECTION REPORT	26	0004	402	0			0						
END OF SREF INSPECTION REPORT	27	0005	501	M	Flammable stora	ge missing ceiling.	0				Structural Department		
	28	0006	000	0	Remove wooder	/plastic chocks from corridor/rated doors.	4						
						END OF SREF INSPECTION REPORT							
A re-inspection of the identified deficiencies will be preformed approximately days subsequent of inspection date. Re-Inspection Date:													
The principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school.	The prin	cipal shall h	old at least o	one (1) fire	drill during each mo	nth, with an additional drill being held within the first 30 days of school.	N	Ю					

Printed: 2/2/2021 - 1:41 PM

2/2/2021		Apalachee Elementary School			ry School		
INSPECTION DATE		SCHOOL/ FACILITY/CAMPUS					
INSPECTOR: Juan E. Williams	The second secon	850 Trojan Trail					
	LEON COUNTY SCHOOLS	Tallahassee, Florida 32311					
INSPECTOR SIGNATURE SIGNATURE DATE	FACITLITIES & CONSTRUCTION DEPARTMENT						
TYPE OF INSPECTION	3420 W. THARPE ST., TALLAHASSEE, FL 32303	F.I.S.H. NUMBER					
FIRE CASUALTY SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2020-2021	037-0441-044					
Item # Building Number Room Number C Deficier	cy Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	
Reviewed Emergency Generator Report. YES NO Emergency Generator Report up-to-date as of SREF Inspection. YES NO							
Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies:							

Leon County

School/Site Administrator