

To:

Ms. Gillian Gregory, Assistant Superintendent of Academics Services

Mr. Alvin "Butch" Watkins, Director of Maintenance Mr. Danny Allbritton, Director of Construction

From:

Mr. Juan E. Williams, Coordinator, Fire & Safety

Through:

Mr. LaRoderick E. McQueen, Building Official

Date:

November 30, 2018

Subject:

SREF Inspection for Aquilina Howell Building

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Work orders should be generated addressing each deficient item. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff or through work order submission to the Maintenance Department. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Building Code Enforcement Office. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Deanetra Grissom at grissomd@leonschools.net or fax the report to (850) 617-1790, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board and your Divisional Director.

**Additionally a separate inspection report has been provided for each portable at your site. In accordance with SREF Chapter 4
Section 4.4 (2)**

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Juan E. Williams at the Building Code Enforcement Office at (850) 617-1814. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc:

Mr. Alan Cox, Assistant Superintendent of School Management (with attachments)

Mr. Carl Green, Coordinator of School Plant, Safety, and Sanitation (with attachments)

"Our Hands Keep Their Minds Working"

Code Enforcement and Compliance Department & Small Business Enterprise- 3420 West Tharpe Street - Suite 200 - Tallahassee, Florida 32303-1138 (850) 617-1838 · Fax (850) 617-1790

www.lcscodeenforcement@leoncountyschools.net

"The Leon County School District does not discriminate against any person on the basis of sex (including transgender status, gender nonconforming and gender identity), race, age, color, ethnicity, national origin, religion, pregnancy, marital status, disability, sexual orientation, or genetic information."

Prepared By: Elishia Golden

INSPECTOR: Juan E.	R: Juar	E Wi							ı,
			Williams						SCHOOL/FACILITY/CAMPUS
					LEON COUNTY SCHOOLS		(,,		3955 West Pensacola Street Tallahassee, FL 32304
INSPECTOR SIGNATURE	SIGNATU	П	IGNATO	SIGNATURE DATE	FACITLITIES & CONSTRUCTION DEPARTMENT				
	TYPE C	TYPE OF INSPECTION	ECTION		3420 W. THARPE ST., TALLAHASSEE, FL 32303				F.I.S.H. NUMBER
₩ FR	-	CASUALTY		SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018				037-9284-928
Item Building # Number	ing Room ber Number		00₹	Deficienc	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	T of o	for Re- on Inspection r Correction Date
1 0000	000	ŏ	0	lonthly inspection	Monthly inspection of fire extinguishers need to be done, tag initialed, and report sent to District.	2		_	
2 0000	000	ŏ	0	heck and verify the	Check and verify that all emergency lights and exit lights have battery backup.	0		\rightarrow	
3 0000	000		0	heck all exit light	Check all exit lights to make sure they have battery backup.	0		-	
4 0000	000		O U	Usage of space hea heaters.	Usage of space heater shall comply with Leon County School's Policy regarding the use of space heaters.	1		\rightarrow	
5 0001	000		M	utside at satellite	Outside at satellite dish, PVC Junction Box and pipe are damaged.	р		\rightarrow	
6 0001	000		M	mergency light in	Emergency light in main lobby is inoperable.	0		-	
7 0001	000	-	M	ence on west side	Fence on west side of building is damaged in multiple locations.	1			
8 0001	000	-	M	re alarm report de	Fire alarm report does not match tag.	1			
9 0001	102	\vdash	ME	kit light outside o	Exit light outside of Rm # 102 has no battery backup.	0			
10 0001	102	-	0	Emergency light out in lobby	ıt in lobby.	0			
11 0001	102		0	kit light in hallwa	Exit light in hallway outside Rm # 01-102 has no battery.	0			
12 0001	1 102C		0	Ceiling tile needs to be replaced	be replaced.	0		_	
13 0001	1 102C		O R	Replace damaged ceiling tile	eiling tile.	0		\rightarrow	

26 00	25 00	24 00	23 0	22 0	21 0	20 0	19 0	18 0	17 0	16 0	15 0	14 0	item Bu	*		INSPECTOR SIGNATURE		INSPECTOR: Juan E. Williams	INSPECTION DATE	
0001 1	0001	0001	0001	0001	0001	0001	0001	0001	1000	0001	0001	0001	Building Number P	FRE	잼	R SIGNA		TOR: Ju	ION DAT	
122A	111A	111	111	109	106	104	103	103	103	103	103	103	Room	CASUALTY	TYPE OF INSPECTION	TURE		ian E. V	E	11/30/2018
0	Z	Z	0	Z	Z	Z	0	Z	Z	0	Z	X	ი 0 ≥] 7	SPECTIC	SIGNAT		Villiams	$\ $	2018
Ceiling tiles need to	Sprinkler head missing from room.	seal penetrations at	as powered equip	Emergency light m	Emergency light m	Exit door is slamming close	Surge protectors m	Handicap buttons inoperable	Exit light out in En	Surge protectors m	Handicap button out on door	Exit light out in En	Deficienc	SANITATION	×	SIGNATURE DATE				
Ceiling tiles need to be re-installed around computer cables (going through ceiling tiles).	sing from room.	Seal penetrations at wall at sprinkler riser.	Gas powered equipment needs to be stored in the proper location.	Emergency light missing/not identified in Gang bathroom.	Emergency light missing/not identified in Gang bathroom.	ing close.	Surge protectors must plug into a dedicated outlet (no piggy backing).	inoperable.	Exit light out in Emergency Mode (outside of Rm # 103).	Surge protectors must plug into a dedicated outlet (no piggy backing).	ut on door.	Exit light out in Emergency Mode (outside).	Deficiency Description and Corrective Action Required	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018	3420 W. THARPE ST., TALLAHASSEE, FL 32303	FACITLITIES & CONSTRUCTION DEPARTMENT	LEON COUNTY SCHOOLS			
1	1	0	2	1	1	2	0	0	0	0	0	0	# of Times Deficiency Previously Cited							
													Schedule for Correction No Later Than				t a			
													Re- Inspection Correction	037	F.I.S		955 Wes Tallaha		SCHOOL	Amilina
													Site-Wide Building- Wide Exterior Campus or	037-9284-928	F.I.S.H. NUMBER		3955 West Pensacola Street Tallahassee, FL 32304		SCHOOL/ FACILITY/CAMPILS	Hawall R
	EH&S	Structural Department		Electrical Department	Electrical Department	Structural Department		Electrical Department	Electrical Department		Electrical Department	Electrical Department	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	∞	λi λi		la Street 32304		AMPIIS	mildian

0
0
1
0
0
0
0
1
Egress Door from stage needs to have path cleared to Right of Way (also from Exit at stairs leading to same area).
2
2
of Times Schedule for Deficiency Correction Previously No Later Cited Than
3955 Tal

		11/30	11/30/2018							Page 4 of 4
INSPE	INSPECTION DATE	ATE	0107/					Aquilina I	Aquilina Howell Building	ilding
INSPE	INSPECTOR: Juan E. Williams	Juan E.	William	IS				SCHOOL/F	SCHOOL/ FACILITY/CAMPUS	MPUS
					LEON COUNTY SCHOOLS		w	3955 West	55 West Pensacola Street	a Street
INSPEC	INSPECTOR SIGNATURE	IATURE	SIGNA	SIGNATURE DATE	FACITUTIES & CONSTRUCTION DEPARTMENT				j	-
		TYPE OF INSPECTION	SPECTI	ON N	3420 W. THARPE ST., TALLAHASSEE, FL 32303			F.I.S.	F.I.S.H. NUMBER	
*	FIRE	CASUALTY	1	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018			037.	037-9284-928	
# Item	Building	Room	00≤	Deficienc	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
40	0001	208	Z	Emergency light m	Emergency light missing/not identified in Gang bathroom.	1				Electrical Department
41	0001	800	Z	Exit light outside o	Exit light outside of Rm # 800 has no battery backup.	0				Electrical Department
42	0001	800	Z	Exit light out in En	Exit light out in Emergency Mode outside of elevator - Expiration date is 08/01/2018.	0				Electrical Department
43	0001	800	0	Elevator inspection	Elevator inspections tag has expired. 08/01/2018.	0				
					END OF SREF INSPECTION REPORT					
re-inspe	ction of the	identified d	leficiencie	s will be preformed appr	A re-inspection of the identified deficiencies will be preformed approximately 60-90 days subsequent of inspection date. Re-Inspection Date:					
he princ	pal shall ho	ld at least or	ne (1) fire	drill during each month	The principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school.	NO				
ignature	of facility	administr	ator attes	ting to Fire Evacuation	Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies:		Date of Acknowledgement:	edgement:		
X	0	9	3	March						
Leon (Schoo	Leon County School/Site Administrator	lmin istra	yor	1						

Printed: 12/4/2018 - 2:37 PM