

To:

Ms. Marsha Glover-Sanders, Principal, Astoria Park Elementary School

Ms. Jean Pepe, Assistant Principal, Astoria Park Elementary School

Mr. Alvin "Butch" Watkins, Director of Maintenance

Mr. Danny Allbritton, Director of Construction

From:

Mr. Lorenzo Hillman, Coordinator, Fire & Safety

Through:

Mr. LaRoderick E. McQueen, Building Official

Date:

March 23, 2018

Subject:

SREF Inspection for Astoria Park Elementary School

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Please
 do not submit work orders for the deficiency line items in the M (Maintenance) column. Upon completion of all work
 orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction and Capital Outlay) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement and Compliance Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Elishia Golden at goldene2@leonschools.net or fax the report to (850) 617-1790, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board.

Additionally a separate inspection report has been provided for each portable at your site, in accordance with SREF Chapter 4 Section 4.4 (2)

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Lorenzo Hillman at the Code Enforcement and Compliance Department at (850) 617-1814 or email at hillmanl@leonschools.net. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc:

Ms. Susan Kraul, Director of Elementary Schools (with attachments)

Dr. Alan Cox, LCS Assistant Superintendent of School Management (with attachments)

Mr. Carl Green, Coordinator of School Plant, Safety, and Sanitation (with attachments)

"Our Hands Keep Their Minds Working"

Code Enforcement and Compliance Department & Small Business Enterprise- 3420 West Tharpe Street - Suite 200 - Tallahassee, Florida 32303-1138 (850) 617-1838 · Fax (850) 617-1790

www.lcscodeenforcement@leoncountyschools.net

"The Leon County School District does not discriminate against any person on the basis of sex (including transgender status, gender nonconforming and gender identity), race, age, color, ethnicity, national origin, religion, pregnancy, marital status, disability, sexual orientation, or genetic information."

Printed:	31	30	29	28	27	26	25	24	23	22	21		ltem	\$	\$	INSPE		T	NSP	INSPL
Printed: 3/26/2018	0001	0001	0001	0001	0001	0001	0001	0001	0001	0001	0001		Building	TINE		INSPECTOR SIGNATURE			INSPECTOR: I ORENZO HII I MANI	2 INSPECTION DATE
- 7.52 AM	104 A	104	102 K	102 F	102	102	101	000	000	000	000		Room	CASUALIY	S CONTROL ON	NATURE			OREN	2/13
	Z	0	0	0	Z	0	C	0	Ω	Z	0	-	00≤		3	SIGN			7	2/13/2018
	HVAC Unit, Mounted on Wa	Keep Combustible Materials	Remove Storage From Mechanical Room	Keep Combustible Materials	Smoke Detector is Hanging Down Out of Ceiling.	Remove Combustible Materi	Egress Door, Going From Ro Compliant Hardware.	Curtains on Windows and B Standards.	(ADA)/Egress Compliant Ha	Privacy Dividers Missing at	Certificate of Occupancy Issuance.	Parts of Building #1 Wars D	Deficiency D	SANITATION	CA	SIGNATURE DATE				
	HVAC Unit, Mounted on Walls, is Damaged; Needs to Be Repaired or Replaced.	Kecp Combustible Materials 3' Clear From the Perimeter of the Hot Water Heater.	anical Room.	Keep Combustible Materials 3' Clear From the Perimeter of Electrical Panels.	Down Out of Ceiling.	Remove Combustible Materials Hanging From Ceiling in Classroom.	Egress Door, Going From Recently Renovated Office Into Corridor, Does Not Have (ADA)/Egress Compliant Hardware.	Windows and Bookcases Do Not Have Labels Designating Materials Meets (NFPA)	(ADA)/Egress Compliant Hardware Missing From Required Doors.	Privacy Dividers Missing at Urinals in Boys Gang Bathroom.	Certificate of Occupancy Issuance.		Deficiency Description and Corrective Action Required	FISCAL YEAR: 2017-2018	3420 W. THARPE ST., TALLAHASSEE, FL 32303	FACITLITIES & CONSTRUCTION DEPARTMENT	S100HDS ALUNCO MOST		The state of the s	
	0	5	1	4	0	0	0	-	0	0	0	C a	# of Times Deficiency Previously				Tallahas	2465 At		
												Than	Schedule for Correction				Tallahassee, Florida 32303	Atlas Road		4
												Date	Re- Inspection	037	F.I.S		da 32303		SCHOOL/	storia P
							U	Building- Wide	Building- Wide	Building- Wide	Building- Wide	Campus or Portable	Site-Wide Building- Wide Exterior	037-0401-040	F.I.S.H. NUMBER				SCHOOL/ FACILITY/CAMPUS	Astoria Park Elementary
•	HVAC Department				Systems Department		Capital Outlay		Capital Outlay	Structural Department		MAINTENANCE ASSIGNMENT	REMARKS CODE REFERENCE	.0	Xi				AMPUS	mentary

Printed: 3/26/2018 - 7:52 AM

42	14	40	39	38	37	36	35	34	33	32	ltem	×		INSPE		T	MODE	in a second
0001	0001	0001	0001	0001	0001	0001	0001	0001	0001	0001	Building	FIRE	בו	INSPECTOR SIGNATURE		150,087	INSPECTOR DATE	
108 L	108 G	108 F	108 F	108	108	108	107	106	104 A	104 A	Room	CASUALTY	TYPE OF INSPECTION	NATURE		THE TOTAL TORENZO HILLMAN	AIE	2/13
Z	0	Z	0	Z	Z	Z	Z	Z	0	0	003	MALT N	USPECT	SIGN		0 11		2/13/2018
HVAC Producing Excessive Amounts of Dust Collecting on Food Equipment and Air Vents.	Means of Egress Shall Be Maintained at All Times.	Install Free Wire Properly (Going Through Ducts in Rated Wall).	Remove Storage in Mechanical Room.	Adjust Water Fountain, So Water is Contained to the Catch Basin.	Sprinkler Head is Hanging Out of the Ceiling In Cafeteria.	Cafeteria Entry Doors, By Serving Line, are Slamming Closed.	Exit Light Missing From Bathroom.	Carpet is Loose in Corridor, Outside 01-106.	Remove Storage in Electrical Room.	Keep Combustible Materials 3' Clear From the Perimeter of Electrical Panels.	Deficiency Description and Corrective Action Required	SANITATION		SIGNATURE DATE FACITLITIES & CONSTRUCTION DEPARTMENT	STOOMS ALURO UGS	LMAN		
2	ω	1	4	0	0	0	0	0	ω	5	# of Times Deficiency Previously Cited			T GILLIAN	Tallahaa	2465 Atl		
											Schedule for Correction No Later Than			i ananassee, Fiorida 52505	non Eloui	Atlas Road		
											Re- Inspection Correction Date	037	F.I.S	ua 32303	5 22202		SCHOOL	storia P
											Site-Wide Building- Wide Exterior Campus or Portable	037-0401-040	F.I.S.H. NUMBER				SCHOOL/ FACILITY/CAMPUS	Astoria Park Elementary
HVAC Department		HVAC Department		Plumbing Department	EH&S Department	Structural Department	Electrical Department	Carpet Shop			REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	0	Ä				AMPUS	mentary

2/13/2018

	TOTAL ON THE						A	storia Po	Astoria Park Elementary	PONTAYI
INS I	INSPECTOR: LOR	INSPECTOR: LORENZO HII I MAN	OH!	MAN				SCHOOL/F	SCHOOL/ FACILITY/CAMPUS	AMPUS
					S100kps Aluno 11027	2465 Atl	2465 Atlas Road			
INSPE	INSPECTOR SIGNATURE	NATURE	SIGN	SIGNATURE DATE	FACITUTIES & CONSTRUCTION DEPARTMENT					
	5	TYPE OF INSPECTION	SPECT	ON	3420 W. THARPE ST., TALLAHASSEE, FL 32303			מות	RIGH NIMBED	
×	FIRE	CASUALTY	4	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018			037.	037-0401-040	0
item #	Building Number	Room Number	00₹	Deficie	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
43	0001	108 L	0	Extension Cords M	Extension Cords Must Plug into Dedicated Outlet.	-				
4	0001	110	0	Remove Storage From Bathroom	om Bathroom.					
45	0001	110	0	Remove Storage Wi	Remove Storage Within 18" of Sprinkler Head.	-				
46	0001	111	Z	Remove Chevrons F Access From Pod.	Remove Chevrons From Exit Light Showing Direction of Egress From Classroom Into Corridor Access From Pod.	0				Electrical Department
47	0001	112	Z	Remove Chevrons F Access From Pod.	Remove Chevrons From Exit Light Showing Direction of Egress From Classroom Into Corridor Access From Pod.	0				Electrical Department
48	0001	112	Z	In Main Corridor, Remo Main Corridor Intersect.	In Main Corridor, Remove Chevron From Exit Light Showing Direction of Egress Where Pod and Main Corridor Intersect.	0				Electrical Department
49	0001	113	Z	Remove Chevron Sh	Remove Chevron Showing Direction of Egress From Pod Area Into Corridor.	0				Electrical Department
50	0001	113 A	0	Remove Festive Ligi	Remove Festive Lights Hanging In Classroom.	0				
51	0001	113 J	0	Remove Storage in Mechanical Room	Mechanical Room.	ယ				
52	0001	114 G	0	Remove Damaged Soap Dispenser	oap Dispenser.	0				
53	0001	114 H	0	Replace and Date W	Replace and Date Water Stained Ceiling Tiles.	-				

7									Page 6 of L
NSP	INSPECTION DATE	2/13/2018	2018				Astoria Park Elementary	ark Elen	
INSP	INSPECTOR: LORENZO HILLMAN	LORENZ	70 HIL	LMAN		±	SCHOOL/	SCHOOL/ FACILITY/CAMPUS	AMPUS
				ALUMNIA MOST	2403 A	Atlas Koad			
				Significant mean	Tallaha	Tallahassee, Florida 32303	da 32303		
INSPE	INSPECTOR SIGNATURE	NATURE	SIGN	SIGNATURE DATE FACITLITIES & CONSTRUCTION DEPARTMENT					
\$		TYPE OF INSPECTION	SPECT				F.L.S.	F.I.S.H. NUMBER	~
*	FIRE	CASUALTY X	E S	SANITATION COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018			037	037-0401-040	
Item	Building	Room	∩ 0 ≤	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	ν ς ς	Re- Inspection Correction	Site-Wide Building- Wide Exterior	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
								or Portable	
40	1000	113	C	Remove Combustibles From the Ceiling.	_υ				
55	0001	115	0	Remove All After-Market Festive Lighting From Classrooms.	2				
56	1000	115 B	0	Surge Protectors Must Plug into a Dedicated Outlet, No Piggybacking.	1				
57	0001	115 D	0	Remove All After-Market Festive Lighting From Classrooms.	_{دي}				
58	0001	115 G	Z	Light Switch Cover Missing.	0				Electrical Department
59	0001	116	Z	Sprinkler Head Is Hanging Out of Ceiling.	0				HVAC Department
60	0001	166 A	0	Remove Combustible Materials Hanging From Ceiling.	0				
61	0001	116 G	0	Remove Storage From Mechanical Room.	2				
62	0001	116 G	0	Remove Cords Going Under Door (Surge Protector).	1				
53	1000	116 G	0	Surge Protectors Must Plug into a Dedicated Outlet, No Piggybacking.	<u></u>				
64	0001	116 Н	0	Light Fixture Missing Cover.	0				

74		72	71	70	69	68	67	66	S		Item	*		INSPEC			INSPE	No of the last of
0002	0002	0002	0002	0002	0001	0001	0001	0001	0001	Number	Building	FIRE		INSPECTOR SIGNATURE			INSPECTOR: I OF	
210	209	000	000	000	801	801	801	116 J	116 J	Number	Room	CASUALTY	TYPE OF INSPECTION	VATURE			INSPECTOR DATE	2/13/
0	0	Z	С	0	Z	Z	0	×	Z	0.0	S	WITH SERVICE S	SPECT	SIGN			70	2/13/2018
Replace and Date Water Stained Ceiling Tiles	Keep Combustible Materials 2' Clear Perimeter of the Hot Water Heater.	Outside Building #2, Wooden Gazebo is Rott Falling In.	Missing (ADA) Handles on Doors. Install (A	Remove All After-Market Festive Lighting From Classrooms	Outside 01-801, GFCI Cover is Damaged.	Handle on Gas Valve is Damaged/Missing.	Remove Storage From Utility Room.	(ADA)/(F.I.S.H.) Sign Missing From Bathroom	Sprinkler Head is Hanging Out of the Ceiling.	Deficiency Description		SANITATION		REDATE	<u> </u>			
,s	ter of the Hot Water Heater.	Outside Building #2, Wooden Gazebo is Rotted With Splintered Wood, Exposed Nails, and Roof is Falling In.	Missing (ADA) Handles on Doors. Install (ADA) Compliant Door Handles on All Required Doors.	rom Classrooms.				oom.	άσ	Deficiency Description and Corrective Action Required		COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018	3420 W. THARPE ST., TALLAHASSEE, FL 32303	FACITLITIES & CONSTRUCTION DEPARTMENT	LEON COUNTY SCHOOLS		And the state of t	
<u> </u>		0	2	2	0	0	ω	0	-	Deficiency Previously Cited	# of Times				Tallahas	2465 At		
										Correction No Later Than	Schedule				Tallahassee, Florida 32303	Atlas Road		
										Inspection Correction Date	Ζ Ρ	037	FLS		da 32303		SCHOOL/	storia P
		Exterior Campus	Building- Wide	Building- Wide							Site-Wide	037-0401-040	F.I.S.H. NUMBER				SCHOOL/ FACILITY/CAMPUS	Astoria Park Flomontary
		Structural Department	SREF 5(13)(a). Structural Department Capital Outlay		Electrical Department	HVAC Department		Sign Shop	EH&S Department	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT		0	ä				AMPUS	rage / of 1.

97 0003 317 M Exterior Door Missing Closer.	96 0003 317 O Room is Required to Be Swept and Maintained Regularly.	95 0003 316 M Boiler Certification is Expired.	94 0003 316 O Cut Weeds Back From HVAC Equipment.	93 0003 316 M Paint on Door is Peeling and Chipped.	92 0003 316 M Fire Sprinkler Controls Sign Needs to Be Re-Attached.	91 0003 316 M Remove Old Rusted Road Signs.	90 0003 316 M Exterior Door Missing Closer.	89 0003 315 M Exterior Door Missing Closer.	88 0003 310 O By 03-310, Replace and Date Water Stained Ceiling Tiles.	87 0003 304 O Remove Combustibles Attached to Light Fixtures.	86 0003 302 A O Only Non-Combustible Shelving Can Be Used in the Kiln Room.	Item Building Room Windson Number C Deficiency Description and Corrective Action Required	FIRE CASUALTY SANITATION COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018	TYPE OF INSPECTION	1	"WOTECTOK: LORENZO HILLMAN	INSPECTION DATE	2/13/2010
	Maintained Regularly.		pment.	ed.	to Be Re-Attached.				r Stained Ceiling Tiles.	Light Fixtures.	an Be Used in the Kiln Room.	ption and Corrective Action Required	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018	FACITLITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303	ALUMOS		The state of the s	
1	သ	1	0	0	0	0	2	1	0	0	0	# of Times Deficiency Previously Cited			Tallaha	2465 A		
												Schedule for Correction No Later			Tallahassee, Florida 32303	Atlas Road		_
												Re- Inspection Correction Date	037	F.I.S	da 32303		SCHOOL/	Astoria Park Elementary
												Site-Wide Building- Wide Exterior Campus or Portable	037-0401-040	F.I.S.H. NUMBER			SCHOOL/ FACILITY/CAMPUS	ark Flor
Structural Department		HVAC Department		Paint Shop	Sign Shop	Sign Shop	Structural Department	Structural Department				REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	0	20			AMPUS	MONTAN

106 0089 107 0089 108 0089 109 0089					0089	_	103 0005	102 0005	101 0005	100 0005	99 0004	98 0003	Item Building # Number	FIRE	_	INSPECTOR SIGNATURE			INSPECTOR: LORENZO HILL MAN	110000000000000000000000000000000000000
0089 134	134	134	+	+	-		501	501	501	501	000	317	er Number	CAS		TYPE OF			RIORE	2/]
0	Z	0	-	+	+	+	0	Z	0	Z	X	Z X	003	CASUALTY	THE OF INSPECTION	2	1		H OZN	2/13/2018
Surge Protectors Mus-	Emergency Light Inoperable	Remove Combustibles From the Ceiling	Remove Weeds Grow	Wooden Slats on Rai	Cover Exposed Pipe Under Ramp	Ramp Leading Up to	Gas Powered Equipm	Fire Sprinkler Contro	Accessibility to Fire	Exterior Door Missing Closer	Exterior Door Missing Closer	Fire Extinguisher is I	21	SANITATION	I CN	SIGNATURE DATE			MAN	
Surge Protectors Must Plug into a Dedicated Outlet, No Piggybacking.	perable.	ss From the Ceiling.	Remove Weeds Growing in Skirting Around Portable.	Wooden Slats on Railing Missing or Damaged.	Under Ramp.	Ramp Leading Up to Portable is Loose and Leaning Needs to Be Repaired or Replaced.	Gas Powered Equipment is Required to Be Stored in a Properly Ventilated Storage Location.	Fire Sprinkler Controls Sign Needs to Be Re-Attached.	Accessibility to Fire Sprinkler Drain Shall Be Maintained at All Times for Testing and Inspections.	ng Closer.	ng Closer.	Fire Extinguisher is Missing From Electrical Room.	Deficiency Description and Corrective Action Required	FISCAL YEAR: 2017-2018	3420 W. THARPE ST., TALLAHASSEE, FL 32303	FACITLITIES & CONSTRUCTION DEPARTMENT	LEON COUNTY SCHOOLS			
-	1		0	1	-	H	5	0	6	1	1	0	# of Times Deficiency Previously Cited				Tallahas	2465 Atl		
													Schedule for Correction No Later Than				Tallahassee, Florida 32303	Atlas Road		
													Re- Inspection Correction Date	037	F.L.S		da 32303		SCHOOL/	storia P
Portable	Portable	Portable	Portable	Portable	Portable	Portable							Site-Wide Building- Wide Exterior Campus or Portable	037-0401-040	F.I.S.H. NUMBER				SCHOOL/ FACILITY/CAMPUS	Astoria Park Elementary
	Electrical Department			Structural Department	Structural Department	Structural Department		Sign Shop		Structural Department	Structural Department	EH&S Department	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	Ö	Z				AMPUS	Page 10 of 12

	121	120	119	118	117	116	115	114	113	112	E	Item	*	\$	INSPE		TWO!	INSPE	
	0099	0089	0089	0089	0089	0089	0089	0089	0089	0089	0089	Building	FIRE	FI =	INSPECTOR SIGNATURE		INSTECTOR: LORENZO HILLMAN	INSPECTION DATE	
	155 B	155	155	155	155	155	134 A	134	134	134	134	Room	CASUALTY	TYPE OF INSPECTION	NATURE		LOKEN	ATE	2/13,
	Z	Z	K	0	Z	Z	Z	Z	Z	Z	Z	00≥	LTY 💥	SPECT	SIGN		O HILL		2/13/2018
	Handrails on Wood	Modify Threshold t	Main Entry/Exit Do	Remove Weeds Gro	Wooden Ramp, at (Requirements.	Wooden Ramp, Go	Replace and Date V	Handrails Do Not (Handrails on Wood	Reconfigure or Adj Requirements.	Modify Both Three	Deficie	SANITATION	ON N	SIGNATURE DATE		MAN		
	Handrails on Wooden Ramp Leading to Portable are Not (ADA) Compliant.	Modify Threshold to Comply with (ADA)/Egress Requirements.	Main Entry/Exit Door Will Not Close and Latch Properly.	Remove Weeds Growing in Skirting and Through Deck of Wooden Ramp.	Wooden Ramp, at Concrete Transition, Is Damaged and Does Not Meet (ADA)/Egress Requirements.	Wooden Ramp, Going in Into Portable, Is Rotted and Damaged in Multiple Locations.	Replace and Date Water Stained Ceiling Tiles With Light Fixture.	Handrails Do Not Comply with (ADA)/Egress Requirements.	Handrails on Wooden Ramp Leading to Portable are Not (ADA) Compliant.	Reconfigure or Adjust Wooden Ramp Leading to Portable to Meet (ADA) Accessibility Code Requirements.	Modify Both Thresholds to Comply with Egress Requirements.	Deficiency Description and Corrective Action Required	FISCAL YEAR: 2017-2018	3420 W. THARPE ST., TALLAHASSEE, FL 32303	FACITLITIES & CONSTRUCTION DEPARTMENT	LEON COUNTY SCHOOLS			
,	J.	0	0	0	0	0	0	0	3	2	1	# of Times Deficiency Previously Cited				Tallahas	2465 Atlas		
												Schedule for Correction No Later Than				Tallahassee, Florida 32303	as Road		
												Re- Inspection Correction Date	037	F.I.S		da 32303		SCHOOL/	, tou.
1 Oranoro	Portable	Portable	Portable	Portable	Portable	Portable	Portable	Portable	Portable	Portable	Portable	Site-Wide Building- Wide Exterior Campus or Portable	037-0401-040	F.I.S.H. NUMBER				SCHOOL FACILITY/CAMPUS	1- 61-
Sunctural Department	Charles Dansel	Structural Department	Structural Department	Structural Department	Structural Department	Structural Department	Electrical Department	Structural Department	Structural Department	Structural Department	Structural Department	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	0	25				amplis	rage 11 of 12

ŀ										Page 12 of 12
		2/13/2018	2018					fauia D	l El	96
INSPI	INSPECTION DATE	ATE					/10	n T milos	Asior in Fark Elementary	entary
120	INSPECTOR: LORENZO HILLMAN	LOREN	OHIL	LMAN		2465 Atl	Atlas Road		COLLOCK LACIEL LACHINE OS	AMPOS
					STOOMS ALUNDS LIGHT	Tallahass	Tallahassee, Florida 32303	32303		
NSPE	INSPECTOR SIGNATURE	NATURE	SIGN	SIGNATURE DATE	FACITLITIES & CONSTRUCTION DEPARTMENT					
}	בות	TYPE OF INSPECTION	ISPEC1	JION	3420 W. THARPE ST., TALLAHASSEE, FL 32303			F.I.S.I	F.I.S.H. NUMBER	
×	FIRE	CASUALTY	TT WE	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2017-2018			037-	037-0401-040	
Item #	Building	Room	003	<u>Deficie</u>	Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
122	0099	428	Z	Handrails on Wood	Handrails on Wooden Ramp Leading to Portable are Not (ADA) Compliant.	w			Portable	Structural Department
123	0099	428	Z	Repair Obvious Wa	Repair Obvious Water Damage in Ceiling in and Around Bathroom.	1			Portable	Structural Department
124	0099	428	×	Floor, in Both Bathı	Floor, in Both Bathrooms, Is Loose and Sagging.	0			Portable	Carpet Shop
125	0099	428	×	Emergency Light Inoperable	perable.	0			Portable	Electrical Department
126	0099	428 B	Z	Lock Feature on Door is Inoperable	or is Inoperable.	0			Portable	Locksmith Department
					END OF SREF INSPECTION REPORT					
re-ins	pection of th	e identified	deficienci	ies will be preformed appro	re-inspection of the identified deficiencies will be preformed approximately 60-90 days subsequent of inspection date. Re-Inspection Date:					
he prin	cipal shall h	old at least o	ne (1) fir	re drill during each month, v	he principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school.	NO				
ignatu	re of facilit	y administr	ator atte	esting to Fire Evacuation	ignature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies:		Date of Acknowledgement:	edgement:		
Scho X	X Leon County School/Sile Administrator	dministra	ator a	iden 3	29/18					