INSPECTION DATE

TYPE INSPECTION

FIRE SAFETY CASUALTY

SIGNATURE DATE

SANITATION

LEON COUNTY SCHOOLS MAINTENANCE DEPARTMENT "Our hands keep their minds working"

Administration SCHOOL/FACILITY/CAMPUS 037-9001-900 F.I.S.H./F.I.C.E. NUMBER

2757 West Pensacola St., Tallahassee **ADDRESS**


COMPREHENSIVE SAFETY INSPECTION - STANDARD FISCAL YEAR 2012-13

Dept	Work Order	Building Number	Room Number	M 0 C	Estimated Cost	Deficiency Description and Corrective Action Required	Number of Times Def. Cited Before	Sched for Correction NLT	Completion Date	Line Item #
	0	0000	000	0	0	Sitewide-Monthly inspection of fire extinguishers needs to be done and	1	Immed.		1
						card initialed.				
_	О	0000	000	0	0	Main fire alarm panel is showing troubles. (Fire alarm site wide is being	0	Immed.		2
						redone)				
	o	0001	000	0	0	Building wide-Space heaters that do not comply with LCSD safety	0	Immed.		3
						features need to be removed.				
	0	0001	006	0	0	Extension cords cannot be used as permanent power.	1	Immed.	-	4
	О	0001	006	0	0	Surge protectors are piggy backed. Surge protectors not plugged into	1	Immed.		5
						a dedicated wall outlet.				
	0	0004	000	0	0	Building wide-Space heaters that do not comply with LCSB safety policy	0	Immed.		6
						need to be removed.				
	0	0089	009	0	0	This portable is unoccupied at this time. It is getting ready to be re-	0	Immed.		7
						located.				
	0	0099	010	0	0	This portable is unoccupied at this time. It getting ready to be re-	0	Immed.		8
						located.				
	0	0099	151 Y	0	0	No access.	1			9
ELE	254743	0000	000	М	0	Main lobby exit light is inoperable, normal mode.	0	07/26/13	-	10
ELE	254743	0001	002 C	М	0	Remove exit light above 01-002C.	0	07/26/13		11
ELE	254743	0001	002 E	М	0	Above 01-002E emergency light is inoperable.	0	07/26/13		12

Printed: 7/15/2013 8:41:04 AM

The principal shall hold at least one (1) emergency drill during each month, with an additional drill being held within the first 30 days of school.

Signature of facility administrator attesting to Emergency Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies



LEON COUNTY SCHOOLS MAINTENANCE DEPARTMENT "Our hands keep their minds working"

Administration SCHOOL/FACILITY/CAMPUS 037-9001-900 F.I.S.H./F.I.C.E. NUMBER

F.I.S.H./F.I.C.E. NUM

ADDRESS

2757 West Pensacola St., Tallahassee

INSPECTOR SIGNATURE

SIGNATURE DATE

COMPREHENSIVE SAFETY INSPECTION - STANDARD FISCAL YEAR 2012-13

TYPE INSPECTION

FIRE SAFETY CASUALTY

ALTY SANITATION

Dept	Work Order	Building Number	Room Number	M O C	Estimated Cost	Deficiency Description and Corrective Action Required	Number of Times Def. Cited Before	Sched for Correction NLT	Completion Date	Line Item #
ELE	254743	0001	003 A	М	0	Emergency light is inoperable.	0	07/26/13		13
ELE	254743	0001	008	М	0	Junction box missing cover with exposed wires.	1	07/26/13		14
ELE	254744	0001	026	М	0	Side entry exit light is inoperable.	0	07/26/13	_	15
ELE	254744	0002	011	0	0	No access.	0	Immed.		16
ELE	254744	0004	012	М	0	Emergency light outside of 04-012 is inoperable.	0	07/26/13		17
ELE	254744	0004	020	М	0	In corridor outside of 04-020 emergency light is inoperable.	0	07/26/13		18
ELE	254745	0099	002	М	0	Emergency light at main entry is inoperable.	0	07/26/13		19
ELE	254745	0099	151 N	М	0	In corridor outside of 99-151N emergency light is inoperable.	0	07/26/13		20
ELE	254745	0099	533	М	o	At main entry emergency/exit light is inoperable, in emergency mode.	1	07/26/13		21
ELE	254746	0004	020	М	0	Electrical receptacle is missing cover.	1	07/26/13		22
ELE	254746	0099	008	М	0	Light switch cover is damaged needs to be repaired or replaced.	1	07/26/13	· · ·	23
HVA	254748	0001	800	М	0	No current State certification on boiler.	1	07/26/13		24
MAS	254749	0004	001	М	0	Double door exit of 04-001 threshold needs to be brought up to proper	0	07/26/13		25
						height.				
SGN	254751	0099	002	М	0	Multiple rooms inside portable do not have FISH number.	0	07/26/13		26
SGN	254751	0099	102	М	О	Interior rooms are missing FISH numbers.	0	07/26/13		27
SGN	254751	0099	533	М	0	Replace exit sign with externally reflective exit sign on secondary	0	07/26/13		28
						egress.				
STR	254795	0099	002	М	0	Secondary exit stairs have loose boards and nails that need to be re-	0	07/26/13		29

Drintad:	7/15/2013	0.11.01	A B


The principal shall hold at least one (1) emergency drill during each month, with an additional drill being held within the first 30 days of school.

No

Signature of facility administrator attesting to Emergency Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies

Signature Date

06/26/13 INSPECTION DATE



LEON COUNTY SCHOOLS MAINTENANCE DEPARTMENT "Our hands keep their minds working"

Administration SCHOOL/FACILITY/CAMPUS

> <u>037-9001-900</u> F.I.S.H./F.I.C.E. NUMBER

INSPECTOR SIGNATURE

SIGNATURE DATE

2757 West Pensacola St., Tallahassee ADDRESS

TYPE INSPECTION

FIRE SAFETY CASUALTY

✓ SANITATION

COMPREHENSIVE SAFETY INSPECTION - STANDARD FISCAL YEAR 2012-13

Dept	Work Order	Building Number	Room Number	M O C	Estimated Cost	Deficiency Description and Corrective Action Required	Number of Times Def. Cited Before	Sched for Correction NLT	Completion Date	Line Item #
						secured and no skid needs to be replaced.				
STR	254795	0099	008	М	0	Stairs at main entry are loose and wood rotted need to be repaired or	1	07/26/13		30
						replaced.				
STR	254795	0099	008	М	0	Closers need to be added to both egress doors of this portable.	0	07/26/13		31
STR	254795	0099	102	М	0	Closers need to be added to both doors of this portable.	0	07/26/13		32
STR	254795	0099	533	М	0	Closers need to be added to both exits of this portable.	0	07/26/13		33
STR	254975	0099	008	М	0	In steps on front of portable leading up to main door are rotted and	0	07/26/13		34
						loose need to be repaired or replaced. (Handrail also)				
SYS	254796	0004	003	M	0	Building wide-Notification device in bathrooms need to be installed	0	07/26/13		35
						properly.				
						In corridor outside of 04-003 security device cover is hanging off needs				
						to be reinstalled.				
SYS	254796	0004	023	М	o	No current inspection report at fire alarm panel.	1	07/26/13		36
SYS	254796	0099	002	М	0	In Communication room no fire alarm initiation device is installed	0	07/26/13		37
						above fire alarm panel.				

Printed: 7/15/2013 8:41:04 AM	Printed:	7/15/2013	8:41:04	AM
-------------------------------	----------	-----------	---------	----

The principal shall hold at least one (1) emergency drill during each month, with an additional drill being held within the first 30 days of school.

•	1/		
	Yes		Ν