

To:

Mrs. Eydie Tricquet, Director, FDLRS, Bloxham Building

Mr. Alvin "Butch" Watkins, Director of Maintenance

Mr. Danny Allbritton, Director of Construction

From:

Mr. Juan E. Williams, Coordinator, Fire & Safety

Through:

Mr. LaRoderick E. McQueen, Building Official

Date:

July 15, 2019

Subject:

SREF Inspection for Bloxham Building

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Please do not submit work orders for the deficiency line items in the M (Maintenance) column. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction and Capital Outlay) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement and Compliance Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Deanetra S. Grissom at grissomd@leonschools.net or fax the report to (850) 617-1800, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board.

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Juan E. Williams at the Code Enforcement and Compliance Department at (850) 617-1814 or email at williams 20@leonschools.net. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc: Dr. Alan Cox, Assistant Superintendent of School Management (with attachments)

7/15/2019										Page 1 of
INSP	ECTION D					Bloxham Building				
INSF	ECTOR:	Juan E.	Willian	วร	The Part of Management of State of Stat	SCHOOL/ FACILITY/CAMPUS				
	/	IAI.	1/1/			725 South Calhoun Street				
1	run	211	100	al)	LEON COUNTY SCHOOLS	Tallahassee, Florida 32301				
INSPECTOR SIGNATURE SIGNATURE DATE					EACITITIES & CONSTRUCTION					
TYPE OF INSPECTION					FACITLITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303					
1 38	FIRE 3	CASUA	LTY	SANITATION	COMPREHENSIVE SAFETY INSPECTION	F.I.S.H. NUMBER				
			140		FISCAL YEAR: 2019-2020 037-9001-75F					F
item #	Building Number	Room Number	M O C	<u>Deficier</u>	cy Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT
1	0000	000	M	ADA/egress hardware missing from required doors.					Building	
2	0001	113D	M	Emergency light out.					Wide	Structural Department
3	0001	118A	0	Extension cords	cannot be used as permanent power.	0				Electrical Department
4	0001	201	0	Replace missing		2				
5	0001	201A	0	Replace and date ceiling tiles that have water stains.						
6	0001	208	0	Outside of #208, ceiling tile is missing.						
7	0001	800A	M	Emergency light out in stairwell - top floor.						
8	0001	800J	M	Emergency light	0				Electrical Department	
9	00B1	022	0		ceted Panel Box from floor area - not in use.	0				Electrical Department
10	00B1	024	M	F.A. in Trouble N		0			Basement	· · · · · · · · · · · · · · · · · · ·
11	00B1	024A				0			Basement	Building Automation
12	00B1	025		Light fixture at basement entry is missing cover. Hole in wall.					Basement	8
13	00B1	023		Water leaking in through walls.					Basement	Structural Department
15	OODI	027	М	water leaking in t		1			Basement	Structural Department
	END OF SREF INSPECTION REPORT									Structural Department
A re-inspection of the identified deficiencies will be an Count										
The principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall hold at least one (1) fire drill during each month with an additional drill being half to the principal shall be added to the princi										
Signature of facility administrator attesting to Fire Pure gooding D. III.										
Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies: Date of Acknowledgement:										
X Quelle Jugard Leon County School/Site Alministrator										

Printed: 7/15/2019 - 3:39 PM