

To: Mr. Joe Burgess, Principal, Lawton Chiles High School
Ms. Grace Bigelow, Assistant Principal Chiles High School
Ms. Calli Pickens, Assistant Principal Chiles High School
Mr. Dan Molinaro, Assistant Principal Chiles High School
Mr. Paul Lambert, Assistant Principal Chiles High School
Mr. Ryan Peck, Director of Maintenance
Mr. Danny Allbritton, Director of Construction

From: Mr. Tonnie W. Rollins, Project Manager, Fire & Safety Inspector

Through: Mr. LaRoderick E. McQueen, Certified Building Official/Divisional Director

Date: November 25, 2024

Subject: SREF Inspection for Lawton Chiles High School

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Work orders will be generated addressing each deficient item. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff or through work order submission to the Maintenance Department. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction) in the MOC column are to be addressed by the Construction/Facilities Department through Capital Outlay projects or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Kathryn White at whitek3@leonschools.net or fax the report to (850) 617-1790, to her attention.


Please note a copy of this SREF inspection report will be forwarded to the Board and your Divisional Director.

Additionally a separate inspection report has been provided for each portable at your site. In accordance with SREF Chapter 4 Section 4.4 (2)


If you have any questions or comments regarding any items noted on this report, please feel free to contact **Mr. Tonnie W. Rollins at the Code Enforcement Department at (850) 617-1800 or email at rollinst2@leonschools.net**. Thank you for your time and cooperation in this matter.

ATTACHMENT


Cc: Mr. Scott Hansen, LCS Director of Secondary Schools (with attachments)


| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |

| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 1 | 0000 | 000 | O | Remove plastic/wooden door chocks from propping open corridor/rated doors. | 11 | | | Site Wide | |
| 2 | 0000 | 000 | O | Install locking mechanism on security fencing around HVAC equipment, gas valves, and mechanical equipment. | 11 | | | Site Wide | |
| 3 | 0000 | 000 | O | All gas meters on outside of buildings 8 and 9 shall have locks on at all times. | 2 | | | | |
| 4 | 0000 | 000 | O | Clean light covers campus wide. | 1 | | | Site Wide | |
| 5 | 0000 | 000 | O | All fire extinguishers need to be inspected monthly and card must be initialed and report sent to the district. | 1 | | | Site Wide | |
| 6 | 0000 | 000 | O | Pigeon feces/waste need to be cleaned near room #01-218 | 1 | | | | |
| 7 | 0000 | 000 | O | Remove spider webs and dirt dobbbers throughout the entire campus. | 1 | | | Site Wide | |
| 8 | 0001 | 100A | O | Alarm panel showing trouble | | | | | |
| 9 | 0000 | 100A | O | Outside stairs obstructed. | | | | | |
| 10 | 0001 | 101D | O | Replace missing/broken ceiling tile(s). | | | | | |
| 11 | 0001 | 103 | O | Light fixture cover broken. | 1 | | | Site Wide | |
| 12 | 0001 | 103 | O | Replace water stained ceiling tile(s). | | | | | |
| 13 | 0001 | 104 | O | Replace and date water stained and/or broken ceiling tile(s) (x3). | 0 | | | | |
| 14 | 0001 | 109 | O | Broken or missing receptacle cover plate. | 1 | | | | SREF 5(2)(e)(8)j |
| 15 | 0001 | 109 | O | Doorway obstructed. | 1 | | | | SREF 5(2)(e)(8)j |


| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| FISCAL YEAR: 2024-2025 | | | | | |

| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 16 | 0001 | 110C | O | Doorway and walkway obstructed. | 1 | | | | SREF 5(2)(e)(8)(j) NFPA 70 406.8 |
| 17 | 0001 | 116 | O | Door blocked. | 0 | | | | |
| 18 | 0001 | 117 | O | Door blocked. | 0 | | | | |
| 19 | 0001 | 118 | O | Storage in mechanical room is prohibited. | 0 | | | | |
| 20 | 0001 | 119 | O | Storage in mechanical room is prohibited. | 0 | | | | |
| 21 | 0001 | 121 | O | Classroom needs general housekeeping. | 1 | | | | |
| 22 | 0001 | 203A | O | Replace and date water stained and/or broken ceiling tile(s). | 0 | | | | SREF 5(2)(e)(8)j |
| 23 | 0001 | 208 | O | Replace water stained ceiling tile(s). | | | | | |
| 24 | 0001 | 209 | O | Replace water stained ceiling tile(s). | 2 | | | | SREF 5(2)(e)(8)j |
| 25 | 0001 | 214 | O | Classroom needs general housekeeping. | 1 | | | | |
| 26 | 0001 | 214A | O | Replace water stained ceiling tile(s). | | | | | |
| 27 | 0001 | 214C | O | Replace water stained ceiling tile(s). | 1 | | | | |
| 28 | 0001 | 214D | O | Lights not working (x2) | 1 | | | | |
| 29 | 0001 | 214E | O | Lights on walls | 1 | | | | Paint Department |
| 30 | 0001 | 214F | O | Lights on walls and ceiling. | 1 | | | | NFPA 1-10.19.3.1 |


| 08/28/2024 | | | |  | | Lawton Chiles High School SCHOOL/ FACILITY/CAMPUS 7200 Thomasville Road Tallahassee, Florida 32312 | | | | |
|--|-----------------|-------------|-------------|--|--|---|-------------------------------|---|---|--|
| INSPECTION DATE | | | | | | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | | | | | | | |
| | | | | | | | | | | |
| INSPECTOR SIGNATURE SIGNATURE DATE | | | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | | |
| TYPE OF INSPECTION | | | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | | | COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | 037-1141-114 | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT | |
| 31 | 0001 | 216 | O | Door obstructed | 1 | | | | | |
| 32 | 0001 | 217 | O | Classroom needs general housekeeping. | | | | | | |
| 33 | 0001 | 217 | O | Storage in mechanical room is prohibited. | | | | | | |
| 34 | 0001 | 217 | O | Door obstructed | | | | | | |
| 35 | 0001 | 217A | O | Unobstructed access is required at panelboards. | 1 | | | | | |
| 36 | 0001 | 217A | O | Needs general housekeeping. | | | | | | |
| 37 | 0001 | 217A | O | Storage in mechanical room is prohibited. | | | | | | |
| 38 | 0001 | 218 | O | Outside of door needs to be painted | | | | | | |
| 39 | 0001 | 218 | O | Remove combustible materials from ceiling | | | | | NFPA 101-10.3.1 | |
| 40 | 0002 | 000 | O | Items in hallway between 204 and 215 needs to be removed | | | | | | |
| 41 | 0002 | 000 | O | Extension cords cannot be used as permanent power. Remove extension cord in walkway. | | | | | | |
| 42 | 0002 | 104B | O | Replace water stained ceiling tile(s). | | | | | | |
| 43 | 0002 | 104C | O | Replace water stained ceiling tile(s). | | | | | | |
| 44 | 0002 | 105 | O | Remove combustible materials from ceiling. | | | | | | |
| 45 | 0002 | 115 | O | Extension cords cannot be used as permanent power. Remove extension cord in walkway. | | | | | | |

| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 46 | 0002 | 115A | 115 | Remove non-approved furniture that does not have NFPA label or certificate. | | | | | |
| 47 | 0002 | 117 | O | Replace water stained ceiling tile(s). | 1 | | | | |
| 48 | 0002 | 122A | O | Replace water stained ceiling tile(s). | 1 | | | | |
| 49 | 0002 | 123 | O | More than 20% of combustibles covering walls in classrooms. | 1 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |
| 50 | 0002 | 123 | O | More than 20% of combustibles covering walls in classrooms. | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 51 | 0002 | 123 | O | Escape Window/ Exit obstructed | 1 | | | | |
| 52 | 0002 | 202A | O | No access. | | | | | |
| 53 | 0002 | 204 | O | Extension cord cannot be used as permanent power. | | | | | |
| 54 | 0002 | 204 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 1 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |
| 55 | 0002 | 205 | O | Replace water stained ceiling tile(s). | 1 | | | | SREF 5 (2) (e) (8) j |
| 56 | 0002 | 205 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 1 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |
| 57 | 0002 | 206 | O | Lights on walls | | | | | |
| 58 | 0002 | 206A | O | Storage in mechanical room is prohibited. | 1 | | | | |
| 59 | 0002 | 210 | O | Door difficult to open and needs general housekeeping | | | | | |
| 60 | 0002 | 211A | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 1 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |


| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| 61 | 0002 | 212 | O | Remove non-approved furniture that does not have NFPA label or certificate. | 1 | | | | NFPA 101-10.3.2 |
| 62 | 0002 | 212B | C | Smoke detector hanging from ceiling. | | | | | |
| 63 | 0002 | 212B | C | Remove flammable liquids and/or internal combustion engines from room. These items shall be stored in the flammable storage room only. | 1 | | | | SREF 5(2)69A-58.0051(2)(7) and (3) |
| 64 | 0002 | 213 | O | Storage in mechanical room is prohibited. | 1 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |
| 65 | 0002 | 214 | O | Doorway obstructed. | | | | | |
| 66 | 0002 | 214 | O | Walkway obstructed. | | | | | |
| 67 | 0002 | 215 | O | Remove festive lights hanging from ceiling. Combustible materials on walls and/or ceiling shall not exceed 20% in a non-sprinklered building and/or 40% in a sprinklered building. | 1 | | | | NFPA 101-15.7.4.3 |
| 68 | 0003 | 101 | O | Light cover hanging/ Lights not working *2 | 1 | | | | |
| 69 | 0003 | 101A | O | Locker release in freezer will not turn | 1 | | | | |
| 70 | 0003 | 104 | O | Room is not designated storage on FISH report. Remove storage or add automatic initiation device. | 1 | | | | |
| 71 | 0003 | 104 | O | Remove combustible materials from ceiling. | | | | | |
| 72 | 0003 | 105 | O | Hood system over the stove is not working. | 0 | | | | |
| 73 | 0003 | 105A | O | Replace and date water stained and/or broken ceiling tile(s). | 1 | | | | |
| 74 | 0003 | 106 | O | Boiler room is being used as storage. Room is not designated storage on FISH report. | 0 | | | | SREF 5 (10) (e) |
| 75 | 0003 | 107 | O | Mechanical room is being used as storage. Room is not designated storage on FISH report. | 0 | | | | SREF 5(16)(6)a |


| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| 76 | 0003 | 108 | O | Storage in electrical room is prohibited. | 0 | | | | |
| 77 | 0003 | 109 | O | Storage in electrical room is prohibited. with gas equipment. Flammable liquids and/or equipment needs to be stored in the proper location. | 0 | | | | |
| 78 | 0004 | 101 | O | Boiler room is being used as storage. Room is not designated storage on FISH report. | 0 | | | | SREF 5 (10) (e) |
| 79 | 0004 | 103 | O | Emergency escape window shall not be obstructed, | 0 | | | | |
| 80 | 0004 | 103 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 81 | 0005 | 000 | O | Entire building has improper storage, blocking electrical panel boxes, remove combustible materials from ceiling, general housekeeping is needed and potential fire hazards. | | | | | |
| 82 | 0005 | 103 | O | Exposed wires on wall. | | | | | |
| 83 | 0005 | 103 | O | Fire extinguisher needs an inspection. | | | | | |
| 84 | 0005 | 107 | O | Room is not designated storage on FISH report. Remove storage or add automatic initiation device. | 0 | | | | |
| 85 | 0005 | 107 | O | Unobstructed access is required at panelboards. | 0 | | | | |
| 86 | 0005 | 108 | O | Room is not designated storage on FISH report. Remove storage or add automatic initiation device. | 0 | | | | |
| 87 | 0005 | 109 | O | Room is not designated storage on FISH report. Remove storage or add automatic initiation device. | 0 | | | | |
| 88 | 0005 | 110 | M | Insulation is hanging from ceiling. | 0 | | | | HVAC Department |
| 89 | 0005 | 110 | O | Replace and date water stained and/or broken ceiling tile(s). | | | | | |


| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | 037-1141-114 | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 90 | 0005 | 110 | O | Classroom needs general housekeeping. | 0 | | | | |
| 91 | 0005 | 110 | O | Entrance obstructed. | | | | | |
| 92 | 0005 | 110 | O | Extension cords cannot be used as permanent power. | | | | | |
| 93 | 0005 | 111 | O | Sprinkler controls needs inspection | | | | | |
| 94 | 0005 | 111 | O | Doorway shall not be obstructed. | 0 | | | | |
| 95 | 0005 | 111A | O | Door next to 05-11A obstructed with hazard. | | | | | |
| 96 | 0005 | 113 | O | No access. | 0 | | | | |
| 97 | 0005 | 114 | O | Replace water stained ceiling tile(s). (x3). | 0 | | | | |
| 98 | 0005 | 114 | O | Combustible materials on walls and/or ceiling shall not exceed 20% in a non-sprinklered building and/or 40% in a sprinklered building. | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 99 | 0005 | 114A | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | NFPA 101-15.2.11.1.1 NFPA 101-4.5.3.2 |
| 100 | 0005 | 116 | O | Exposed wiring on wall. | 0 | | | | |
| 101 | 0005 | 119 | O | Room is not designated storage on FISH report. Remove storage or add automatic initiation device. | 0 | | | | |
| 102 | 0005 | 121A | O | Replace water stained ceiling tile(s). | 0 | | | | |
| 103 | 0005 | 123C | O | Replace water stained ceiling tile(s). | 0 | | | | |


| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | | | | | |
| | | FISCAL YEAR: 2024-2025 | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 104 | 0005 | 124 | O | Replace water stained ceiling tile(s). | | | | | |
| 105 | 0005 | 124C | O | Remove combustible materials from ceiling. | 0 | | | | |
| 106 | 0005 | 124C | O | Replace water stained ceiling tile(s). | | | | | |
| 107 | 0005 | 124F | O | Broken or missing receptacle cover plate. | 0 | | | | SREF 5(2)(c)(8)(j) |
| 108 | 0005 | 124H | O | Broken or missing receptacle cover plate. | | | | | |
| 109 | 0005 | 124J | O | Broken or missing receptacle cover plate. | 0 | | | | SREF 5(2)(c)(8)(j) |
| 110 | 0005 | 124J | O | Replace water stained ceiling tile(s). | | | | | |
| 111 | 0005 | 125 | O | Storage in mechanical room is prohibited. | | | | | |
| 112 | 0005 | 125 | O | Lock malfunction. | | | | | |
| 113 | 0005 | 126 | O | Light inoperable. | | | | | |
| 114 | 0005 | 126 | O | Wasp nest above door | | | | | |
| 115 | 0005 | 500A | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 116 | 0006 | 103 | M | Mechanical room unlocked. | 0 | | | | Electrical Department |
| 117 | 0006 | 108 | O | Replace missing/broken ceiling tile(s). | 0 | | | | |
| 118 | 0006 | 108 | O | Light is not operating correctly, please repair light. | 0 | | | | |
| 119 | 0006 | 109 | O | Replace water stained ceiling tile(s). | 0 | | | | |

| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | 037-1141-114 | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 116 | 0006 | 110 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 117 | 0006 | 110 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 118 | 0006 | 111 | O | Remove combustibles around washer and dryer. | 0 | | | | |
| 119 | 0006 | 112 | O | Trip hazard needed on entrance and exit doors. | | | | | |
| 120 | 0006 | 112 | O | Unable to access light switches. | | | | | |
| 121 | 0006 | 112 | O | Replace water stained ceiling tile(s). | | | | | |
| 122 | 0006 | 112 | O | Light is not operating correctly, please repair light. | | | | | |
| 123 | 0006 | 113 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 124 | 0006 | 113 | O | Lights not working (x6) | 0 | | | | |
| 125 | 0006 | 114 | O | Light is not operating correctly, please repair light. | | | | | |
| 126 | 0006 | 114 | O | Walkway blocked | | | | | |
| 127 | 0006 | 115 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 128 | 0006 | 115 | O | Lights not working (x4) | | | | | |
| 129 | 0006 | 118 | O | Remove combustibles around washer and dryer. | | | | | |
| 130 | 0006 | 118 | O | Storage in laundry room is prohibited. | | | | | |
| 131 | 0006 | 119A | O | Unable to turn shower off. | | | | | |
| 132 | 0006 | 119A | O | Light switch cover plate is missing | | | | | |


| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | | | | | |
| | | FISCAL YEAR: 2024-2025 | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 133 | 0006 | 119A | O | Replace damaged ceiling tile | | | | | |
| 134 | 0006 | 119D | O | Replace water stained ceiling tile(s). | | | | | |
| 135 | 0006 | 119H | O | Remove non-approved furniture that does not have NFPA label or certificate. | | | | | |
| 136 | 0006 | 119H | O | General Housekeeping | | | | | |
| 137 | 0006 | 120A | O | Wall plate needs to be replaced | 0 | | | | |
| 138 | 0006 | 124 | O | Mechanical room is being used as storage. Room is not designated storage on FISH report. | | | | | SREF 5 (16)(6)a |
| 139 | 0006 | 600 | O | Hallway used as storage. | | | | | |
| 140 | 0006 | 600 | O | To much slack on chain on gate Northside of building. | | | | | |
| 141 | 0007 | 102 | O | Extension cords cannot be used as permanent power. | 0 | | | | |
| 142 | 0007 | 102 | O | Festive Lights on wall. | | | | | |
| 143 | 0007 | 102 | O | Remove combustible materials from ceiling. | | | | | |
| 144 | 0007 | 102 | O | Curtains shall have label or certificate verifying flame retardant meeting NFPA 701. | | | | | NFPA 101-10.3.1. |
| 145 | 0007 | 102 | O | Curtains shall have label or certificate verifying flame retardant meeting NFPA 701. | | | | | NFPA 101-10.3.1. |
| 146 | 0007 | 102 | O | Light is not operating correctly, please repair light. | | | | | |
| 147 | 0007 | 102A | O | Appliances need to plug into a direct outlet. | 0 | | | | |
| 148 | 0007 | 103 | O | Combustible materials on walls and/or ceiling shall not exceed 20% in a non-sprinklered building an | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 149 | 0007 | 103 | M | Spalding floor near emergency exit window. | 0 | | | | Structural Department |

| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | | | | | |
| | | FISCAL YEAR: 2024-2025 | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 145 | 0007 | 103 | O | Festive Lights on wall. | 0 | | | | NFPA 101-10.3.2 |
| 146 | 0007 | 103 | O | Curtains shall have label or certificate verifying flame retardant meeting NFPA 701. | 0 | | | | NFPA 101-10.3.1. |
| 147 | 0007 | 103 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 148 | 0007 | 105 | O | Extension cords cannot be used as permanent power. | 0 | | | | |
| 149 | 0007 | 106 | O | Remove non-approved furniture that does not have NFPA label or certificate. | 0 | | | | NFPA 101-10.3.2 |
| 150 | 0007 | 106 | O | Door leading to next room obstructed | | | | | |
| 151 | 0007 | 106 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 152 | 0007 | 109 | O | Storage in mechanical room is prohibited. | | | | | |
| 153 | 0007 | 109A | O | Remove non-approved furniture that does not have NFPA label or certificate | | | | | |
| 154 | 0007 | 111 | O | Fire extinguisher needs inspection | 0 | | | | |
| 155 | 0007 | 111 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 156 | 0007 | 118 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | NFPA 101-5.7.4.3 |
| 157 | 0007 | 119 | O | Curtains shall have label or certificate verifying flame retardant meeting NFPA 70. | 0 | | | | NFPA 101-10.3.2 |
| 158 | 0007 | 119 | O | Lights not working (x2) | 0 | | | | NFPA 101-10.3.2 |
| 159 | 0007 | 121B | O | Combustible materials on walls and/or ceiling shall not exceed 20% in a non-sprinklered building and/or 40% in a sprinklered building. | 0 | | | | NFPA 101-15.7.4.3 (1) |


| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | | | | | |
| | | FISCAL YEAR: 2024-2025 | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 160 | 0007 | 122 | O | Appliances need to plug into a direct outlet. | | | | | |
| 161 | 0007 | 122 | O | Remove non-approved furniture that does not have NFPA label or certificate. | | | | | |
| 162 | 0007 | 123 | O | Remove non-approved furniture that does not have NFPA label or certificate./ Festive lights on wall. | | | | | |
| 163 | 0007 | 123 | O | Lights not working/ Walkway obstructed. | 0 | | | | |
| 164 | 0007 | 204 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 165 | 0007 | 206 | O | Doorway leading to next classroom is obstructed. | 0 | | | | |
| 166 | 0007 | 207 | O | Combustible materials on wall shall not exceed 20% or 40%. | | | | | NFPA 101-15.7.4.3 (1) |
| 167 | 0007 | 207 | O | Remove combustible materials from ceiling. | | | | | |
| 168 | 0007 | 207 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 169 | 0007 | 207A | O | Doorway leading to next classroom is obstructed. | | | | | |
| 170 | 0007 | 208 | O | Remove combustible materials from ceiling. | 0 | | | | NFPA 101-10.3.2 |
| 171 | 0007 | 208 | O | Combustible materials on walls and/or ceiling shall not exceed 20% in a non-sprinklered building and | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 172 | 0007 | 208 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 173 | 0007 | 208 | O | Doorway leading to next classroom is obstructed. | 0 | | | | |
| 174 | 0007 | 209 | O | Remove non-approved furniture that does not have NFPA label or certificate. NFPA | 0 | | | | |
| 175 | 0007 | 209 | O | Furniture obstructing doorway leading to next class. | 0 | | | | |

| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re- Inspection Correction Date | Site-Wide Building- Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|--|---|--|---|---|---|
| 176 | 0007 | 212A | O | Remove combustible materials from ceiling. | 0 | | | | |
| 177 | 0007 | 213 | O | Festive Lights on wall. | 0 | | | | |
| 178 | 0007 | 213 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 179 | 0007 | 213 | O | Combustible materials on wall shall not exceed 20% | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 180 | 0007 | 215A | O | Walkway obstructed. | 0 | | | | |
| 181 | 0007 | 215A | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 182 | 0007 | 219 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 183 | 0007 | 219C | O | Storage in electrical room is prohibited. | 0 | | | | |
| 184 | 0007 | 219D | O | Storage in mechanical room is prohibited. | 0 | | | | |
| 185 | 0007 | 220 | O | Electrical room is being used as storage. Room is not designated storage on FISH report. | 0 | | | | SREF 5 (16)(6)a |
| 186 | 0007 | 220 | O | Mechanical room is being used as storage. Room is not designated storage on FISH report. | 0 | | | | SREF 5 (16)(6)a |
| 187 | 0007 | 220 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 188 | 0007 | 220A | O | Festive Lights on wall. | 0 | | | | |
| 189 | 0007 | 220A | O | Lights not working (X4) | 0 | | | | |
| 190 | 0008 | 102 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 191 | 0008 | 102A | O | Doorway obstructed. | 0 | | | | |
| 192 | 0008 | 103 | M | Wood Fence needs repair near (08-103) | 0 | | | | |

| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 193 | 0008 | 104 | O | Remove non-approved furniture that does not have NFPA label or certificate. | 0 | | | | |
| 194 | 0008 | 105 | O | Doorway is obstructed leading to next class room. | 0 | | | | |
| 191 | 0008 | 106 | O | T.V. monitor blocking doorway is obstructed leading to next class room. | 0 | | | | |
| 192 | 0008 | 107 | O | Exit Obstructed | 0 | | | | |
| 193 | 0008 | 107 | O | Entrance obstructed. | 0 | | | | |
| 194 | 0008 | 107 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window | 0 | | | | |
| 195 | 0008 | 107A | O | Replace water stained ceiling tile(s). | 0 | | | | |
| 196 | 0008 | 109 | O | Install ADA/FISH sign. | 0 | | | | SREF 5 (10)(i)(2) and (5) |
| 197 | 0008 | 109A | O | T.V. and T.V. Card obstructing doorway. | 0 | | | | |
| 198 | 0008 | 109B | O | Replace water stained ceiling tile(s). | 0 | | | | |
| 199 | 0008 | 115 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 200 | 0008 | 116 | O | Remove combustible materials from ceiling | 0 | | | | NFPA 101-10.3.1 |
| 201 | 0008 | 116 | O | Entrance doorway obstructed. | 0 | | | | Electrical Department |
| 202 | 0008 | 116A | O | Walkway obstructed. | 0 | | | | |
| 203 | 0008 | 116A | O | Doorway obstructed. | 0 | | | | |
| 204 | 0008 | 118 | O | Fish number covered. | 0 | | | | Locksmith Department |
| 205 | 0008 | 118 | O | Replace water stained ceiling tile(s). | 0 | | | | |

| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| FISCAL YEAR: 2024-2025 | | | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 206 | 0008 | 118 | O | Closet needs a fish number. Ceiling tile is not flush with ceiling. | 0 | | | | |
| 207 | 0008 | 118 | O | Replace and date water stained ceiling tile(s). | 0 | | | | |
| 208 | 0008 | 202A | O | Extension cord cannot be used as permanent power. | 0 | | | | |
| 209 | 0008 | 202B | O | Walkway obstructed. | 0 | | | | |
| 210 | 0008 | 202B | O | Replace water stained ceiling tile(s). Ceiling tile is not flush with ceiling. | 0 | | | | |
| 211 | 0008 | 202C | O | Chemical room door prompt open | | | | | |
| 212 | 0008 | 202C | O | Replace damaged ceiling tile(s). | | | | | |
| 2013 | 0008 | 205 | O | Light not working. | | | | | |
| 214 | 0008 | 206A | O | Light not working/Light cover hanging | | | | | |
| 215 | 0008 | 206A | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 216 | 0008 | 207 | O | Festive Lights on walls. | | | | | |
| 217 | 0008 | 209 | O | Festive Lights on walls. | | | | | |
| 218 | 0008 | 209 | O | Remove combustible materials from ceiling. | | | | | |
| 219 | 0008 | 209A | O | Light Cover hanging | | | | | |
| 221 | 0008 | 210 | O | Combustible materials on wall shall not exceed 20% | 0 | | | | NFPA 101-15.7.4.3 (1) |
| 222 | 0008 | 210 | O | Remove combustible materials from ceiling. | 0 | | | | |
| 213 | 0008 | 214 | M | Replace water stained ceiling tile(s). | 0 | | | | Electrical Department |


| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |


| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| 214 | 0008 | 214 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | 0 | | | | |
| 215 | 0008 | 214C | O | Storage in electrical room is prohibited. | 0 | | | | |
| 216 | 0008 | 214D | O | Storage in mechanical room is prohibited. | 0 | | | | |
| 217 | 0008 | 215 | O | Remove combustible materials from ceiling. | 0 | | | | |
| 218 | 0008 | 215 | O | Light Cover hanging. | 0 | | | | |
| 219 | 0008 | 216 | O | Lights not working | | | | | |
| 220 | 0008 | 216 | O | Provide and maintain an unobstructed access to the exit and/or emergency escape window. | | | | | |
| 221 | 0008 | 216A | O | Remove combustible materials from ceiling. | | | | | |
| 223 | 0008 | 800 | O | Door on second floor unable to access | | | | | |
| 224 | 0009 | 001 | O | Needs a fire extinguisher | | | | | |
| 225 | 0009 | 104 | O | Replace water stained ceiling tile(s). | | | | | |
| 226 | 0009 | 104B | O | Replace damaged ceiling tile(s). | | | | | |
| 227 | 0009 | 105 | O | Light cover hanging./Lights not working. | | | | | |
| 228 | 0009 | 105A | O | Light cover hanging./Lights not working. | | | | | |
| 229 | 0009 | 201 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |
| 230 | 0009 | 201 | O | Extension cord cannot be used as permanent power. | | | | | |
| 231 | 0009 | 202 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |



| | | | | | |
|--|--|--|--|--------------------------------------|--|
| 08/28/2024 | |  | | Lawton Chiles High School | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | |
| | | | | Tallahassee, Florida 32312 | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | |
| | | FISCAL YEAR: 2024-2025 | | | |

| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
|--------|-----------------|-------------|-------------|--|--|---------------------------------------|-------------------------------|---|---|
| 232 | 0009 | 203 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |
| 233 | 0009 | 203 | O | Remove combustible materials from ceiling. | | | | | |
| 234 | 0009 | 203A | O | Light Cover missing | | | | | |
| 235 | 0009 | 204 | O | Festive lights on wall. | | | | | |
| 236 | 0009 | 204 | O | Door leading to next room obstructed | | | | | |
| 237 | 0009 | 205 | O | Light Cover hanging (x3) | | | | | |
| 238 | 0009 | 205 | O | Light is not operating correctly, please repair light. | | | | | |
| 239 | 0009 | 205A | O | Doorway blocked. | | | | | |
| 240 | 0009 | 205A | O | Light Cover hanging (x2) | | | | | |
| 241 | 0009 | 206 | O | Festive lights on wall. | | | | | |
| 242 | 0009 | 206 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |
| 243 | 0009 | 206 | O | Extension Cord on floor. | | | | | |
| 244 | 0009 | 207 | O | Extension Cord on floor. | | | | | |
| 245 | 0009 | 208 | O | Remove combustible materials from ceiling. | | | | | |
| 246 | 0009 | 208 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |
| 247 | 0009 | 208A | O | Light is not operating correctly, please repair light. | | | | | |
| 248 | 0009 | 208A | O | Uncover Fish number. | | | | | |

| 08/28/2024 | |  | | Lawton Chiles High School | | | | | |
|--|-----------------|--|-------------|---|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | |
| INSPECTOR SIGNATURE | | SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT | | | | | |
| TYPE OF INSPECTION | | 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | COMPREHENSIVE SAFETY INSPECTION | | 037-1141-114 | | | | | |
| | | FISCAL YEAR: 2024-2025 | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 249 | 0009 | 209 | O | Festive lights on wall. | | | | | |
| 250 | 0009 | 209 | O | Combustible materials on wall shall not exceed 40% | | | | | NFPA 101-15.7.4.3 (2) |
| 251 | 0009 | 211 | O | Unable to access. | | | | | |
| 252 | 0009 | 213 | O | Remove combustible materials from ceiling. | | | | | |
| 253 | 0009 | 213C | O | Storage room is prohibited in communications room. | | | | | |
| 254 | 0009 | 213D | O | Storage in electrical room is prohibited. | | | | | |
| 255 | 0009 | 214 | O | Festive lights on wall. | | | | | |
| 256 | 0009 | 215 | O | Combustible materials on wall shall not exceed 20% | | | | | NFPA 101-15.7.4.3 (1) |
| 257 | 0009 | 216 | O | Doorway leading to next classroom is obstructed. | | | | | |
| 258 | 0010 | 001 | O | Wood Fence needs repair around baseball field | | | | | |
| 259 | 0010 | 102 | O | Remove flammable liquids and propane tank storage unlocked. | | | | | |
| 260 | 0010 | 102 | O | Wall plate needed on outlets outside of building | | | | | |
| 261 | 0010 | 103A | O | Exit Obstructed | | | | | |
| 262 | 0010 | 105 | O | Storage in mechanical room is prohibited. | | | | | |
| 263 | 0010 | 105 | O | Fire extinguisher needs inspection. | | | | | |
| 264 | 0010 | 107 | O | Light Cover missing | | | | | |
| 265 | 0011 | 006 | O | Exit needs to be marked. | | | | | |
| 266 | 0011 | 006 | O | Replace water stained ceiling tile(s). | | | | | |
| 267 | 0012 | 001 | O | Fire extinguisher not mounted properly. | | | | | |
| 268 | 0012 | 001 | O | Exposed wires above door. | | | | | |

| 08/28/2024 | | | |  FACILITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303 COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | Lawton Chiles High School SCHOOL/ FACILITY/CAMPUS 7200 Thomasville Road Tallahassee, Florida 32312 | | | | |
|--|-----------------|-------------|-------------|--|--|---|--|---|---|---|
| INSPECTION DATE | | | | | | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | | | | | | | |
| | | | | | | | | | | |
| INSPECTOR SIGNATURE SIGNATURE DATE | | | | | | F.I.S.H. NUMBER | | | | |
| TYPE OF INSPECTION | | | | | | 037-1141-114 | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | | | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re- Inspection Correction Date | Site-Wide Building- Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 269 | 0012 | 001 | O | Gate around A/C unit needs a lock, | | | | | | |
| 270 | 0012 | 002 | O | Gate around A/C unit needs a lock, | | | | | | |
| 271 | 0012 | 004 | O | Exit Obstructed | | | | | | |
| 272 | 0012 | 004 | O | Outside gate for meter box open | | | | | | |
| 273 | 0012 | 004 | O | Outside gate for electrical box open | | | | | | |
| 274 | 0012 | 005 | O | Storage in restroom is prohibited. Restroom cannot be fully sanitized due to storage | | | | | | |
| 275 | 0012 | 006 | O | Exit Obstructed | | | | | | |
| 276 | 0013 | 003 | O | Storage in electrical room is prohibited. | | | | | | |
| 277 | 0013 | 004 | O | Storage in mechanical room is prohibited. | | | | | | |
| 278 | 0013 | 004 | O | Storage in electrical room is prohibited. | | | | | | |
| 279 | 0013 | 004 | O | Lock hardware is not operating properly. | | | | | | |
| 280 | 0014 | 105 | O | Festive lights on walls. | | | | | | |
| 281 | 0014 | 105 | O | Combustible materials on wall shall not exceed 20% | | | | | | NFPA 101-15.7.4.3 (1) |
| 282 | 0014 | 105A | O | Replace water stained ceiling tile(s). | | | | | | |
| 284 | 0014 | 109 | O | Replace water stained ceiling tile(s). | | | | | | |
| 285 | 0014 | 110 | O | Replace water stained ceiling tile(s). | | | | | | |
| 286 | 0014 | 201 | O | Remove combustible materials from ceiling. | | | | | | |
| 287 | 0014 | 201 | O | Combustible materials on wall shall not exceed 20% | | | | | | NFPA 101-15.7.4.3 (1) |
| 288 | 0014 | 202B | O | Door obstructed | | | | | | |
| 289 | 0014 | 203 | O | Remove combustible materials from ceiling. | | | | | | |

| 08/28/2024 | | | |  LEON COUNTY SCHOOLS | | | | Lawton Chiles High School | | | | |
|--|-----------------|-------------|-------------|--|--|--|--|--|---------------------------------------|-------------------------------|---|---|
| INSPECTION DATE | | | | | | | | SCHOOL/ FACILITY/CAMPUS | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | | | | | 7200 Thomasville Road | | | | |
| | | | | | | | | Tallahassee, Florida 32312 | | | | |
| INSPECTOR SIGNATURE | | | | SIGNATURE DATE | | | | | | | | |
| TYPE OF INSPECTION | | | | FACILITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | | | F.I.S.H. NUMBER | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | | | COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | | | 037-1141-114 | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | | | | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| 290 | 0014 | 205A | O | Replace damaged ceiling tile(s). | | | | | | | | |
| 291 | 0014 | 208 | O | Lights not working (X2) | | | | | | | | |
| 292 | 0014 | 210 | O | Fire extinguisher blocked | | | | | | | | |
| 293 | 0014 | 210A | O | Exit blocked | | | | | | | | |
| 294 | 0014 | 210A | O | Storage in communication room is prohibited. | | | | | | | | |
| 295 | 0014 | 210B | O | Storage in electrical room is prohibited. | | | | | | | | |
| 296 | 0014 | 211 | O | Receptacle is required by NFPA 70 to be GFCI protected. | | | | | | | | |
| 297 | 0017 | 001 | O | Replace stained ceiling tile(s). | | | | | | | | |
| 298 | 0017 | 003 | O | Fire extinguisher needed in room. | | | | | | | | |
| 299 | 0019 | 001 | O | Fire extinguisher needed in room. | | | | | | | | |
| 300 | 0019 | 001 | O | Extensions cord used as permanent | | | | | | | | |
| 301 | 0020 | 001 | O | Fence needs repair leading to track/gate needs a lock | | | | | | | | |
| 302 | 0021 | 000 | O | Baseball Press Box need a FISH. | | | | | | | | |
| 303 | 0021 | 000 | O | Fire extinguisher needed in room. | | | | | | | | |
| 304 | 0099 | 125 | O | Storage in restroom is prohibited. Restroom cannot be fully sanitized due to storage. | | | | | | | | |
| 305 | 0099 | 323 | O | No Isle from exit to entrance. | | | | | | | | |
| 306 | 0099 | 323 | O | Light inoperable. | | | | 0 | | | | Sign Department |
| 307 | 0099 | 480 | O | Storage in restroom is prohibited. Restroom cannot be fully sanitized due to storage. | | | | 0 | | | | |
| | | | | END OF SREF INSPECTION REPORT | | | | | | | | |

| | | | | | | | | | | |
|--|-----------------|--|----------------------|--|--|--|---------------------------------------|-------------------------------|---|--|
| 08/28/2024 | |  LEON COUNTY SCHOOLS | | Lawton Chiles High School | | | | | | |
| INSPECTION DATE | | | | SCHOOL/ FACILITY/CAMPUS | | | | | | |
| INSPECTOR: Tonnie W. Rollins | | | | 7200 Thomasville Road | | | | | | |
| | | | | Tallahassee, Florida 32312 | | | | | | |
| INSPECTOR SIGNATURE SIGNATURE DATE | | FACILITIES & CONSTRUCTION DEPARTMENT 3420 W. THARPE ST., TALLAHASSEE, FL 32303 | | F.I.S.H. NUMBER | | | | | | |
| TYPE OF INSPECTION | | COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2024-2025 | | 037-1141-114 | | | | | | |
| <input checked="" type="checkbox"/> FIRE <input checked="" type="checkbox"/> CASUALTY <input checked="" type="checkbox"/> SANITATION | | | | | | | | | | |
| Item # | Building Number | Room Number | M O C | Deficiency Description and Corrective Action Required | | # of Times Deficiency Previously Cited | Schedule for Correction No Later Than | Re-Inspection Correction Date | Site-Wide Building-Wide Exterior Campus or Portable | REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT |
| A re-inspection of the identified deficiencies will be performed approximately _____ days subsequent of inspection date. Re-Inspection Date: _____ | | | | | | | | | | |
| The principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school. YES <input type="checkbox"/> NO <input type="checkbox"/> | | | | | | | | | | |
| Reviewed Emergency Generator Report. YES <input type="checkbox"/> NO <input type="checkbox"/> Emergency Generator Report up-to-date as of SREF Inspection. YES <input type="checkbox"/> NO <input type="checkbox"/> | | | | | | | | | | |
| Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies: | | | | | | | | | | |
| <div style="display: flex; align-items: center;"> <div style="margin-right: 10px;"> <input checked="" type="checkbox"/> </div> <div>  </div> </div> <div style="margin-top: 5px;"> Leon County School/Site Administrator </div> | | | | | | | | | | |